



November 2019 (FOR ALL SKP SUBSCRIBERS)

2_2019 - **SILCA KEY PROGRAMS PRO v. 30.1.x.xx**

Silca Key Programs PRO UPGRADE 2/2019



For any info regarding the 2/2019 SKP PRO Upgrade, please, read the NEWS document in the SILCA KEY PROGRAMS PRO.





September 2019 (FOR SKP WEB SUBSCRIBERS)

1_2019 - SILCA KEY PROGRAMS v. 21.11.x.xx

TRIAX-QUATTROCODE				NEWS
Lock Manufacturer	Lock-system	New SSN	Data Card	
MLS	MLS KT122 ELITE 2 FP 6+5P	2131	2242	YES
PREFER	Prefer IAA (5+6+5)	2123	4682	NO
VOLVO	HU152S16 (2T-10W)	2125	4680	NO
VOLVO	HU152S16 (2T-10W)	2126	4680	NO

CODE PROGRAM				NEWS
Lock Manufacturer	Lock-system	New SSN	Data Card	
ABUS	ABUS A93 (5P)	5000	4684	NO
CHERY		4999	4676	NO
CHICAGO		5001	4685	NO
MLS	MLS KT152-MLS 6P FAMILY-RED LINE FP2	4992	1872	YES
MLS	MLS KT052-MLS-6P Antibumping Final FP2	4996	1872	YES

July 2019 (FOR SKP WEB SUBSCRIBERS)

1_2019 - SILCA KEY PROGRAMS v. 21.11.x.xx

Silca Key Programs




Bug fixed

- o fixed a bug cutting after decoding the card 869


TRIAX-QUATTROCODE

NEWS

Lock Manufacturer	Lock-system	New SSN	Data Card	
HAFELE	Hafele HW15R (2t-4W)	2113	3061	NO
MLS	MLS KT122 ELITE 2 FP2 6+5P	2115	2242	YES
MLS	MLS KT130 ELITE 1 FP2 6P	2117	1851	YES
STANDERS	Standers (6P)	2114	1857	NO

CODE PROGRAM

NEWS

Lock Manufacturer	Lock-system	New SSN	Data Card	
GUARD	Profile G17 T6	4994	666	NO
HAFELE	-	4971	4642	NO
MLS	MLS KT115 Standard FP2 5P	4988	2273	YES
MLS	MLS KT117 Standard FP2 6P	4989	2765	YES
MLS	MLS KT119 MLS FP2 6P	4991	1872	YES
MLS	MLS KT138 FAMILY FP2 6P	4990	1872	YES
NATIONAL	NATIONAL	4995	1043	NO
US-LOCK	-	4993	4012	NO



June 2019 (FOR SKP WEB SUBSCRIBERS)

1_2019 - SILCA KEY PROGRAMS v. 21.11.x.xx

Silca Key Programs UPGRADE 1/2019



For any info regarding the 1/2019 SKP Upgrade, please, read the NEWS document in the SILCA KEY PROGRAMS.



February 2019 (FOR SKP WEB SUBSCRIBERS)

3_2018 - SILCA KEY PROGRAMS v. 21.10.x.xx

SILCA KEY PROGRAMS



IMPORTANT NOTICE


Starting from the Silca Key Programs update 1/2019, there will be a change with the minimum required PC characteristics to be able to properly install the SKP:


- Only Windows® 7 operating systems (32 or 64 bit), Windows® 8 (32 or 64 bit) and Windows® 10 (32 or 64 bit) will be supported.
- A minimum of 5 GB of free disk space will be required.
- 4 GB of RAM is recommended.

TRIAX-QUATTROCODE

NEWS

Lock	Manufacturer	Lock-system	New SSN	Data Card	
MUL.T.LOCK		Mul-T-Lock Break Secure 3DS	2024	2242	NO
	Wilka	Carat S3	1983	4359	NO
	Wilka	Carat S5	1984	4359	NO
VAST		Vast (2T-8W)	2095	4591	NO
DOM		Dom IX7TW (Prf. 282)	2054	4508	YES
DOM		Dom IX7TW (Prf. 283)	2055	4509	YES
DOM		Dom IX7TW (Prf. 284)	2056	4510	YES
DOM		Dom IX7TW (Prf. 285)	2057	4511	YES
DOM		Dom IX7TW (Prf. 288)	2094	4588	YES
DOM		Dom IX7TE (Prf. 278)	2089	4568	YES
DOM		Dom IX7TE (Prf. 274)	2090	4569	YES
DOM		Dom IX7TE (Prf. 275)	2091	4570	YES
DOM		Dom IX7TE (Prf. 273)	2092	4571	YES
DOM		Dom IX TWIDO (Prf. 280)	2052	4506	YES
DOM		Dom IX TWIDO (Prf. 281)	2053	4507	YES
DOM		Dom IX TECO (Prf. 270)	2087	4566	YES
DOM		Dom IX TECO (Prf. 271)	2088	4567	YES

CODE PROGRAM					NEW
Lock	Manufacturer	Lock-system	New SSN	Data Card	
	HON	HON (5P)	4897	4574	NO
	FCV	FCV Stiftsatz B (5P)	4898	4579	NO
	FCV	FCV Stiftsatz B (6P)	4899	4579	NO

IDEA PROGRAM					NEW
Lock	Manufacturer	Lock-system	New SSN	Data Card	
	ABLOY	Abloy (AY1) - DX_15°	525	4580	NO
	ABLOY	Abloy (AY1) - SX_15°	526	4582	NO



November 2018 (FOR ALL SKP SUBSCRIBERS)


3_2018 - SILCA KEY PROGRAMS v. 21.10.x.xx


Silca Key Programs UPGRADE 3/2018



For any info regarding the 3/2018 SKP Upgrade, please, read the NEWS document in the SILCA KEY PROGRAMS.



TRIAIX / QUATTROCODE					NEW
Lock Manufacturer	Lock-system	New SSN	Data Card		
A.P.FER	Astral W39	2064	1414	YES	
A.P.FER	Astral W39	2065	1414	YES	
M&T	Astral W41	2066	1414	YES	
M&T	Astral W41	2067	1414	YES	
YALE	Superior 1 Star 10 Pin	2068	4541	NO	
YALE	Platinum 3 Star 10 Pin	2069	4541	NO	
HUGO	HUGO GR 5S	2076	4548	NO	
SECUREMME	SECUREMME K3.3 (5+5)	2077	4551	NO	
KASSEL	NF 11 (6+5)	2078	4552	NO	
DOM	Dom IX Twinstar (Prof. 298)	2070	4542	YES	
DOM	Dom IX Twinstar Std. Cut (Prof. 298)	2071	4543	YES	
DOM	Dom IX Twinstar Prf. Cut (Prof. 298)	2072	4544	YES	
DOM	Dom IX Twinstar (Prof. 299)	2073	4545	YES	
DOM	Dom IX Twinstar Std. Cut (Prof. 299)	2074	4546	YES	
DOM	Dom IX Twinstar Prf. Cut (Prof. 299)	2075	4547	YES	

CODE PROGRAM					NEW
Lock Manufacturer	Lock-system	New SSN	Data Card		
CCC		4882	4460	NO	
KEYA		4881	4516	NO	
UEME		4883	4518	NO	
SOPRANO		4884	4519	NO	
WELKA		4885	4520	NO	
BULLDOG		4886	4521	NO	
CISA		4887	4522	NO	
SOPRANO	S-60	4888	4523	NO	
SOPRANO	S-25	4889	4524	NO	
RIELDA	RS3	4451	3756	YES	
EVERGOOD		4890	4526	NO	
SOBINCO		4891	4527	NO	
KEYA	-	4892	4532	NO	
CORNI	CC8	4894	4533	NO	
STAM		4534	4893	NO	

Silca Key Programs




Bug fixed


- Silca Software Interface (SSI) : solved a bug loading DAT file with minor cuts than the card has
- SKP installation : solved a bug during installation of Windows 32 bit version

TRIAX / QUATTROCODE

NEW

Lock Manufacturer	Lock-system	New SSN	Data Card	
SILCA	Silca SK3 side	2010	4395	NO
SILCA	Silca SK3 back side	2012	4407	NO
FLEXON	FLEXON CS2100 (6P)	2027	4351	NO
FLEXON	FLEXON CS2001 (5+5)	2028	4458	NO
HYUNDAI	Hyundai (2T- 8W)	2037	3336	NO
M&T	M&T Champions Pro CP4 (C6LVJ2)	2034	3802	YES
M&T	M&T Champions Pro CP4 (C6LJ2)	1738	3802	YES
M&T	M&T Champions Pro CP4 (C6LJK)	1739	3802	YES
KABA	Kaba K86 - matrix plus Dealer Code	2030	4464	YES
KABA	Kaba K91 - entro Dealer Code	2031	4467	YES
KABA	Kaba K86 - matrix plus	2032	4468	YES
KABA	Kaba K91 - entro	2033	4469	YES
M&C	M&C Condor (Snake)	2022	4428	YES
M&C	M&C Condor (Side)	2023	4429	YES
M&C	M&C Condor Mirror	2038	4435	YES
M&C	M&C Condor Mirror	2039	4435	YES
M&C	M&C Condor Mirror	2040	4435	YES
M&C	M&C Condor Mirror	2041	4435	YES
M&C	M&C Condor Mirror	2042	4435	YES
M&C	M&C Condor Mirror	2044	4435	YES
M&C	M&C Condor Mirror	2045	4435	YES
M&C	M&C Condor Mirror	2046	4435	YES
M&C	M&C Condor Mirror	2047	4435	YES
M&C	M&C Condor Mirror	2048	4435	YES
M&C	M&C Condor Mirror (Main+snake)	2049	4438	YES
M&C	M&C Condor Mirror (Main+side)	2050	4440	YES
M&C	M&C Condor Mirror (Main pins)	2051	4443	YES
M&C	M&C Condor Mirror (Snake)	2058	4444	YES
M&C	M&C Condor Mirror (Side)	2059	4445	YES
M&C	M&C Condor Mirror (Snake+Side)	2060	4512	YES
ISEO	R11 PROGRESS (SGE)	2061	1597	YES
DOM	Dom IX TWIDO (Prf. 280)	2052	4506	YES
DOM	Dom IX TWIDO (Prf. 281)	2053	4507	YES
DOM	Dom IX TWIDO (Prf. 282)	2054	4508	YES

DOM	Dom IX TWIDO (Prf. 283)	2055	4509	YES
DOM	Dom IX TWIDO (Prf. 284)	2056	4510	YES
DOM	Dom IX TWIDO (Prf. 285)	2057	4511	YES

CODE PROGRAM				NEW
Lock Manufacturer	Lock-system	New SSN	Data Card	
IBFM	Art.2260/60mm	4870	4470	NO
IBFM	Art.2240/40mm	4871	4471	NO
IBFM	Art.2302/OL/54mm	4872	4472	NO
IBFM	Art.2215/15mm	4873	4473	NO
IBFM	Art.2220/20mm	4874	4474	NO
IBFM	Art.2225/25mm	4875	4475	NO
RIELDA	RS3	4451	3756	YES
ASSA ABLOY	Assa Abloy C310	4880	4505	NO
LSDA	-	4878	4493	NO
LSDA	-	4879	4495	NO



May 2018 (FOR ALL SKP SUBSCRIBERS)

2_2018 - **SILCA KEY PROGRAMS v. 21.9.x.xx**

Silca Key Programs UPGRADE 2/2018





For any info regarding the 2/2018 SKP Upgrade, please, read the NEWS document in the SILCA KEY PROGRAMS.




March 2018 (FOR SKP WEB SUBSCRIBERS)


1_2018 - SILCA KEY PROGRAMS v. 21.8.0.xx


TRIAx					NEW
Lock Manufacturer	Lock-system	New SSN	Data Card		
HYUNDAI	Hyundai Kona (2T-8W)	1990	4362	NO	
Yale	987 Plus	1992	4365	NO	
ABUS	ABUS BIKE 8N	1993	4366	NO	
Schlage	C999 Ultra	1994	4280	NO	
ABUS	ABUS BIKE 6N	1995	4368	NO	
VACHETTE	V-DIS Courte A	1996	4369	NO	
VACHETTE	V-DIS Longue B	1997	3448	NO	
VACHETTE	YALE 1000 EF 6P	1998	4369	NO	
VACHETTE	V-DIS+	1999	4266	NO	
GERDA	GERDA EVO (6+5+5)	2002	3580	NO	
VACHETTE	Vachette Radial NT	1012	2712	YES	
EUROLOCKS	dethleffs EU22RP (2T-6W)	2004	4350	NO	

QUATTROCODE					NEW
Lock Manufacturer	Lock-system	New SSN	Data Card		
HYUNDAI	Hyundai Kona (2T-8W)	1990	4362	NO	
YALE	987 Plus	1992	4365	NO	
ABUS	ABUS BIKE 8N	1993	4366	NO	
Schlage	C999 Ultra	1994	4280	NO	
ABUS	ABUS BIKE 6N	1995	4368	NO	
VACHETTE	V-DIS Courte A	1996	4369	NO	
VACHETTE	V-DIS Longue B	1997	3448	NO	
VACHETTE	YALE 1000 EF 6P	1998	4369	NO	
VACHETTE	V-DIS+	1999	4266	NO	
EUROLOCKS	Dethleffs EU22RP (2T-6W)	2004	4350	NO	

VIPER					NEW
Lock Manufacturer	Lock-system	New SSN	Data Card		
Hyundai	Hyundai Kona (2T-8W)	4799	4362	NO	

IDEA				NEW
Lock Manufacturer	Lock-system	New SSN	Data Card	
VITAL	ASEC-SECURITY	586	4388	NO
EUROSPEC	Eurospec C 3L	587	4389	NO

PRIMA LASER				NEW
Lock Manufacturer	Lock-system	New SSN	Data Card	
VITAL	ASEC-SECURITY	586	4388	NO
EUROSPEC	Eurospec C 3L	587	4389	NO

CODE PROGRAM				NEW
Lock Manufacturer	Lock-system	New SSN	Data Card	
PUNDRA	-	4842	561	NO
PUNDRA	-	4843	561	NO
PUNDRA	-	4844	561	NO

February 2018 (FOR SKP WEB SUBSCRIBERS)

1_2018 - **SILCA KEY PROGRAMS v. 21.7.1.xx**

Silca Key Programs UPGRADE 1/2018

WINDOWS® 10 BUG



Bug fixed

Silca has solved many issues of Silca Key Programs, OEM CLIENT and Wintransfer in Windows® 10.

These are our suggestions:

- Upgrade Windows® 10 to the latest version: 1709.xxxx
- Install SKP **version 21.7.1.54** or later via WEB or by DVD

Note : the **OEM CLIENT** customers will receive a DVD with **version 3.0.0.5** that solves many issues related to the program and not only specific of Windows® 10 Operative System.



January 2018 (FOR ALL SKP SUBSCRIBERS)

1_2018 - SILCA KEY PROGRAMS v. 21.7.x.xx

Silca Key Programs UPGRADE 1/2018





For any info regarding the 1/2018 SKP Upgrade, please, read the NEWS document in the SILCA KEY PROGRAMS.





November 2017 (FOR ALL SKP SUBSCRIBERS)

3_2017 - SILCA KEY PROGRAMS v. 21.6.x.xx

Silca Key Programs UPGRADE 3/2017		
	For any info regarding the 3/2017 SKP Upgrade, please, read the NEWS document in the SILCA KEY PROGRAMS.	

November 2017 (FOR SKP WEB SUBSCRIBERS)


2_2017 - SILCA KEY PROGRAMS v. 21.5.5.xx



 Triax / QCODE family				
Lock Manufacturer	Lock-system	New SSN	Data Card	
ABUS	Abus EC660	Series C-Z	4063	YES
AGENT	Agent NEW GMD-500(5+5+5)	1967	4329	
APECS	APECS RT-110(50/60C)-C-G (6P)	1929	4297	
A.P.FER	A.P.FER CHAMPIONS PRO (CP4-JP)	1893	3802	YES
ASEC-Security	ASEC 6P Dimple	1921	4286	
BMW	BMW (2T-8W)	1890	1842	
CES	POLLUX WZ (6+5+6)	1935	4303	YES
CES	POLLUX WZ (7+6+7)	1936	4304	YES
CISA	CISA AP4 Pmec-C KA	1861	4230	YES
CISA	CISA AP4 Pmec-A KA	1862	4230	YES
CISA	CISA AP4 Pmec-9 KA	1863	4230	YES
CISA	CISA AP4 Pmec-6 KA	1864	4230	YES
CISA	CISA AP4 Pmec-5 KA	1865	4230	YES
CISA	CISA AP4 Pmec-3 KA	1866	4230	YES
CISA	CISA AP4 Pmec-C CA	1970	4230	YES
CISA	CISA AP4 Pmec-A CA	1971	4230	YES
CISA	CISA AP4 Pmec-9 CA	1972	4230	YES
CISA	CISA AP4 Pmec-6 CA	1973	4230	YES
CISA	CISA AP4 Pmec-5 CA	1974	4230	YES
CISA	CISA AP4 Pmec-3 CA	1975	4230	YES


DOM	Dom Sigma Plus (Prof. 146)	1926	4294	YES
ELZETT	X11 (6+3+2)	1887	4262	
FAB	FAB (2T-4W)	1891	4265	
FORD	FORD HU101 (2T-10W)	1956	4320	
GEVY	GEVY 5 PINS	1924	4290	
GEVY	GEVY 6 PINS	1925	4292	
GEVY	GEVY 11 PINS	1927	4293	
HUF-FAB	VAG Mid (4T-9W+3W)	1706	4105	
HUF-FAB	VAG High (4T-10W+4W)	1892	4264	
HUGO	HUGO GR 4S	1919	4284	
HUGO	HUGO GR 3.5S	1920	4285	
IBFM	IBFM 2304/CS	1932	4300	
IBFM	IBFM 2306	1934	4302	
IBFM	IBFM 2309	1933	4301	
INAFER	INAFER (5P+6P)	1917	4280	
KIA	Kia (2T-- 8W)	1886	4129	
KIA	Kia (2T-- 8W)	1916	3336	
MAGNUM	Magnum 6P	1930	4299	
M&C	M&C Condor (snake+side pins)	1957	4319	YES
MG MONTI	MG ST-K09	1889	4263	YES
MUL.T.LOCK	Mul.T.Lock interactive	1894	4267	
OGDEN	Ogden Axial 45 (7P)	1789	446	YES
OGDEN	Ogden Axial 40 (7P)	1790	445	YES
PREFER	Prefer A	1885	4261	
PREFER	Prefer AA	1883	4259	
PREFER	Prefer DAA	1882	4252	
PREFER	Prefer EAA	1884	4260	
PREFER	Prefer GAB	1880	3941	
PREFER	Prefer HAA	1881	4250	
RAV-BARRIACH	LOXIS/ILA	1928	4296	
SUPERLOCK	Superlock SL 11/15	1918	4281	
TITAN	Titan K5-K55/CR T75 (275)	1931	2570	
TRIMARK	TriMark (2T-6W)	1888	4203	



YALE	Yale 2100	1895	4266	
------	-----------	------	------	--

At the moment the systems are not available on Triax-e.code and Triax 2 due lack of internal board memory.

Triax / QCODE family	Modified SSN	Key-system	Brand
 Bug fixed	Modified distance of the first cut from the Tip		
	1827	Mercedes HU126T (2T-10W)	HUF

 Viper				
Lock Manufacturer	Lock-system	New SSN	Data Card	
KIA	Kia (2T-- 8W)	1887	4129	
BMW	BMW (2T-8W)	4807	1842	
FAB	FAB (2T-4W)	4808	4265	
KIA	Kia (2T - 8W)	4809	3336	
Ford	FORD HU101 (2T-10W)	4810	4320	



Viper	Modified SSN	Key-system	Brand
 Bug fixed	Solved a problem related to decoding		
	850	Clio 3 (1T-6W) Emergency key	HUF

 Unocode299/399/PRO family and UC199				
Lock Manufacturer	Lock-system	New SSN	Data Card	
UAP	UAP Kinetica	4819	4246	
UAP	UAP 35mm cyl.	4820	4246	
PUDRA	-	4821	561	
WILKA	Wilka TH6 PR100	4822	2952	
GREATWALL	-	4823	4251	
YALE	Yale Jixin	4824	4253	



CDP	-	4825	4254	
BAB	-	4826	4255	
GELEM	SP148	4827	4256	
TONYON	TY330	4828	4257	
TRELOCK	MS 506	4829	4258	
TRELOCK	MS 506	4830	4258	
DOM	Dom Sigma Plus (Prof. 146)	4831	4295	YES
IBFM	IBFM SERIE 2300	4832	594	
FORD AUS	-	4834	4337	


August 2017 (FOR SKP WEB SUBSCRIBERS) 2_2017

SILCA KEY PROGRAMS v. 21.5.2.xx

Triax / QCODE family		New SSN	Key-system	Brand
	YES	1872	Securystar Extra Safe (6+6+6)	SECURYSTAR

(*) At the moment the system is not available on Triax-e.code and Triax 2 due lack of internal board memory.

Triax / QCODE family	Modified SSN	Key-system	Brand
 Bug fixed	Modified cutting path		
	 256	Evva 3KS-3KS+ (1T)	EVVA

Silca Key Program			
 Bug fixed	Corrected a problem related to cards manual adjustments		
	Solved problem in the Codemaker function related to the J1 jaw		



July 2017 (FOR ALL SKP SUBSCRIBERS)

2_2017 - **SILCA KEY PROGRAMS v. 21.5.x.xx**

Silca Key Programs UPGRADE 2/2017



For any info regarding the 2/2017 SKP Upgrade, please, read the NEWS document in the SILCA KEY PROGRAMS.



May 2017 (FOR SKP WEB SUBSCRIBERS) 1_2017

SILCA KEY PROGRAMS v. 21.4.1.xx

Triax / QCODE family		New SSN	Key-system	Brand
		1841	Yale YA99R (6+6)	YALE
	YES	1849	Keso K8000 Omega^2 Syst. 9 / Var. 44	KESO
	YES	1847	Keso K8000 Omega^2 (right frontprofile)	KESO
		1543	Mul.T.Lock Gardesa Tiger (7P)	MUL.T.LOCK
		1845	Mul.T.Lock interactive (223)	MUL.T.LOCK
		1846	Mul.T.Lock interactive (248)	MUL.T.LOCK
		646	Mul.T.Lock Junior/Classic	MUL.T.LOCK
		1844	Mul.T.Lock Gardesa Lion	MUL.T.LOCK
		1843	Mul.T.Lock integrator	MUL.T.LOCK
	YES	1848	Evva 4KS (1T)	EVVA
		1850	HOK HOK2R (6P)	HOK
	YES	1851	CISA AP4 PG	CISA
	YES	1853	CISA AP4 PG 3L	CISA
	YES	1854	CISA AP4 PG 3C	CISA
	YES	1855	CISA AP4 PG CA	CISA
	YES	1856	CISA AP4 PG P/S	CISA
	YES	1852	CISA AP4 PE	CISA
	YES	1857	CISA AP4 PE 3L	CISA
	YES	1858	CISA AP4 PE 3C	CISA
	YES	1859	CISA AP4 PE CA	CISA
YES	1860	CISA AP4 PE P/S	CISA	

(*) At the moment the system is not available on Triax-e.code and Triax 2 due lack of internal board memory.

Unocode299/399/PRO family and UC199		New SSN	Key-system	Brand
	YES	4214	RPS+	WINKHAUS
		4221	Cylinder VIP+	ASSA-ABLOY
		3719	HDI+/VMI+	VACHETTE
		4216	Cylinder VMI	ASSA-ABLOY

April 2017 (FOR SKP WEB SUBSCRIBERS) 1_2017

SILCA KEY PROGRAMS v. 21.4.0.xx

Silca Transponder Program

Silca Transponder Program has been updated with 120 new vehicle applications.

















Managing T80 transponders



As from this version the RW4 PLUS and FASTCOPY PLUS devices can manage the new Silca T80 transponder to be used for:

- Copying keys with Texas® Crypto 80 bit Toyota® transponders.
- Generating Texas® Crypto 80 bit transponders.

This RW4 PLUS/FASTCOPY PLUS software version also requires the internal C-Box module (version 329) to be updated; see further details in the device handbook and the information given in the on-line guide of "Silca Remote Service".

Triax / QCODE family	New SSN	Key-system	Brand
	 1770	Vela 1000	ABUS
	 1775	Vela 2000	ABUS
	 1830	XP20S	ABUS
	 1826	Condor	M&C
	 1832	Condor	M&C
	 1833	Condor	M&C
	 1834	Condor	M&C
	 1835	Condor	M&C
	 1836	Condor	M&C
	 1837	Condor	M&C
	 1838	Condor	M&C
	 1839	Condor	M&C
 1840	Condor	M&C	

(*) At the moment the system is not available on Triax-e.code and Triax 2 due lack of internal board memory.

Unocode299/399/PRO family and UC199	New SSN/Card	Key-system	Brand
	 4451/3756	RS3	RIELDA
	4805/4059	KeyMark X4 7P	MEDECO
	4806/4213	C300	ASSA-ABLOY
	4547/3864		MITSUBISHI



March 2017 (FOR ALL SKP SUBSCRIBERS)

1_2017 - SILCA KEY PROGRAMS v. 21.3.x.xx

Silca Key Programs UPGRADE 1/2017



For any info regarding the 1/2017 SKP Upgrade, please, read the NEWS document in the SILCA KEY PROGRAMS.



December 2016 (FOR ALL SKP SUBSCRIBERS)

3_2016 - **SILCA KEY PROGRAMS v. 21.2.x.xx**

Silca Key Programs UPGRADE 3/2016



For any info regarding the 3/2016 SKP Upgrade, please, read the NEWS document in the SILCA KEY PROGRAMS.



Quattrocode / Triax 2 / Triax-e.code



A new **R30** clamp that can house FUTURA removable jaws has been introduced for the **QUATTROCODE and TRIAX-e.code key-cutting machines**. The R30 clamp is necessary only for the new lock systems developed by SILCA with new jaws.

All existing options for QUATTROCODE and TRIAX-e.code will not be replaced by removable jaws for the R30 clamp.

Triax Quattro



A **R30** clamp that can house Triax PRO removable jaws has been introduced for the **TRIAX QUATTRO key-cutting machine**. All lock systems developed on the removable jaws of TRIAX PRO can also be used with the R30 clamp on the TRIAX QUATTRO.

Triax family



To use the **R30 clamp with the TRIAX-e.code, TRIAX 2 and TRIAX QUATTRO key-cutting machines**, replace the U102TT and U103TT tracers on the Tracer Tower with a single O4TT tracer. The necessary instructions are included in the box of the optional R30 clamp (D746897ZB).

Triax 2 / Triax-e.code




TRIAX-e.code e TRIAX 2: the machine memory is full.


This update implements all the lock systems already available on the QUATTROCODE, TRIAX QUATTRO and TRIAX PRO key-cutting machines. These systems and the new ones to be developed by Silca will be included **ONLY** in Silca Key Programs and not incorporated into the machines. Therefore, Silca Key Programs is necessary to use the new systems with the **TRIAX-e.code and TRIAX 2 key-cutting machines**.


Triax Pro



All lock systems that can be used with the standard R29-01J-02J clamp have been implemented.

Triax PRO	Modified SSN	Key-system	Brand
 Bug fixed	Solved a problem related to the cutting algorithm		
	60	Kaba Titan-Aura-Combi (K22-K32-K33)	KABA
	19	Kaba Titan-Titan Combi-Aura(K22-K32-K33)	KABA

Triax / QCODE family	Modified SSN	Key-system	Brand
 Bug fixed	Corrected code table in according with manufacturer's specifications.		
	🔒 1235	Iseo R50 Cantiere (Chiave Cantiere)	ISEO

Unocode Pro			
 Bug fixed	Problem solved in "PC queue" when a number of passages are used to cut the key		





November 2016 (for SKP Web subscribers) **2_2016 - SILCA KEY PROGRAMS v. 21.1.3.xx**

Only for Triax PRO

The following systems are available with the new jaws:



New SSN	Key-system	Clamp	Brand
191	4SE MC10R (6P)	R29-62J-63J	MCM
201	450 (FT500)	R29-64J-65J	FICHET
202	480 (FT510)	R29-64J-65J	FICHET
 526	X-TRA (5+5)	R29-80J-81J	WINKHAUS
 703	X-TRA Inclined (5P)	R29-80J-81J	WINKHAUS
1049	Logic 17 (5+5)	R29-66J-67J	FIAM
1050	Logic 18/19 (5+5)	R29-66J-67J	FIAM
1058	Template	R29-68J-69J	SILCA
1101	Twin 6000 (5P)	R29-70J-71J	ASSA
 1343	D20 (6+7)	R29-72J-73J	ABUS
 1359	Astral Tekno Special Profiles	R29-74J-75J	CISA
 1360	Bricard Serial XP Special Profiles	R29-74J-75J	CISA
1559	Prestige B5	R29-76J-77J	LEHMANN
 1613	ON-tra (P1)	R29-78J-79J	WINKHAUS
 1614	ON-tra (P3)	R29-78J-79J	WINKHAUS
 1616	ON-tra + (P1-P1)	R29-78J-79J	WINKHAUS
 1617	ON-tra + (P1-P2)	R29-78J-79J	WINKHAUS
 1618	ON-tra + (P1-P3)	R29-78J-79J	WINKHAUS
 1619	ON-tra + (P1-P4)	R29-78J-79J	WINKHAUS
 1620	ON-tra + (P1-P5)	R29-78J-79J	WINKHAUS
 1621	ON-tra + (P1-P6)	R29-78J-79J	WINKHAUS
 1622	ON-tra + (P1-P7)	R29-78J-79J	WINKHAUS
 1623	ON-tra + (P1-P8)	R29-78J-79J	WINKHAUS
 1624	ON-tra + (P3-P1)	R29-78J-79J	WINKHAUS
 1625	ON-tra + (P3-P2)	R29-78J-79J	WINKHAUS
 1626	ON-tra + (P3-P3)	R29-78J-79J	WINKHAUS
 1627	ON-tra + (P3-P4)	R29-78J-79J	WINKHAUS
 1628	ON-tra + (P3-P5)	R29-78J-79J	WINKHAUS
 1629	ON-tra + (P3-P6)	R29-78J-79J	WINKHAUS
 1630	ON-tra + (P3-P7)	R29-78J-79J	WINKHAUS
 1631	ON-tra + (P3-P8)	R29-78J-79J	WINKHAUS
 1667	ON-tra (EGS)	R29-78J-79J	WINKHAUS
 1690	Astral Tekno CA (Special Profiles)	R29-74J-75J	CISA
 1691	Astral Tekno CE P-S (Special Prof.)	R29-74J-75J	CISA








Triax / QCODE family	New SSN	Key-system	Brand
	1770 (*)	Vela 1000	ABUS
	1775 (*)	Vela 2000	ABUS
	1776 (*)	I6BM	BASI
	 1769 (*)	EVOK22 (11 Pin)	SECUREMME
	 1778 (*)	EVOK64 (11 Pin)	SECUREMME
	 1777 (*)	EVOK64 (10 Pin)	SECUREMME
	 1779 (*)	IX6 SR S (prof. 250/251/252/253/254)	DOM













(*) At the moment the system is not available on Triax-e.code and Triax 2 due lack of internal board memory.

Unocode299/399/PRO family and UC199	New SSN/Card	Key-system	Brand
	4764/4145		RENAULT - DACIA
	 4765/4146	Matrix	M&C
	4766/4147	Triton 5900 Ej CLIQ to UC199	ASSA
	4767/4148	Triton - 501 Ikke CLIQ to UC199	RUKO
	4768/4149	Triton Ikke CLIQ to UC199	TRIO-VING
	4769/4151	AUB system	YALE


Triax / QCODE family	Modified SSN	Key-system	Brand
 Bug fixed	Changed cutter in according with manufacturer specifications		
	1402	SY55 - C11	FACCHINETTI
	1403	SY30 SY32 SY35 - C11	FACCHINETTI


Triax family	Modified SSN	Key-system	Brand
 Bug fixed	Moved the fixed depth during the cutting of the Axis 1.		
	 1231	IXGAMMA (Prof.153)(5+3+7P)	DOM
	 1244	IXGAMMA (Prof.154)(5+3+7P)	DOM
	 1245	IXGAMMA (Prof.155)(5+3+7P)	DOM

Triax Quattro Triax PRO	Modified SSN	Key-system	Brand
 Bug fixed	On Axis 3, changed cutter and used circular interpolation in according with manufacturer specifications.		
	1247	IX Saturn (5+4+7P)	DOM
	1494	IX Saturn (Prof. 168)	DOM
	 1507	IXSATS (Prof. 169)	DOM
	 1508	IXSATS (Prof. 170)	DOM
	 1509	IXSATS (Prof. 171)	DOM
	 1510	IXSATS (Prof. 172)	DOM


Triax PRO	Modified SSN	Key-system	Brand
 Bug fixed	Added the 29R-01J-02J calmp set		
	 1032	2 in 1 MK (prof 233)	DORMA
	 1215	2 in 1 MK (prof 233)	DORMA
	 1461	T250 (6+5P)	TITAN
	 1462	T250 (2T-5W)	TITAN
	Added the 29R-24J-25J calmp set		
	864	C3 (5+5)	LINCE

October 2016 (for SKP Web subscribers) 2_2016 - SILCA KEY PROGRAMS v. 21.1.2.xx

Triax / QCODE family	Modified SSN	Key-system	Brand
 Bug fixed	Fixed the search by code in according with manufacturer specifications		
	🔒 1688	Astral Tekno CA	CISA
	🔒 1689	Astral Tekno CE P-S	CISA
	🔒 1690	Astral Tekno CA (Special Profiles)	CISA
	🔒 1691	Astral Tekno CE P-S (Special Profiles)	CISA


Triax Pro	Modified SSN	Key-system	Brand
 Bug fixed	Modified movements to avoid "Faulty contact made" when cutting the key back		
	19	Titan-Titan Combi-Aura (K22-K32-K33)	KABA
	60	Titan-Aura-Combi (K22-K32-K33)	KABA


September 2016 (for SKP Web subscribers) 2_2016 - SILCA KEY PROGRAMS v. 21.1.1.xx


Triax / QCODE family	New SSN	Key-system	Brand
	1734 (*)	Euro Locks EU21P (2T-7/8W)	EURO LOCKS
	🔒 1731 (*)	Kaba ExperT Cross S1.0a (K89A)	KABA
	🔒 1732 (*)	Kaba ExperT Cross S1.0am (K89A)	KABA
	🔒 1736 (*)	Kaba ExperT Cross S1.0am (K89A) D. Code	KABA
	🔒 1733 (*)	Kaba ExperT Cross S1.0b (K89B)	KABA
	🔒 1735 (*)	Kaba ExperT Cross S1.0bm (K89B)	KABA
	🔒 1737 (*)	Kaba ExperT Cross S1.0bm (K89B) D. Code	KABA
	🔒 1738 (*)	M&T Champions Pro CP4 (C6LJ2)	M&T
	🔒 1739 (*)	M&T Champions Pro CP4 (C6LJK)	M&T
	1740	Mauer Crypto (6+6+6)	MAUER

(*) At the moment the system is not available on Triax-e.code and Triax 2 due lack of internal board memory.

Unocode299/399/PRO family and UC199	New SSN/Card	Key-system	Brand
	4763/538		HUWIL

Triax / QCODE family	Modified SSN	Key-system	Brand
 Bug fixed	Modified data cards in according with manufacturer specifications		
	🔒 1688	Cisa Astral Tekno CA	CISA
	🔒 1690	Cisa Astral Tekno CA (Special Profiles)	CISA

Triax PRO	Modified SSN	Key-system	Brand
 Bug fixed	Added the 29R-01J-02J calmp set		
	🔒 804	Dom IX6 SR E (prof 132)	DOM

Viper family	Modified SSN	Key-system	Brand
 Bug fixed	Solved a problem related to the cutting algorithm		
	694	Ford C-Max (2T-10W)	FORD
	1165	Ford (2T-10W)	FORD
	1513	Ford (2T-10W)	FORD

July 2016 (for all SKP subscribers)














2_2016 - **SILCA KEY PROGRAMS v. 21.1.x.xx**



Silca Key Programs UPGRADE 2/2016




For any info regarding the 2/2016 SKP Upgrade, please, read the NEWS document in the SILCA KEY PROGRAMS.



Triax / QCODE family	Modified SSN	Key-system	Brand
 Bug fixed	Modified cutting algorithm in according with manufacturer specifications		
	 1578	Pro Star-Mobile Code (6+6+6)	SECURYSTAR
	547	V-18 (6+6+6)	GOAL
	1182	V-18 (7+7+7)	GOAL
	Added codes from 6001 to 6314		
	921	Cadillac (2T- 8W)	HUF
	766	Opel - (2T- 8W)	HUF
	984	Special Opel (2T-8W)	HUF
	Improved dimple decoding		
	 1417	Bravus 1000 (Shoulder stop)	ABUS
	 1419	Bravus 3000 (Shoulder stop)	ABUS
	 1420	Bravus 4000 (Shoulder stop)	ABUS
	 1536	Bravus 3000 (Tip stop)	ABUS
	 1646	Bravus 1000 (Tip stop)	ABUS
	 1654	Bravus 4000 (Tip stop)	ABUS
	 1418	Bravus 2000 (Shoulder stop)	ABUS
 1650	Bravus 2000 (Tip stop)	ABUS	
 1647	O9	OXLOC	
 1701	O9,3	OXLOC	
 1700	O9,2	OXLOC	

QCODE family	Modified SSN	Key-system	Brand
 Bug fixed	Added depths on axis 5 and 6 in according with manufacturer specifications		
	 1012	Vachette Radial NT	VACHETTE


Viper family	Modified SSN	Key-system	Brand
 Bug fixed	Added codes from 6001 to 6314		
	921	Cadillac (2T- 8W)	HUF
	766	Opel - (2T- 8W)	HUF





June 2016 (for SKP Web subscribers)


1_2016 - **SILCA KEY PROGRAMS v. 21.0.6.xx**

Triax / QCODE family	New SSN	Key-system	Brand
	 1722(*)	Trelock InX M2 (4T-4W)	TRELOCK
	 1723(*)	Trelock InX ML2 (4T-4W)	TRELOCK
	1707	Yardeni 6 Master-No cut tip	YARDENI
	1708	Yardeni 6 Regular-Cut tip	YARDENI
	1709	Yardeni 6 Master-Cut tip	YARDENI

(*) At the moment the system is not available on Triax-e.code and Triax 2 due lack of internal board memory.

Unocode299/399/PRO family and uc199	Modified SSN/card	Key-system	Brand
 Bug fixed	Modified the clamp side		
	4752	Chiave ridotta 5P	MG (MONTI)

Triax / QCODE family	Modified SSN	Key-system	Brand
 Bug fixed	Changed cutter in according with manufacturer specifications		
	 256	Evva 3KS - 3KS+ (1T)	EVVA
	 1221	Evva 3KS (2T)	EVVA
	 1300	Evva 3KS+ (2T)	EVVA
	Modified data cards in according with manufacturer specifications		
	750	Yardeni 6 Regular-No cut tip	YARDENI
	1411	Trelock RS455-H2 (4T-4W)	TRELOCK

Viper family	Modified SSN	Key-system	Brand
 Bug fixed	Solved a problem related to the decoding		
	850	Clio 3 (1T-6W)	VALEO RENAULT

May 2016




(for SKP Web subscribers)





1_2016 - **SILCA KEY PROGRAMS v. 21.0.4.xx**

Silca Key Programs UPGRADE



Updated the comparative list.

Unocode299/399/PRO family and UC199	New SSN/Card	Key-system	Brand
	 4735/4079	O8,3	OXLOC
	 4736/4080	O8,2	OXLOC
	4743/1039		HUDSON
	4744/1039		HUDSON
	4745/1039		ESP
	4746/1039		ESP
	4747/1039		ESP
	4748/1039		HUDSON
	4749/1039		HUDSON
	4750/4101	Normal key 4 Pins	MG (MONTI)
	4751/4101	Normal key 5 Pins	MG (MONTI)
	4752/4102	Short key 5 Pins	MG (MONTI)
	4753/4103	Simmetrical key 6 Pins	MG (MONTI)
	4754/561		ESP
	4755/4106	RF-360	BEMA


Triax / QCODE family	New SSN	Key-system	Brand
	 1700	O9,2	OXLOC
	 1701	O9,3	OXLOC
	 1702	O8,2 (4P)	OXLOC
	 1703	O8,3 (4P)	OXLOC
	1704(*)	Vag HU162T (4T-8W)	VOLKSWAGEN SKODA
	295	5 Pins	RONIS
	269	5 Pins	CODEM

(*) At the moment the system is not available on Triax-e.code and Triax 2 due lack of internal board memory.



May 2016 (for SKP Web subscribers)

1_2016 - **SILCA KEY PROGRAMS v. 21.0.3.xx**

Silca Transponder Program	Silca Transponder Program and RW Software Upgrade	
	New Software Upgrade of RW devices (ver. 04.01.084) on : RW4, RW4 PLUS, FASTCOPY and FASTCOPY PLUS devices.	

April 2016 (for SKP Web subscribers) **1_2016 - SILCA KEY PROGRAMS v. 21.0.2.xx**

Unocode299/399/PRO family and uc199	Modified SSN/card	Key-system	Brand
	Solved a problem related to the stop key		
	4408/3623	Fab 200 RS	FAB

Silca Transponder Program	Silca Transponder Program and RW Software Upgrade		
	New Software Upgrade of RW devices (ver. 04.00.083) on : RW4, RW4 PLUS, FASTCOPY and FASTCOPY PLUS devices.		


April 2016 (for SKP Web subscribers) **1_2016 - SILCA KEY PROGRAMS v. 21.0.1.xx**

Unocode299/399/PRO family and UC199	New SSN/Card	Key-system	Brand
	4738/4082		L&F
	4737/4081		EURO LOCKS
	4734/1643		BURG
	4741/2888		ANKERSLOT
	4739/3351		NEMEF
	4740/3351		NEMEF

Triax e-code/Triax 2 STAND ALONE mode			
	The internal memory of this cutting machine is full. All new systems will be available only in the Silca Key Program and not in STAND ALONE mode.		

Triax / QCODE family	New SSN	Key-system	Brand
	1679	Champions Pro CP4-CM7	MOTTURA
	1680	Champions Pro CP4 Armo-Riarmo	MOTTURA
	1681	Champions Pro CP4 Matic	MOTTURA
	1682	Champions Pro CP4 Riarmo Att-Dis	MOTTURA
	1683	Champions C28 Plus	MOTTURA
	1684	Champions C39	MOTTURA
	1685	Champions C43 Plus (5+5)	MOTTURA
	1688	Astral Tekno CA	CISA
	1689	Astral Tekno CE P-S	CISA
	1690	Astral Tekno CA (Special Profiles)	CISA
	1691	Astral Tekno CE P-S (Special Profiles)	CISA
	1692	R7 Extra Cantiere (Cantiere)	ISEO
	1693	R7 Extra Cantiere (Padronale)	ISEO
	1694	R7 Extra Ricifrabile (Cantiere)	ISEO
	1695	R7 Extra Ricifrabile (Padronale 1)	ISEO

	🔒 1696	R7 Extra Ricifrabile (Padronale 2)	ISEO
	1697	DEC261 SKG	DORMA-ISEO

Triax / QCODE family	Modified SSN	Key-system	Brand
 Bug fixed	Corrected a problem related to the cutting algorithm		
	1001	Kia - Hyundai (4T-6W)	KIA-HYUNDAI
	1310	Kia - Hyundai (4T-6W)	KIA-HYUNDAI
	Corrected code table in according with manufacturer's specifications.		
	1499	D10/D15 (6+7)	ABUS
	Decoding enabled		
	1550	Valeo (2T - 8W)	VALEO

March 2016 (for ALL SKP subscribers)

1_2016 - **SILCA KEY PROGRAMS v. 21.0.x.xx**

Silca Key Programs UPGRADE 1/2016



For any info regarding the 1/2016 SKP Upgrade, please, read the NEWS document in the SILCA KEY PROGRAMS.



Triax e-code/Triax 2 STAND ALONE mode





The internal memory of this cutting machine is full.
All new systems will be available only in the Silca Key Program and not in STAND ALONE mode.


Triax / QCODE family	Modified SSN	Key-system	Brand
	Modified data cards according to manufacturer specifications		
	960	V-18 (6+6+6)	GOAL
	1613	(7+7+7) (7.9mm)	WEST
	1614	(5+5) (6.5mm)	WEST
	1615	(6+6) (8.0mm)	WEST
	1618	New X-Key (7+6+6)	SHOWA
	2184	GMD-500 (5+5+5)	AGENT
	2197	V-18 Master (12+12+6)	GOAL
	2491	D-9 (3+3+3)	GOAL
	2494	V-18 Master (14+14+7)	GOAL
	2839	Tostem (4T-5W)	TOSTEM
	2992	West (6+6) (8.0mm) New	WEST
	3035	Kodai (15P)	NAGASAWA
	3060	V-18 (7+7+7)	GOAL
	3223	Alpha (5+4)	ALPHA
	3224	Keylex (5+5+5)	NAGASAWA
	3477	Seacuretech (5+5) (2T-3W)	SEACURETECH
	3477	2000 Series (5+5) (2T-3W)	YALE
	3480	Seacuretech (5+5)	SEACURETECH
	3480	2000 Series (5+5)	YALE
	3531	Tostem (4T-7W)	TOSTEM
	3732	West (3+3) (8mm)	WEST
	3734	Agent (6+6)	AGENT
	3735	West (8+8) (8.0mm)	WEST
	3736	West (5+5) (6.5mm) New	WEST
	3874	W2-DAC (4T-4W)	SHOWA



Bug fixed

QCODE family	Modified SSN	Key-system	Brand
 Bug fixed	Solved a problem related to the decoding		
	34	Sea (4T-5W)	SEA
	35	Sea 20/23 (4T-5W)	SEA
	157	Sea 3 (4T-5W)	SEA
	297	Sea 2 (4T-5W)	SEA

Viper family	Modified SSN	Key-system	Brand
 Bug fixed	Modified data cards according to manufacturer specifications		
	2074		B&S

Prima Laser/Idea family	Modified SSN	Key-system	Brand
 Bug fixed	Added code table in according with manufacturer's specifications.		
	579	6601	MOBELLA
	Corrected code table in according with manufacturer's specifications.		
	434	TrioVing 17	TRIO-VING
	513	TrioVing_17	TRIO-VING

January 2016 (for SKP Web subscribers)


3_2015 - **SILCA KEY PROGRAMS v. 20.8.1.xx**






Unocode299/399 family and UC199	New SSN/Card	Key-system	Brand
	4635/4016		CHICAGO
	4636/4017		CRAFTSMAN
	4653/4022		MINDA-HUF
	4654/4037		MINDA-HUF
	4655/4038		MINDA-HUF
	4656/4039		MINDA-HUF
	4657/4040		BURG
	4658/4041	Market TAIWAN	FORD
	4659/4042	YCF 35-35	FEDERAL
	4660/1041		CHICAGO
	4661/730	V63	ABUS
	4662/729	Z74	ABUS
	4663/4043	40/50	SOFICLEF
	4664/4015		ILLINOIS
	4665/4015		ILLINOIS
	4666/1054		JOFCO
	4667/1054		NATIONAL
	4668/1054		NATIONAL
	4669/1054		NATIONAL
	4670/4044	Market TAIWAN	MAZDA
	4671/1054		NATIONAL
	4672/1054		NATIONAL
	4673/666	Profile G17	GUARD
	4674/1054		NATIONAL
	4675/1054		NATIONAL
	4676/1054		NATIONAL
	4677/1054		NATIONAL
	4678/1054		NATIONAL
	4679/1041		CHICAGO
	4680/1041		CHICAGO
	4681/1041		CHICAGO
	4682/1041		CHICAGO
	4683/1041		CHICAGO
	4684/1041		CHICAGO
	4685/1041		CHICAGO
	4686/1041		CHICAGO
	4687/1041		CHICAGO
	4688/1041		CHICAGO
	4689/1041		CHICAGO
	4690/1041		CHICAGO
	4691/1041		CHICAGO
	4692/1041		CHICAGO
	4693/1041		CHICAGO
	4694/4018		PUNDRA
	4695/4018		PUNDRA
	4696/539		HUWIL








	4635/4016		CHICAGO
	4636/4017		CRAFTSMAN


Triax e-code/Triax 2 STAND ALONE mode

	<p>The internal memory of this cutting machine is full. All new systems will be available only in the Silca Key Program and not in STAND ALONE mode.</p>
---	--

Triax / QCODE family	New SSN	Key-system	Brand
	 1649	DWM6 (2T-6W+4+5)	CES
	 1651	DWM6 (2T-6W)	CES
	 1652	DWM5 (2T-5W+4+5)	CES
	 1653	DWM5 (2T-5W)	CES
	1658	Emergency Key (5+5+4)	NISSAN
	1660	P2	WILKA
	1661	PR300Q	WILKA
	1662	P3Q	WILKA
	1663	2000 Plus Series (5+5)	YALE

Viper machine	New SSN	Key-system	Brand
	2197	Market TAIWAN	FORD
	2198		ABUS
	2199		ABUS
	2200	Market TAIWAN	MAZDA
	Added code table in according with manufacturer's specifications.		
	2020		SUBARU

Triax / QCODE family	Modified SSN	Key-system	Brand
 Bug fixed	Returned to the standard decoding		
	57	Keso K2000 Syst. 3 / Var. 4 (5 Axis)	KESO
	273	Keso K2000S Syst. 4 / Var. 3 (3 Axis)	KESO
	673	Keso K2000S Omega Syst. 4/Var. 13 (3mm)	KESO
	 1158	Keso K4000 Omega Syst. 7 / Var. 39	KESO
	1298	Keso K2000 Syst. 3/Var. 4 (5mm)	KESO
	1299	Keso K2000S Omega Syst. 4 / Var. 3 (5mm)	KESO
	 1466	Keso K4000 Omega (right frontprofile)	KESO
	 1576	Keso K2500FP (Syst.7 / Var.41)	KESO
	1656	Keso K10RS (3 Axis)	KESO
	1657	Keso K10RS Omega Syst. 4 / Var. 3 (5mm)	KESO

Prima Laser/Idea family	Modified SSN	Key-system	Brand
 Bug fixed	Modified data cards according to manufacturer specifications		
	584	Securmap 11	SECUREMME



SKP PRO WEB Update



December 2015 (for ALL SKP subscribers)

3_2015 - SILCA KEY PROGRAMS v. 20.8.x.xx

Silca Key Programs UPGRADE 3/2015




For any info regarding the 3/2015 SKP Upgrade, please, read the NEWS document in the SILCA KEY PROGRAMS.




Triax e-code/Triax 2 STAND ALONE mode



The internal memory of this cutting machine is full.
All new systems will be available only in the Silca Key Program and not in STAND ALONE mode.

QCODE family	Modified SSN	Key-system	Brand
 Bug fixed	Solved a problem related to the cutting algorithm		
	261-295-926-607	RS3-Abus EP 10	VARIOUS
	303	Prefer (3+3W)	PREFER
	302	Prefer (3+3W+2)	PREFER

TRIAx family	Modified SSN	Key-system	Brand
 Bug fixed	Solved a problem related to the decoding		
	1348	BMW BW9EHP (4T-4W)	ZADI

November 2015 (for SKP Web subscribers)

2_2015 - SILCA KEY PROGRAMS v. 20.7.6.xx

Triax e-code/Triax 2 STAND ALONE mode




The internal memory of this cutting machine is full.
All new systems will be available only in the Silca Key Program and not in STAND ALONE mode.

Silca Key Programs



Corrected a problem related importing of DAT file for flat keys, with programs SSI







Unocode299/399 family and UC199	Modified Card	Key-system	Brand
 Bug fixed	Corrected the space of cut.		
	3907	Vitess 2000	PFAFFENHAIN
	3910	Zolit/Vitess 1000	PFAFFENHAIN
	3913	Vitess 1000	PFAFFENHAIN
	3915	Zolit/Vitess 2000	PFAFFENHAIN
	3916	Zolit/Vitess 4000	PFAFFENHAIN
	3922	Vitess 4000	PFAFFENHAIN






November 2015 (for SKP Web subscribers) 2_2015 - **SILCA KEY PROGRAMS v. 20.7.5.xx**

Triax e-code/Triax 2 STAND ALONE mode



The internal memory of this cutting machine is full.
All new systems will be available only in the Silca Key Program and not in STAND ALONE mode.

Triax / QCODE family	New SSN	Key-system	Brand
	 1637	(Pr.169-170-171-172)(Precoded)	INN
	 1638	(Prof. 169)	INN
	 1639	(Prof. 170)	INN
	 1640	(Prof. 171)	INN
	 1641	(Prof. 172)	INN
	1642	Pacri (5+5)	PACRI
	1643	164 DBNE (5+5)	KALE


QCODE family	Modified SSN	Key-system	Brand
 Bug fixed	Corrected a problem related to the decoding algorithm		
	302	Prefer (3+3W)	PREFER
	303	Prefer (3+3W+2)	PREFER
	Corrected a problem related to movement of the cutting		
	 261	RS3/CHIFRAL/EP10 (4+4+5)	ABUS/CISA/BRICARD
	 607	RS3 75 (4+4+5)	CISA
	 925	EP10 (4+4+5)	ABUS
 926	EP10 (4+4+5)	ABUS	

Triax e-code/Triax 2



Bug fixed

A new machine internal program which solves a generic problem related to the decoding and the carriage speed.

Unicode299/399 family and UC199	New SSN/Card	Key-system	Brand
	4348/3550		MIWA
	4483/3806		HONDA
	4599/3973	Market Jap. stop 3	MITSUBISHI
	4600/3974		MIWA
	4601/3975	Market Japan.	MIWA
	4602/3976	ATL4 & ATL5	SQUIRE&SONS
	4603/3979	KB	SQUIRE&SONS
	4604/3982		EURO LOCKS
	4605/3984		RONIS
	4606/3985	Chinese market (reversed cuts)	TOYOTA
	4607/3987		MINDA-HUF

4608/4003




















HONDA


October 2015 (for SKP Web subscribers) 2_2015 - SILCA KEY PROGRAMS v. 20.7.3.xx


Silca Key Programs UPGRADE



The test of SILCA KEY PROGRAMS with WINDOWS 10 resulted positive.


Triax / QCODE family	New SSN	Key-system	Brand
	1612	Avocet Pioneer plus (6P)	FEDERAL
	1615	TWO (6P)	CORBIN
	 1613	ON-tra (P1)	WINKHAUS
	 1614	ON-tra (P3)	WINKHAUS
	 1616	ON-tra + (P1-P1)	WINKHAUS
	 1617	ON-tra + (P1-P2)	WINKHAUS
	 1618	ON-tra + (P1-P3)	WINKHAUS
	 1619	ON-tra + (P1-P4)	WINKHAUS
	 1620	ON-tra + (P1-P5)	WINKHAUS
	 1621	ON-tra + (P1-P6)	WINKHAUS
	 1622	ON-tra + (P1-P7)	WINKHAUS
	 1623	ON-tra + (P1-P8)	WINKHAUS
	 1624	ON-tra + (P3-P1)	WINKHAUS
	 1625	ON-tra + (P3-P2)	WINKHAUS
	 1626	ON-tra + (P3-P3)	WINKHAUS
	 1627	ON-tra + (P3-P4)	WINKHAUS
	 1628	ON-tra + (P3-P5)	WINKHAUS
	 1629	ON-tra + (P3-P6)	WINKHAUS
	 1630	ON-tra + (P3-P7)	WINKHAUS
	 1631	ON-tra + (P3-P8)	WINKHAUS
1632	W551 (4+4+3)	PREFER	
1633	S211 (5+5+4)	PREFER	
1635	Subaru Emergency Key (2T-4W)	TOKAI RIKA	

Viper machine	New SSN	Key-system	Brand
	2194	Subaru Emergency Key (2T-4W)	TOKAI RIKA

Unocode299/399 family and UC199	New SSN/Card	Key-system	Brand
	4595/1039		BOMMER
	4592/3960	TE01	TOKOZ
	4593/3961	EG	UNION
	4585/3935		JPM
	4585/3937		SUZUKI
	4586/3431		ANKERSLOT
	4588/723		EURO LOCKS
	4589/723		EURO LOCKS
	4591/1435		EURO LOCKS
	4592/1643		BURG


September 2015 (for SKP Web subscribers) 2_2015 - **SILCA KEY PROGRAMS v. 20.7.2.xx**

Triax / QCODE family	New SSN	Key-system	Brand
	1463	UL20 (6P)	PREFER

Triax / QCODE family	Modified SSN	Key-system	Brand
 Bug fixed	Modified data cards according to manufacturer specifications		
	20	K2000 (82D-3A)	KESO
	273	K2000S (20+20+20)	KESO
	1299	K2000S Omega (5mm)	KESO
	Returned to the standard decoding		
	20	K2000 (82D-3A)	KESO
	21	K2000 (90D-3A)	KESO
	105	1000/Lips (3A)	KESO
	598	K1000S (3 Axis)	KESO
	807	K1000 (3 Axis)	KESO



July 2015 (for SKP Web subscribers)

2_2015 - SILCA KEY PROGRAMS v. 20.7.1.xx

Triax family	Modified SSN	Key-system	Brand
 Bug fixed	Corrected a problem related to movement of the decoding		
	1285	Euro Locks (2T-5W)	EURO LOCKS


July 2015 (for ALL SKP subscribers)

2_2015 - SILCA KEY PROGRAMS v. 20.7.x.xx

Silca Key Programs UPGRADE 2/2015		
	For any info regarding the 2/2015 SKP Upgrade, please, read the NEWS document in the SILCA KEY PROGRAMS.	



July 2015 (for SKP Web subscribers)


1_2015 - SILCA KEY PROGRAMS v. 20.6.4.xx


Triax / QCODE family	Modified SSN	Key-system	Brand
 Bug fixed	Modified data cards according to manufacturer specifications		
	393	IX5 DAS (pf.038/101)	DOM
	20	K2000 (82D-3A)	KESO
	21	K2000 (90D-3A)	KESO


May 2015 (for SKP Web subscribers)


1_2015 - SILCA KEY PROGRAMS v. 20.6.2.xx

Triax / QCODE family	New SSN	Key-system	Brand
	1570	118 (6P)	CHAIRO
	1571	280/50 (6+6)	DURO
	1572	Bmw (2T-8W)	HUF
	 1577	New Star Guard (6+6+6)	SECURYSTAR
	 1578	Pro Star-Mobile Code (6+6+6)	SECURYSTAR
	 1576	Casa	KESO

Triax / QCODE family	Modified SSN	Key-system	Brand
 Bug fixed	Modified data cards according to manufacturer specifications		
	57	K2000 (5 Axis)	KESO
	20	K2000 (3 Axis)	KESO
	21	K2000S (3 Axis)	KESO
	277	K2000S (Step-Drilling)	KESO
	273	K2000S (20+20+20)	KESO
	673	K2000S Omega (3mm)	KESO
	1298	K2000 (5mm)	KESO
	1299	K2000S Omega (5mm)	KESO
	598	K1000S (3 Axis)	KESO
	1264	NW4 (5P - 2T-5W)	MAUER / MLS



Triax-e.code	Modified SSN	Key-system	Brand
 Bug fixed	Fixed entry tip on laser track according to manufacturer specifications		
	1420	Bravus 4000	ABUS

Unocode299/399 family and UC199	New SSN/Card	Key-system	Brand
	4566/561		CHICAGO
	4568/3890	DG1	SARGENT
	4569/3891	DG2-DG3	SARGENT
	4570/258		GIOBERT
	4571/3899	ATK	AVOCENT
	4573/3899		WESLOCK

Viper machine	New SSN	Key-system	Brand
	2184	Bmw (2T-8W)	HUF




March 2015 (for all SKP subscribers)


1_2015 - **SILCA KEY PROGRAMS v. 20.6.x.xx**


Silca Key Programs UPGRADE 1/2015		
	For any info regarding the 1/2015 SKP Upgrade, please, read the NEWS document in the SILCA KEY PROGRAMS.	

February 2015 (for SKP Web subscribers)

2_2014 - **SILCA KEY PROGRAMS v. 20.5.0.xx**


Triax / QCODE family	New SSN	Key-system	Brand
	1550	Valeo (2T - 8W)	TOYOTA
	 1553	Palladium (7P)	VIRO
	 1554	Palladium PV (7P)	VIRO

Triax / QCODE family	Modified SSN	Key-system	Brand
 Bug fixed	Modified cutting algorithm and cutter in according to manufacturer specifications.		
	747	164SN-ST-SK-SM-SR-DSN-OBS S (6P)	KALE
	1545	SPC F6 (6P)	S2

Viper machine	Modified SSN	Key-system	Brand
 Bug fixed	Corrected a problem related to movement of the cutting tip.		
	2177	Valeo (2T-8W)	TOYOTA

January 2015 (for SKP Web subscribers)

2_2014 - **SILCA KEY PROGRAMS v. 20.4.1.xx**

Viper machine	Modified SSN/card	Key-system	Brand
 Bug fixed	Corrected a problem related to movement of the cutting tip.		
	1117	Valeo (2T-7W)	CITROËN FIAT LANCIA MAN PEUGEOT

December 2014 (for ALL SKP subscribers)

2_2014 - **SILCA KEY PROGRAMS v. 20.4.x.xx**


Silca Key Programs UPGRADE 2/2014




For any info regarding the 2/2014 SKP Upgrade, please, read the NEWS document in the SILCA KEY PROGRAMS.





October 2014 (for SKP Web subscribers) 1_2014 - SILCA KEY PROGRAMS v. 20.3.1.xx



Silca Key Programs	
 Bug fixed	Corrected a problem in the SSI related to blank cuts in edge keys


September 2014 (for SKP Web subscribers) 1_2014 - SILCA KEY PROGRAMS v. 20.3.0.xx

Triax / QCODE family	Modified SSN	Key-system	Brand
 Bug fixed	Modified data cards according to manufacturer specifications		
	302	Rbz (3+3W)	PREFER / RBZ
	303	(3+3W+2)	PREFER
	88	Quattro 1.0 (Australia)	KABA


Triax / QCODE family	New SSN	Key-system	Brand
	1520	ML+ (5+5)	MAUER
	1521	Bullit (6P)	IBFM
	747	164SN-ST-SK-SM-SR-DSN-OBS S (6P)	KALE











Unicode299/399 family and UC199	New SSN/Card	Key-system	Brand
	4481/148		HERO-HONDA
	4482/148		HERO-HONDA
	3436/2222	S6	KALE
	2342/148		HONDA


Lector / Optika	Silca Key Reader Program Upgrade 1/2014	
	<p>Update with 276 new references. The new references include transponder MH keys, TE Empty Shell keys and FH blades for the Flip keys.</p> <p>Remember to use a USB PEN to update the OPTIKA program. To download the USB-PEN use the "Advanced" function in the OPTIKA "Archives =>Machines" of the Key Reader Program (or SKP).</p>	

Silca Transponder Program	Silca Transponder Program and RW Software Upgrade
	<p>Silca Transponder Program has been updated with 319 new vehicle applications due to the Empty-Shells, MH keys and Flip keys.</p> <p>New Software Upgrade of COM-CODE device (ver 10.3) to manage a new version of Holden-Commodore keys</p> <p>New Software Upgrade of RW devices (ver 3.14.074) : on RW4 devices the Dutch language has been added</p> <p>Update the software on : RW4, RW4 PLUS, FASTCOPY, FASTCOPY PLUS and COM-CODE devices.</p>

August 2014 (for SKP Web subscribers) 1_2014 - SILCA KEY PROGRAMS v. 20.2.5.xx

Triax / QCODE family	Modified SSN	Key-system	Brand
 Bug fixed	Modified data cards according to manufacturer specifications 617 1417-1418-1419-1420	WSM (5+5+6) BRAVUS 1000, 2000, 3000, 4000	CES ABUS


Triax / QCODE family	New SSN	Key-system	Brand
	 1498	AP3 PP solo attive	CISA
	 1504	R9 Country cantiere	ISEO
	 1505	R9 Country padronale	ISEO
	 1506	IXSATS (Prof.169-170-171-172) (Precoded)	DOM
	 1507	IXSATS (Prof. 169)	DOM
	 1508	IXSATS (Prof. 170)	DOM
	 1509	IXSATS (Prof. 171)	DOM
	 1510	IXSATS (Prof. 172)	DOM
	 1511	UDM (4P)	CES

Unocode299/399 family and UC199	New SSN/card	Key-system	Brand
	4462/666	Profile G11	GUARD
	4463/666	Profile G11	GUARD
	4464/666	Profile G11	GUARD
	4465/666	Profile G12	GUARD
	4466/666	Profile G12	GUARD
	4467/666	Profile G12	GUARD
	4468/666	Profile G13	GUARD
	4469/666	Profile G13	GUARD
	4470/666	Profile G13	GUARD
	4471/666	Profile G13	GUARD
	4472/666	Profile G14	GUARD
	4473/666	Profile G14	GUARD
	4474/666	Profile G14	GUARD
	4475/666	Profile G17	GUARD
	4476/666	Profile G17	GUARD
	44770/666	Profile G17	GUARD
	4478/666	Profile G17	GUARD
	4479/666	Profile G17	GUARD
	4480/666	Profile EPS/P EP83	GUARD
	3436/2222	S6	KALE
4460/3785	Depth 1-2-3-4-5	MIWA	
4461/410		SCHLAGE	

June 2014



(for SKP Web subscribers)

1_2014 - **SILCA KEY PROGRAMS v. 20.2.1.xx**

Triax / QCODE family	Modified SSN	Key-system	Brand
 Bug fixed	Corrected a problem related to the cutting algorithm		
	1411	Trelock (4T-4W)	TRELOCK



Triax / QCODE family	New SSN	Key-system	Brand
----------------------	---------	------------	-------

	1494	IX Saturn (Prof. 168)	DOM
	 1495	WSM NEW (5+5+6)	CES
	1496	C6 (5+5)	LINCE
	1497	Toyota (2T-4W)	TOKAY RICA
	1499	D10 D15 (6+7)	ABUS

Unocode299/399 family and UC199	New SSN/card	Key-system	Brand
	4454/3768		CHEVROLET-DAEWOO
	4453/3763	GR 2.55	HUGO
	 4457/3764	Starry	STAHLEX
	4455/3610	NW52	ABUS
	4458/3610	NW52	ABUS
	4456/3611	NW72	ABUS
	4459/3766		DIN-BOX



May 2014 (for All SKP subscribers)

1_2014 - SILCA KEY PROGRAMS v. 20.2.x.xx


Silca Key Programs UPGRADE 1/2014		
	For any info regarding the 1/2014 SKP Upgrade, please, read the NEWS document in the SILCA KEY PROGRAMS.	


December 2013 (for All SKP subscribers)

3_2013 - SILCA KEY PROGRAMS v. 20.1.x.xx


Silca Key Programs UPGRADE 3/2013		
	For any info regarding the 3/2013 SKP Upgrade, please, read the NEWS document in the SILCA KEY PROGRAMS.	


October 2013 (for SKP Web subscribers) 2_2013 - **SILCA KEY PROGRAMS v. 20.0.3.xx**

Silca Transponder Program	RW Software update
 Bug fixed	<ul style="list-style-type: none"> - A minor issue was solved for RW SW devices with version 3.10.068. The Generation of a Texas®-Crypto transponder on a GTI transponder has been corrected. <p>We suggest to upgrade the internal SW of RW4, RW4 PLUS, FASTCOPY, FASTCOPY PLUS devices.</p>

Viper machine	Modified SSN/card	Key-system	Brand
 Bug fixed	Corrected a problem related to code search after decoding, operating in stand alone		
	855/950	Lexus_TOY48P (4T-5W)	TOYOTA LEXUS
	- Corrected a problem related to duplicating the key with read measurements (EXACT COPY) after decoding.		

October 2013 (for SKP Web subscribers) 2_2013 - **SILCA KEY PROGRAMS v. 20.0.1.xx**

Silca Transponder Program	RW Software update
 Bug fixed	<ul style="list-style-type: none"> - A minor issue was solved for RW SW devices with version 3.09.066. <p>We suggest to upgrade the internal SW of RW4, RW4 PLUS, FASTCOPY, FASTCOPY PLUS devices but it's not required.</p>

Unocode299/399 family and uc199	Modified SSN/card	Key-system	Brand
 Bug fixed	Corrected a problem related to code in list		
	2299/345	TWIN/V-10 COMBI	Assa
	Added the new model YAMAHA MAJESTY 250 (Year 2000)		
	2083/289		YAMAHA

Unocode299/399 family	New SSN/card	Key-system	Brand
	4440/3729	Only original key (stop 3)	NISSAN

September 2013 (for SKP Web subscribers) 2_2013 - **SILCA KEY PROGRAMS v. 20.0.0.xx**

Silca Transponder Program	New function																																							
 	<p>a) Copying transponders onto new Silca GTI multi-function transponders With this version, RW devices can copy the following transponders:</p> <ul style="list-style-type: none"> • Second generation Philips Crypto ID46 • Texas Crypto ID60, 61, 62, ... 69, 70, 6A, 6F • Texas fixed code ID4C <p>onto the new Silca GTI** multi-function transponder. (**) See the updated list of models for which keys can be copied (Silca vehicle guide and Silca Transponder Program).</p> <p>b) Generating codes on GTI transponders (Pre-setting) With this RW version used with the "TRP Setting Program" and "Silca Transponder Program", the transponder codes listed below can be generated on the new Silca GTI multi-function transponder; the resulting GTI transponders must be programmed*** on vehicles by means of a diagnostics device or manual procedure</p> <p style="text-align: center;">Texas Crypto Transponders:</p> <table border="1" style="width: 100%;"> <thead> <tr> <th>Silca TRP ID</th> <th>Silca TRP</th> <th>Main Use</th> </tr> </thead> <tbody> <tr> <td style="text-align: center;">60</td> <td style="text-align: center;">T7- T13 - T16</td> <td style="text-align: center;">Ford - Nissan- Kia, Hyundai, others...</td> </tr> <tr> <td style="text-align: center;">61</td> <td style="text-align: center;">T19</td> <td style="text-align: center;">Mitsubishi</td> </tr> <tr> <td style="text-align: center;">62</td> <td style="text-align: center;">T21</td> <td style="text-align: center;">Mitsubishi - Subaru</td> </tr> <tr> <td style="text-align: center;">63</td> <td style="text-align: center;">T17</td> <td style="text-align: center;">Ford - Mazda</td> </tr> <tr> <td style="text-align: center;">64</td> <td style="text-align: center;">T8</td> <td style="text-align: center;">Chrysler - Renault</td> </tr> <tr> <td style="text-align: center;">65</td> <td style="text-align: center;">T18</td> <td style="text-align: center;">Suzuki</td> </tr> <tr> <td style="text-align: center;">66</td> <td style="text-align: center;">--</td> <td style="text-align: center;">Suzuki</td> </tr> <tr> <td style="text-align: center;">67</td> <td style="text-align: center;">T31</td> <td style="text-align: center;">Toyota</td> </tr> <tr> <td style="text-align: center;">69</td> <td style="text-align: center;">T22</td> <td style="text-align: center;">Yamaha Cycles</td> </tr> <tr> <td style="text-align: center;">70</td> <td style="text-align: center;">--</td> <td style="text-align: center;">Toyota EU</td> </tr> <tr> <td style="text-align: center;">71</td> <td style="text-align: center;">--</td> <td style="text-align: center;">Suzuki Cycles</td> </tr> <tr> <td style="text-align: center;">72</td> <td style="text-align: center;">--</td> <td style="text-align: center;">Kawasaki Cycles</td> </tr> </tbody> </table>	Silca TRP ID	Silca TRP	Main Use	60	T7- T13 - T16	Ford - Nissan- Kia, Hyundai, others...	61	T19	Mitsubishi	62	T21	Mitsubishi - Subaru	63	T17	Ford - Mazda	64	T8	Chrysler - Renault	65	T18	Suzuki	66	--	Suzuki	67	T31	Toyota	69	T22	Yamaha Cycles	70	--	Toyota EU	71	--	Suzuki Cycles	72	--	Kawasaki Cycles
Silca TRP ID	Silca TRP	Main Use																																						
60	T7- T13 - T16	Ford - Nissan- Kia, Hyundai, others...																																						
61	T19	Mitsubishi																																						
62	T21	Mitsubishi - Subaru																																						
63	T17	Ford - Mazda																																						
64	T8	Chrysler - Renault																																						
65	T18	Suzuki																																						
66	--	Suzuki																																						
67	T31	Toyota																																						
69	T22	Yamaha Cycles																																						
70	--	Toyota EU																																						
71	--	Suzuki Cycles																																						
72	--	Kawasaki Cycles																																						



Fixed code Texas Transponder:

Silca TRP ID	Silca TRP	Main Use
4C	T3 - T4	Ford, Toyota, Kia, Hyundai, Suzuki, others ...

Philips Crypto2 Transponders:

Silca TRP ID	Silca TRP	Main Use
46	T14	Peugeot, Citroen, Kia, Hyundai, Honda, others ...
46	T32	Chrysler – Renault Dacia
46	--	Mitsubishi CDP
46	--	Mitsubishi Colt
46	--	GM USA Circle +

(***) See the Silca vehicle guide and Silca Transponder Program for a list of vehicle models whose codes can be generated on a GTI transponder.

c) New Texas Crypto transponder ID

- ID (71) Texas Crypto used on Suzuki motor bikes
- ID (72) Texas Crypto used on Kawasaki motor bikes

d) New Texas Crypto 80 BITS transponder ID

- ID (6E-80) Texas Crypto 80 BITS (DST80)
- ID (6E-F4) Texas Crypto 80 BITS (DST40 Fast Auth)
- ID (6E-F8) Texas Crypto 80 BITS (DST80 Fast Auth)
- ID (6E-MA) Texas Crypto 80 BITS (DST+ Mutual Authentication)




To use these new functions with the following devices:

- RW4 + P-Box
- Fast Copy + P-Box
- RW4 PLUS
- Fast Copy PLUS


you need to update the on-board software of all the devices listed above (including P-Box). The "RW" software updates can also be downloaded from the internet through Silca Remote Service.






Triax / QCODE family	Modified SSN	Key-system	Brand
	Corrected the measurement on first step of axis 2 and 3		




 Bug fixed	1409	5000 PS (6+4+5)	AGB
	1440	5000 U-TECH PS (6+4+5)	AGB
Unocode299/399 family	New SSN/card	Key-system	Brand
	4433/3615	Merkur 401 Indirect Code Head-> Tip	RUKO
	4434/3465	Merkur 401 Indirect Code Tip -> Head	RUKO
UC199 machine	New SSN/card	Key-system	Brand
	3749/3667		HYUNDAI
	3750/3667		KIA
	3946/3667		KIA
	3696/3667		HYUNDAI/KIA


September 2013 (for SKP Web subscribers) 2_2013 - SILCA KEY PROGRAMS v. 19.4.1.xx

Triax / QCODE family	Modified SSN	Key-system	Brand
 Bug fixed	Corrected a problem related to the cutting algorithm		
	1264	Mauer NW4 (4T-4W)	TRELOCK
	Renamed depths according to manufacturer specifications		
	799	WKM3-WKM4 (6P)	GERDA
	Added depth 0 to all axis		
	1158	4000S Omega	KESO
	Renamed the system according to manufacturer specifications		
	1444	SPK (prof.161)	BASI

Triax / QCODE family	New SSN	Key-system	Brand
	1458	CX6a (6P)	BASI
	1459	WS42	BKS
	1460	OC4 (6P)	OMEC
	 1461	T250 (6+5P)	TITAN
	 1461	T250 (2T-5W)	TITAN
	1463	Prefer (6P)	PREFER
	1464	DEC260	DORMA-ISEO
	1465	DEC261	DORMA-ISEO



Unocode299/399 family and UC199	New SSN/card	Key-system	Brand
	4428/1401	Dec 150	DORMA
	4429/2668	Dec 160	DORMA

	4432/3708	E90	ABUS
	 4431/3707	Plura	DOM
	 3925/2817	Sigma	DOM
	4430/3706	PX-PXP	GEGE
	4436/3719	HDI+/VIP+	VACHETTE
	4435/3718		PREFER
	4437/2609		EURO LOCKS

UC199 machine	New function
	Database version now available on-board


July 2013 (for All SKP subscribers)


2_2013 - SILCA KEY PROGRAMS v. 19.4.x.xx


Silca Key Programs UPGRADE 2/2013		
	For any info regarding the 2/2013 SKP Upgrade, please, read the NEWS document in the SILCA KEY PROGRAMS.	


June 2013 (for SKP Web subscribers)

1_2013 - SILCA KEY PROGRAMS v. 19.3.7.xx


Silca Key Programs	New function
	<ul style="list-style-type: none"> - In SSI is now possible to import a .DAT or XML KESO file with a maximum of 10000 rows - When updating via WEB, it is now possible to view the News document before downloading the Silca Key Programs


Silca Transponder Program	New function
	<ul style="list-style-type: none"> - Update with 276 new automotive models - The STP database has been updated with all ILCO keys and all automotive transponder models available in ILCO 2013 Automotive catalogue

Triax / QCODE family	Modified SSN	Key-system	Brand
 Bug fixed	Corrected a problem related to the cutting algorithm		
	1411	Trelock (4T-4W)	TRELOCK

Triax / QCODE family	New SSN	Key-system	Brand
	1417-1418-1419-1420	BRAVUS series 1000, 2000, 3000, 4000	ABUS
	1427	HONDA car models Brio e Amage	HONDA
	1426	SE ANS (ANS-2 ANS-3 ANS-4)	GEGE
	777	SE (AP1000-AP2000-AP3000-AP4000-APN-CNS-2 CNS-3-HKS-2-pExtra-pExtra 3-pExtra (Swe)	GEGE



Unocode299/399 family	New SSN/card	Key-system	Brand
	4418/3659	EVEREST 29	SCHLAGE
	2721/802	Briton 7500	SCHLAGE


UC199 machine	New function
	- Two new adapters are available : for FO21P (D708704ZB) and for SIMPLEX (D708040ZB)


Viper machine	New SSN	Key-system	Brand
	2127	HONDA models Brio and Amage	HONDA

May 2013 (for SKP Web subscribers)


1_2013 - **SILCA KEY PROGRAMS v. 19.3.6.xx**


Silca Key Programs	New function
	New icon  allows for a direct connection to www.silca.biz web site in order to obtain more info on the Silca Key Program .



Triax / QCODE family	Modified SSN	Key-system	Brand
 Bug fixed	Corrected a problem related to the code list.		
	1304	Kia (2T-8W)	KIA
	Corrected the depth of cut.		
	1304	Kia (2T-8W)	KIA
	1305	Hyundai (2T-8W)	HYUNDAI

Triax / QCODE family	New SSN	Key-system	Brand
	1412	Subaru Forester (4T-5W)	TOKAJ RIKA



	1414	GMC (2T-10W)	HUF
--	------	--------------	-----

Unocode299/399 family	New SSN	Key-system	Brand
	4287	(models BRZ,IMPREZA,TREZIA,FORESTER,XV)	SUBARU
	4417	RH4/5 41/50mm	ABUS
	4416	Depth 0-1-2-3-4 (MIW13)	MIWA


UC199 machine	New function
	New Swedish language on the machine.


Viper machine	New SSN	Key-system	Brand
	2112	Subaru Forester (4T-5W))	TOKAJ RIKA
	2113	GMC (2T-10W)	HUF
	A new function has been added to the machine related to Card / SN search based on Edge / High security key (snake type key).		

March 2013 (for All SKP subscribers) **1_2013 - SILCA KEY PROGRAMS v. 19.3.x.xx**

Silca Key Programs UPGRADE 1/2013		
	For any info regarding the 1/2013 SKP Upgrade, please, read the NEWS document in the SILCA KEY PROGRAMS.	

February 2013 (for SKP Web subscribers) **3_2012 - SILCA KEY PROGRAMS v. 19.2.0.xx**

Unocode 299/399/EVO	New SSN	Key-system	Brand
	4383	P600 Tip -> Head	ASSA

Triax and QCODE	Modified SSN	Key-system	Brand
	Corrected a problem related to leaving axis 1 completely blank		
	55	Kalotten VS630	WINKHAUS
	115	Kalotten VS6	WINKHAUS
	257	Kalotten VS400	WINKHAUS

Viper



Bug fixed

Corrected a problem related to C clamp recognition

Silca KEY Programs



Silca Transponder Program Upgrade



Software upgrade version 3.04.062 for RW devices (RW4*, RW4 PLUS, FASTCOPY*, FASTCOPY PLUS)

From this version RW devices are able to make a copy of original keys for all vehicles that use Philips® Crypto2 transponders ID46 turning on the vehicle instrument panel just once (acquiring data by means of SNOOP).

This function is useful if data cannot be acquired when the vehicle instrument panel is turned on for the second time (the second LED on SNOOP does not illuminate).

The table below shows the models for which a second data acquisition session was not possible before (the second LED on SNOOP does not illuminate) and which can now be copied with this new method:

Make	Model	Year from	Year to	SILCA REF
CRHYSLER	PT CRUISER	2006	2010	CY24MH
DODGE	CARAVAN	2004	2007	CY24MH
HONDA	ACCORD	2011		HON60MH
HONDA	PILOT	2011		HON60MH

(*) To use the new copying method please update your RW4 or FASTCOPY device plus the P-BOX device.

Consult the updated manuals for further information.


Starting with this version, code generation for the Temic® transponder (ID11) has been improved: with the old version invalid codes could be generated.

Silca Software Interface



Silca Software interface has now 2 new functions

- Pressing the button “Select range” is possible to select a range of items to be sent to the machines
- The new column named “TX” shows the status of transmission to the machine



Unocode 299/399 family

New SSN


Key-system

Brand



SKP PRO WEB Update



	4375	CES PSM (5,6,7 pin)	CES
	4378	Abus NW52	ABUS
	4379	Abus NW72	ABUS

December 2012 (for All SKP subscribers) 3_2012 - SILCA KEY PROGRAMS v. 19.1.x.xx
Silca Key Programs UPGRADE 3/2012

IMPORTANT



Silca Key programs is now **Windows® 8 (32 or 64 bit)** compliant.

To use the Silca Help note, it's required to install a Microsoft software patch available from <http://www.microsoft.com/en-us/download/details.aspx?id=35449> or ask your local

For any info regarding the 3/2012 SKP Upgrade, please, read the NEWS document in the SILCA KEY PROGRAMS






November 2012 (for SKP Web subscribers) 2_2012 - **SILCA KEY PROGRAMS v. 18.8.3.xx**


<p>Silca KEY Programs</p> 	<p>SKP manages a new automatic compact key cutting machine for flat keys named UC199. Most of flat key cards can be cut by this machine with high precision.</p>		
<p>Unocode 299/399 family</p>	<p>New SSN</p>	<p>Key-system</p>	<p>Brand</p>
	<p>4354 4355 4356 4357 4358 4359 4360 2171</p>	<p>d12 SERIE 1200 (Prof. B21-01) d12 SERIE 1200 (Prof. B22-02) d12 SERIE 1200 (Prof. B23-03) d12 SERIE 1200 (Prof. B24-04) d12 SERIE 1200 (Prof. B25-05) d12 SERIE 1200 (Prof. B26-06) d12 SERIE 1200 (Prof. B27-07) PZ 88</p>	<p>ASSA ASSA ASSA ASSA ASSA ASSA ASSA BKS</p>


October 2012 (for SKP Web subscribers)


2_2012 - **SILCA KEY PROGRAMS v. 18.8.3.xx**


<p>Silca KEY Programs</p> <p style="text-align: center;"></p>	<p>-From SSI now is possible to create a indirect code-list selecting the desired SSI column. This function could be useful to locksmiths that manage XML KESO files.</p> <div style="text-align: center;">  </div>
---	---

Triax and QCODE family	Modified SSN	Key-system	Brand
	1323	TEC RPS/RPE	WINKHAUS
	1160	T200	TITAN
	351	Mitsubishi HU56RP (2T-8W)	HUF
	486	Volvo HU56R (2T-8W)	HUF
	936	K1 (6P)	SECUREMME
	802	K2 (5+5P)	SECUREMME

	New SSN	Key-system	Brand
	1356	Lexus (2T-4W)	TOKAJ RICA
	1357	Ford (2T-7W)	HUF
	1359	Astral Tekno Special Profiles	CISA
	1361	Serial XP Special Profiles	BRICARD
	1358	Tostem (4T-7W)	TOSTEM
	1363	KX3-PMK	KAKEN
	1364	KX3-BH	KAKEN

Unocode 299/399 family	New SSN	Key-system	Brand
	4315	PRO 300 – 30/35	TOKOZ

Viper machine	Modified SSN	Key-system	Brand
	351	Mitsubishi HU56RP (2T-8W)	HUF
	486	Volvo HU56R (2T-8W)	HUF

	New SSN	Key-system	Brand
	2042	Lexus (2T-4W)	LEXUS
	2043	Huf-Mahindra (2T-10W)	MAHINDRA
	2044	Man (2T-8W)	MAN
	2045	Ford (2T-7W)	FORD



SKP PRO WEB Update



July 2012 (for All SKP subscribers)

2_2012 - **SILCA KEY PROGRAMS v. 18.7.x.xx**

Silca Key Programs UPGRADE 2/2012

IMPORTANT

Due to the need to upgrade Silca Key Programs, from the SKP 2/2012 Update, Windows 2000 Operating System will no longer be supported.




On request, Silca will provide the relative DVD free to web subscribers who have to install the update on a new PC

For any info regarding the 2/2012 SKP Upgrade, please, read the NEWS document in the SILCA KEY PROGRAMS



May 2012 (for SKP Web subscribers)

1_2012 - **SILCA KEY PROGRAMS v. 18.5.0.xx**

 Silca Transponder Program Upgrade 	Identification of TEXAS/CRYPTO keys with Mutual Authentication (ID=6E) <p>From this version (3.02.061) RW devices can detect keys using Texas Crypto Transponder with Mutual Authentication (6E) that cannot be duplicated.</p> <p>Texas Crypto 6E is used on the most recent car models of :</p> <ul style="list-style-type: none"> - FORD (with Texas 80 bit transponder) - TOYOTA (with "G system" transponder) - KIA, HYUNDAI, SUBARU (most of them with Texas 80 bit transponder) <p>The Silca Transponder Program has been updated with 145 applications including the new MH key and other 25 new car models.</p> <p>68 MH key references are now available.</p> <p>Remember to upgrade the internal SW of RW4, RW4 PLUS, FASTCOPY, FASTCOPY PLUS devices.</p>		
	Unocode 299/399 family	New SSN	Key-system
	4286	Cylinders	ANKER
	4287	For SUBARU Models: Trezia 2011, XV 2012, BRZ 2012	SUBARU

March 2012 (for All SKP subscribers)

1_2012 - **SILCA KEY PROGRAMS v. 18.4.x.xx**

Silca Key Programs UPGRADE 1/2012

For any info regarding the 1/2012 SKP Upgrade, please, read the NEWS document in the SILCA KEY PROGRAMS

