



FUTURA – FUTURA PRO

NEWS WEB



Software version **Futura/Futura PRO 3.37.0 - DB 10.03** - Silca APP version 2.7

Please refer to the machine manual for the operations to follow.

The updated software operator's guide for FUTURA and FUTURA PRO is available on the Silca website (www.silca.biz) within the FUTURA PRO section

JUNE 2022

1_2022 FUTURA/FUTURA PRO V.3.37.0

NUOVI SISTEMI

| LOCK MANUFACTURER | LOCK SYSTEM | PROFILE | SERIES | SN | DATA CARD | CLAMP |
|-------------------|----------------------------|----------|--|------|-----------|-------------|
| ABUS | Oval Cyl SWE | SW..... | SW000001-SW130000 | 9929 | 355 | 01V |
| AGB | AGB GENIO | | 0123456789ABC DEFGH IJKLMNOPQRST UVWXYZ | 2341 | 5220 | 01R-01J-02J |
| ALPHA | Aston Martin AM800 (2T-4W) | | 1-2000 | 2348 | 5248 | 01R-139-02J |
| ALPHA | Renault BJA-HJB (2T-7W) | | 1-2000 | 2349 | 5271 | 01R-139-02J |
| ASSA | SIRIO KT161 | | 000011-375302 | 2350 | 1851 | 01R-01J-02J |
| BKS | BKS WS50 (Profile RC) | - | - | 2342 | 5222 | 01R-140-38J |
| FAB | Aston Martin AM500 (2T-4W) | | 1-2224 | 2347 | 5229 | 01R-139-02J |
| GERDA | GERDA EXXO (5+5) (2T-5W) | - | - | 2337 | 5219 | 01R-90J-02J |
| ISEO | Iseo R500 SPI | TEC..... | 000001-162096 | 2338 | 1597 | 01R-11J-02J |
| ISEO | Iseo R500 SPI Cantiere | TGA..... | 000001-026424 | 2339 | 1597 | 01R-11J-02J |
| ISEO | Iseo R500 SPI Padronale | TGA..... | 100001-126424 | 2340 | 1597 | 01R-11J-02J |
| LOB | DRAGON-LOBIX (6P) | | 0123456789 | 9931 | 5223 | 01V |
| MAZDA | - | | 1234 | 9932 | 5276 | 01V |
| MILLERS | Millers (7P) | | 1234567 | 9930 | 5221 | 01V |
| MOTTURA | 3DKey | - | - | 2335 | 5218 | 08R |


MAY 2022

1_2022 FUTURA/FUTURA PRO V.3.36.0



- New function COPY by ORIGINAL for FUTURA AUTO model: this function lets the user to copy a car key by original using a mechanical tracer to read the cuts.

This process works well for flat car keys only.



Attention: please, to avoid breaking the mechanical tracer, do not use it to read plastic or aluminum keys



- Fixed a bug in the EVVA 4KS card



FUTURA – FUTURA PRO NEWS WEB



APRIL 2022



1_2022 FUTURA/FUTURA PRO V.3.35.1



- Fixed a bug in the Engraving editor

APRIL 2022

1_2022 FUTURA/FUTURA PRO V.3.35.0

| | |
|---|---|
|  | <ul style="list-style-type: none"> - FUTURA AUTO: now is possible to modify the keyblank dimension before copying the key |
|  | <ul style="list-style-type: none"> - Solved the issue for registering the FUTURA machine in MYKEYSPRO using the Futura Android App of the tablet. - In the SSI queue, loading an XML KESO MKS, the name of the key will be shown. - Small adjustments have been done cutting ABUS BRAVUS PRO (all variants) key system according to ABUS notice. |

NEW SYSTEMS

| | LOCK MANUFACTURER | LOCK SYSTEM | PROFILE | SERIES | SN | DATA CARD | CLAMP |
|--|---|----------------------------|----------|---------------|------|-----------|-------------|
|  | ASSA ABLOY | ASS196R (5+5+5) | - | - | 2313 | 5172 | 01R-11J-02J |
| | ELZETT | Elzett 758 | | 012345678 | 9926 | 5215 | 01V |
| | EURO LOCKS | Euro Locks U new (2T - 5W) | - | - | 2329 | 5213 | 01R-01J-02J |
| | ISEO  | Iseo RME Factory | NAC..... | 000001-017163 | 2330 | 1597 | 01R-11J-02J |
| | ISEO  | Iseo RME KS1 | NKS..... | 000001-017163 | 2331 | 1597 | 01R-11J-02J |
| | ISEO  | Iseo RME KS2 | NDA..... | 000001-017163 | 2332 | 1597 | 01R-11J-02J |
| | ISEO  | Iseo R6 SPI | ASP..... | 000001-004044 | 2333 | 869 | 01R-01J-02J |
| | ISEO  | Iseo R500 | TEB..... | 000001-056616 | 2334 | 1597 | 01R-11J-02J |
| | KIA | Kia (2T-- 8W) | KB.... | 0001-3000 | 2324 | 4129 | 01R-01J-02J |
| | KIA | Kia (2T-- 8W) | KC.... | 0001-2900 | 2325 | 4129 | 01R-01J-02J |
| | KIA | Hyundai (2T-- 8W) | HD.... | 0001-2500 | 2326 | 4129 | 01R-01J-02J |
| | KIA | Hyundai (2T-- 8W) | HG.... | 0001-3000 | 2327 | 4129 | 01R-01J-02J |
| | KIA | Hyundai (2T-- 8W) | X.... | 0001-3000 | 2328 | 4129 | 01R-01J-02J |
| | MAUER  | CY100 (6P) | | 000016-375006 | 2336 | 1851 | 01R-11J-02J |



FUTURA – FUTURA PRO NEWS WEB



| | | | | | | | |
|--|-------|---|--------|-----------|------|------|-----|
| | MINDA | - | | 5001-7999 | 9924 | 3866 | 01V |
| | MINDA | - | | 5001-5999 | 9925 | 3866 | 01V |
| | MINDA | - | A0... | 001-700 | 9927 | 5216 | 01V |
| | MINDA | - | R0.... | 1001-2000 | 9928 | 5217 | 01V |



FUTURA – FUTURA PRO NEWS WEB



MARCH 2022

1_2022 FUTURA/FUTURA PRO V.3.34.2



- FUTURA EDGE PLUS: jaw calibration routine has been improved.
- Optical reader: the calibration parameter C2 is now visible

FEBRUARY 2022

1_2022 FUTURA/FUTURA PRO V.3.34.1



- Only for **FUTURA** model
A bug in the setting of cutting speed of flat keys has been fixed.



FUTURA – FUTURA PRO

NEWS WEB



JANUARY 2022

1_2022 FUTURA/FUTURA PRO V.3.34.0

NEW SYSTEMS

| | LOCK MANUFACTURER | LOCK SYSTEM | PROFILE | SERIES | SN | DATA CARD | CLAMP |
|------|-------------------|-------------------------------|-----------|-------------------------|------|-----------|-------------|
| | ASSA ABLOY | ASSA ABLOY Gemma | | 033330-199974 | 9894 | 5146 | 01V |
| | BKS | BKS Serie 36 (6P) | | 0123456789AB | 9922 | 5004 | 01V |
| | BORG LOCKS | Borg locks 1700-YS (2T-4W) | - | - | 2312 | 5165 | 01R-01J-02J |
| | EUROSECURE | Euro Secure ES n. 3 (6P) | | 123456789 | 9918 | 5167 | 01V |
| | EVVA | AKURA 44 Distributors (6+5+5) | - | - | 2314 | 5174 | 01R-138-87J |
| | EVVA | AKURA 44 Individual (6P) | - | - | 2311 | 5166 | 01R-138-87J |
| | FAB | FAB R104 | | 033330-199974 | 9895 | 5146 | 01V |
| | FAB | FAB R5 | | L00002-LA6334 | 9890 | 5145 | 01V |
| | FAB NG | FAB 2 Profi ** (5 pins) | | 0123456789ABC DEFGHI | 9910 | 5068 | 01V |
| | FAB NG | FAB 3 Profi *** (6 pins) | | 0123456789ABC DEFGHI | 9912 | 5161 | 01V |
| | FAB NG | FAB 3*** (5 pins) | | 0123456789ABC DEFGHI | 9911 | 5068 | 01V |
| | FAB NG | FAB 4 **** (6 pins) | | 0123456789ABC DEFGHI | 9916 | 5161 | 01V |
| | GERA | GERA 3000 PLUS SPI | XZA0..... | 00001-09746 | 9915 | 5164 | 01V |
| | GERA | GERA 3000 SPI | XYA0..... | 00001-09746 | 9917 | 5164 | 01V |
| | ISEO | CSF F9 SPI | XEA0..... | 00001-12882 | 9913 | 5163 | 01V |
| | ISEO | CSF F90 SPI | XGA0..... | 00001-12882 | 9914 | 5163 | 01V |
| | KIA | KIA (2T - 8W) | MQ.... | 0001-2500 | 2320 | 4362 | 01R-01J-02J |
| | KIA | KIA (2T-7W) | CV.... | 3001-5409 | 2319 | 5096 | 01R-01J-02J |
| | LORI | Lori 80 Keyway | | 123456789 | 9919 | 5173 | 01V |
| | LORI | Lori 90 Keyway | | 1234567 | 9920 | 5175 | 01V |
| STAR | Star S100TM (5P) | | 012345678 | 9487 | 606 | 01V | |



FUTURA – FUTURA PRO NEWS WEB



| | | | | | | | |
|--|----------|-------------------------|-------|---------------|------|------|-------------|
| | UNION | UNION R101 | | L00002-LA6334 | 9891 | 5145 | 01V |
| | VACHETTE | VACHETTE R1 | | L00002-LA6334 | 9893 | 5145 | 01V |
| | VBH | VBH Q (6P+2T-5W) | - | - | 2321 | 5181 | 01R-01J-02J |
| | YALE | YALE 500+ Upgrade R2 | | L00002-LA6334 | 9892 | 5145 | 01V |



FUTURA – FUTURA PRO NEWS WEB



DECEMBER 2021

1_2021 FUTURA/FUTURA PRO V.3.33.1



- Only for **FUTURA AUTO** model: new “Cutting speed variation” function in card copy for flat and laser keys. This function allows the user to change the speed of advancement and the amount of material to be removed at each pass based on the type of material and the thickness of the key to be encrypted.



- Fixed some minor bugs (Cards: 4357 Wilka Carat S1-S4; 2502 Abus).

DECEMBER 2021

1_2021 FUTURA/FUTURA PRO V.3.33.0



- New function to monitor cutter wear with notifications and emails .

NOVEMBER 2021

1_2021 FUTURA/FUTURA PRO V.3.32.1



- Fixed a severe bug on Tethering connection.

NOVEMBER 2021

1_2021 FUTURA/FUTURA PRO V.3.32.0



- The procedure used to connect the tablet to the machine both directly and through a Wi-Fi network has been improved.



- Problem solved regarding decoding with cutter card 3840.
- Problem solved regarding decoding ABUS Bravus 2000 key.

NEW SYSTEMS

| | LOCK MANUFACTURER | LOCK SYSTEM | PROFILE | SERIES | SN | DATA CARD | CLAMP |
|--|--|-----------------------------|----------|---------------|------|-----------|-------------|
|  | ASSA | SIRIO KT130 | | 000016-857986 | 2302 | 1851 | 01R-01J-02J |
| | ASSA | SIRIO PRO KT150 - Red Elite | | 000001-059000 | 2303 | 2242 | 01R-01J-02J |
| | CES  | CES WNP (5+5+6) | - | - | 2289 | 5123 | 01R-01J-02J |
| | EBERHARD | EBERHARD (5P) | H... | H700-H760 | 9883 | 5120 | 01V |
| | GREENTEQ | ORION 3 Star | - | - | 2307 | 5141 | 01R-01J-02J |
| | HARLEY DAVIDSON | HY10R (5P) | ... | 001-200 | 9884 | 5121 | 01V |
| | ISEO  | ISEO R50 Extra (Cantiere) | SME..... | 000001-029315 | 2304 | 1597 | 01R-11J-02J |
| | ISEO  | ISEO R50 Extra (Padronale) | SME..... | 100001-129315 | 2305 | 1597 | 01R-11J-02J |
| | JAY SWITCH | | | 123 | 9889 | 5138 | 01V |
| | LDV | LDV TOY40 (2T-4W) | - | - | 2306 | 5134 | 01R-01J-02J |
| | MCM | MCM BPSX (6+6) | - | - | 2296 | 5133 | 01R-01J-02J |



FUTURA – FUTURA PRO NEWS WEB



| | | | | | | |
|--------------------------|-----------------------------|------------|-------------|------|------|-------------|
| MCM | MCM SCX NEW (6+5) | - | - | 2295 | 5132 | 01R-01J-02J |
| Meesenburg Großhandel KG | Blaugelb Profilzylinder 6S | | 1234567 | 9885 | 5125 | 01V |
| Meesenburg Großhandel KG | Blaugelb Wendschlüssel (6P) | BG..... | 00001-30000 | 2301 | 5140 | 01R-05J-06J |
| MINDA | | | 9001-9999 | 9886 | 5135 | 01V |
| SANDHAR | | | 123 | 9887 | 5137 | 01V |
| SANDHAR | | | 123 | 9888 | 5138 | 01V |
| SIKURO | SIKURO (6P) | - | - | 2288 | 5122 | 01R-137-02J |
| STAR | STAR S100TM (4+4) | - | - | 2141 | 4704 | 01R-01J-02J |
| THIRARD | THIRARD TIGER 6 | - | - | 2293 | 5128 | 01R-01J-02J |
| THIRARD | THIRARD TRAFIC 12 | - | - | 2292 | 5127 | 01R-01J-02J |
| THIRARD | THIRARD TRANSIT 1 | - | - | 2294 | 5129 | 01R-01J-02J |
| VIRO | VIRO EUROMONOLITH (6P) | ED-K-A.... | 0001-6679 | 2300 | 1604 | 01R-01J-02J |
| VIRO | VIRO EURO-PRO (5P) | EPL-B.... | 3259-5980 | 2298 | 1604 | 01R-01J-02J |
| VIRO | VIRO EURO-PRO (6P) | EPL-A.... | 07222-13900 | 2299 | 1604 | 01R-01J-02J |
| WANGTONG | WANGTONG (6P) | ... | 001-200 | 9882 | 5119 | 01V |



FUTURA – FUTURA PRO NEWS WEB



OCTOBER 2021

1_2021 FUTURA/FUTURA PRO V.3.31.1



- Solved a minor Software problem on HONDA card 1587 and 2354



FUTURA – FUTURA PRO NEWS WEB



JULY 2021

1_2021 FUTURA/FUTURA PRO V.3.31.0

NEW SYSTEMS

| | LOCK MANUFACTURER | LOCK SYSTEM | PROFILE | SERIES | SN | DATA CARD | CLAMP |
|--|-------------------|------------------------|---------|-------------------|------|-----------|-------------|
| | ABUS | ABUS E200 | | EB000001-EB30000 | 9873 | 5100 | 01V |
| | ABUS | ABUS E300 | EC..... | EC00001-EC30000 | 2251 | 5099 | 01R-05J-06J |
| | ABUS | ABUS EC880 | | NH100001-NH131841 | 2280 | 5102 | 01R-01J-02J |
| | AMIG | AMIG 20000 (6P+4W) | | V0100001-V2059460 | 2219 | 4945 | 01R-01J-02J |
| | AMIG | AMIG 10000 (6P) | | B0000001-S0012620 | 2217 | 4947 | 01R-01J-02J |
| | AMIG | AMIG 10000E (6P) | | P0000001-Z0012620 | 2218 | 4948 | 01R-01J-02J |
| | AMIG | AMIG 20000 (6P) | | V0100001-V2059460 | 2283 | 5111 | 01R-01J-02J |
| | AVOCET | Avocet ABS Master RH | - | - | 2282 | 5110 | 01R-01J-02J |
| | BATON | Baton UNITE SERIE 5600 | - | - | 2284 | 5112 | 01R-01J-02J |
| | GERDA | Gerda Hplus (6 pin) | - | - | 2281 | 5109 | 01R-01J-02J |
| | LINCE | LINCE C6XL | - | - | 2285 | 5113 | 01R-01J-02J |



FUTURA – FUTURA PRO NEWS WEB



JULY 2021

1_2021 FUTURA/FUTURA PRO V.3.30.2



- The MyKeys Safe function has been upgraded. Please contact your local Dealer for more information.



FUTURA – FUTURA PRO

NEWS WEB



JUNE 2021

1_2021 FUTURA/FUTURA PRO V.3.30.0

NEW SYSTEMS

| | LOCK MANUFACTURER | LOCK SYSTEM | PROFILE | SERIES | SN | DATA CARD | CLAMP |
|--|-------------------|---------------------------|---------|-----------------|------|-----------|-------------|
| | BASI | BASI V50 | | - | 9880 | 5092 | 01V |
| | BASI | BASI V55 | - | - | 2273 | 5089 | 01R-01J-02J |
| | CARRYBOY | CRY2 (2T-7W) | - | - | 2252 | 5035 | 01R-131-132 |
| | CARRYBOY | CRY2 (2T-7W) | - | - | 2279 | 5098 | 01R-131-132 |
| | CISA | ASIX P8 | P8 | XN.0352.10 | 2244 | 1414 | 01R-05J-06J |
| | CISA | ASIX P8 CA | P8 CA | XN.0358.10 | 2245 | 1414 | 01R-05J-06J |
| | CISA | ASIX P8 CE | P8 CE | XN.0362.10 | 2246 | 1414 | 01R-05J-06J |
| | DELTA | DELTA GB5 | - | - | 2253 | 5041 | 01R-01J-02J |
| | DIERRE | Dierre D-UP | | 0000001-0943516 | 2271 | 5088 | 01R-01J-02J |
| | DIERRE | Dierre D-UP | | 0000001-0235920 | 2272 | 5088 | 01R-01J-02J |
| | EUROSECURE | Euro Secure (6P) | | 123456789 | 5129 | 5093 | 01V |
| | GUARD | GUARD G100 | | 00001-99999 | 2276 | 5095 | 01R-01J-02J |
| | HUF | Huf-Mahindra (2T-9W) | - | - | 2255 | 5046 | 01R-19J-02J |
| | HYUNDAI | Hyundai Smart Key (2T-7W) | S.... | 3001-5409 | 2277 | 5096 | 01R-01J-02J |
| | IBFM | IBFM 9993 | - | - | 2278 | 5097 | 01R-01J-02J |
| | KENSTAN | Kenstan (8P) | | 1234567 | 757 | 2258 | 02R |
| | MAZDA | 7th Generation | | 12345 | 9879 | 5091 | 01V |
| | PHILLIPS | Phillips 4200 (6P) | - | - | 2275 | 5094 | 01R-01J-02J |
| | SOPRANO | Cilindro Clasico | - | - | 2274 | 5090 | 01R-01J-02J |
| | TARONI | TAR15 (5+4) NEXT | - | - | 2262 | 5083 | 01R-01J-02J |
| | TARONI | TAR15 (6P) NEXT | - | - | 2265 | 5084 | 01R-01J-02J |



FUTURA – FUTURA PRO NEWS WEB








| | | | | | | |
|--------|---------------------------|-------|---|------|------|-------------|
| TARONI | TAR15R (5+4) NEXT | - | - | 2263 | 5082 | 01R-01J-02J |
| TARONI | TAR15R (6P) NEXT | - | - | 2268 | 5085 | 01R-01J-02J |
| TARONI | TAR16 (6+5) NEXT | - | - | 2269 | 5086 | 01R-01J-02J |
| TARONI | TAR16 (6P) NEXT | - | - | 2264 | 5084 | 01R-01J-02J |
| TARONI | TAR16R (6+5) NEXT | - | - | 2270 | 5087 | 01R-01J-02J |
| TARONI | TAR16R (6P) NEXT | - | - | 2266 | 5085 | 01R-01J-02J |
| TARONI | TAR17 TAR17R (3P) NEXT | ... | - | 9876 | 5080 | 01V |
| TARONI | TAR17 TAR17R (3P) NEXT | ... | - | 9876 | 5080 | 01V |
| TARONI | TAR25 TAR25R (6P) NEXT | | - | 9877 | 5078 | 01V |
| TARONI | TAR25 TAR25R (6P) NEXT | | - | 9877 | 5078 | 01V |
| TARONI | TAR5 TAR5R (5P) NEXT | | - | 9878 | 5081 | 01V |
| TARONI | TAR5 TAR5R (5P) NEXT | | - | 9878 | 5081 | 01V |

March 2021

1_2021 FUTURA V.3.22.0 – FUTURA PRO V.3.24.0

NEW SYSTEMS

| | LOCK MANUFACTURER | LOCK SYSTEM | PROFILE | SERIES | SN | DATA CARD | CLAMP |
|---|--|---|----------|--------------------------|------|-----------|-------------|
| | ABUS | ABUS E200 | | EB000001- EB30000 | 9873 | 4684 | 01V |
| | ABUS | ABUS E300 | EC..... | EC00001- EC30000 | 2251 | 3325 | 01R-05J-06J |
| | ASSA | ASSA IKON VRS (6P) | | 1234567890ABC DEFGHIL | 9555 | 4974 | 01V-B17 |
| | CISA  | ASIX P8 | - | - | 2244 | 1414 | 01R-05J-06J |
| | CISA  | ASIX P8 CA | - | - | 2245 | 1414 | 01R-05J-06J |
| | CISA  | ASIX P8 CE | - | - | 2246 | 1414 | 01R-05J-06J |
| | ISEO  | ISEO R6 Plus (no chiave di cantiere) | AMP..... | 000001-028834 | 2228 | 869 | 01R-01J-02J |
| | ISEO  | ISEO F7 (6P) | | 000001-010751 | 9554 | 4944 | 01V |
| | KESO  | Keso K6000FP2 Syst. 10 /Var. 45 | - | - | 2230 | 4976 | 01R-01J-02J |
|  | MCM | EA (5P) | | 1234567 | 9872 | 4399 | 01V |
| | MOJA | MOJA Serie J | - | - | 2250 | 5037 | 01R-01J-02J |
| | Mul-T-Lock  | Mul-T-Lock 3DS Break Secure | | 000001-059000 | 2109 | 2242 | 01R-01J-02J |
| | WINKHAUS  | WINKHAUS ON-tra + (EGS) | - | - | 2247 | 5032 | 01R-78J-79J |
| | WINKHAUS  | WINKHAUS ON-tra + (P1) | - | - | 2248 | 5033 | 01R-78J-79J |
| | WINKHAUS  | WINKHAUS ON-tra + (P3) | - | - | 2249 | 5034 | 01R-78J-79J |
| | YALE | YALE Y2P | | C30001-C51204 | 2227 | 4970 | 01R-01J-02J |
| | YALE | YALE Y2S | | 30001-62163 | 2229 | 4973 | 01R-01J-02J |

December 2020

1_2020 FUTURA V.3.21.0 – FUTURA PRO V.3.23.0



- Solved a minor Software problem (card 477)

NEW SYSTEMS

| LOCK MANUFACTURER | LOCK SYSTEM | PROFILE | SERIES | SN | DATA CARD | CLAMP |
|---|------------------------------|---------------------|-------------------|------|-----------|-------------|
| ABUS  | Vela Pro 3000 | - | - | 2216 | 4946 | 01R-01J-02J |
| AMIG | AMIG 20000 (6P+4W) | - | - | 2219 | 4945 | 01R-01J-02J |
| AMIG | AMIG 10000 (6P) | - | - | 2217 | 4947 | 01R-01J-02J |
| AMIG | AMIG 10000E (6P) | - | - | 2218 | 4948 | 01R-01J-02J |
| CISA  | Serial Z75 | (XN003210) | 1-84006AH | 2220 | 2637 | 01R-05J-06J |
| ERA | | | 1234567 | 9861 | 4965 | 01V |
| EUROSPEC | MPX6 3 STAR | | 123456789 | 9862 | 4966 | 01V |
| FEDERAL | APE BS3 | | WA400001-WE411502 | 2223 | 4963 | 01R-01J-02J |
| GEGE  | p Extra - pExtra plus 6 pins | | 1234567890 | 9859 | 4962 | 01V |
| ISEO  | ISEO R50 A2P | SFC..... | 000001-107185 | 2214 | 1597 | 01R-11J-02J |
| ISEO  | ISEO R7 A2P | EBA..... | 000001-157864 | 2212 | 868 | 01R-01J-02J |
| MAHINDRA | | | 1234 | 9863 | 4967 | 01V |
| MIWA | MIWA PS | - | - | 2224 | 4960 | 01R-05J-02J |
| MIWA | MIWA PR | - | - | 2225 | 4961 | 01R-05J-02J |
| NEXO N05 | 6SAB (6P) | - | - | 2211 | 4936 | 01R-01J-02J |
| NEXO N05 | 6S (6P) | - | - | 2110 | 4935 | 01R-01J-02J |
| OMEC | OMEC 2020/08 | - | - | 2226 | 4968 | 01R-05J-06J |
| SILCA  | SK3 MKS | - | - | 2213 | 4941 | 01R-07J-08J |



FUTURA – FUTURA PRO NEWS WEB



| | | | | | | | |
|--|------|--------------------------------|--------|---------------|------|------|---------------|
| | SISO | SISO (2T-5W) | - | - | 2222 | 4959 | 01R-129J-130J |
| | TATA | TATA NEXON | - | - | 2221 | 4958 | 01R-19J-02J |
| | TATA | TIAGO (2T-8W) | | 3000-7559 | 2215 | 4942 | 01R-01J-02J |
| | WT | WT CAM LOCK | | 123456 | 9556 | 4952 | 01V |
| | YALE | Linus Adjustable Cylinder (6P) | P..... | P00001-P30614 | 9860 | 4964 | 01V |



FUTURA – FUTURA PRO NEWS WEB



September 2020

1_2020 FUTURA V.3.20.1 – FUTURA PRO V.3.22.1



- Solved a minor Software problem



FUTURA – FUTURA PRO

NEWS WEB



September 2020

1_2020 FUTURA V.3.20.0 – FUTURA PRO V.3.22.0

NEW SYSTEMS

| LOCK MANUFACTURER | LOCK SYSTEM | PROFILE | SERIES | SN | DATA CARD | CLAMP |
|-------------------|------------------------------------|---------|-----------------------|------|-----------|-------------|
| ABUS | ABUS X60 | FS..... | 00001-98246 | 9541 | 4776 | 01V |
| ABUS | Bravus 1500 (Shoulder stop) | - | - | 2193 | 3655 | 01R-29J-30J |
| ABUS | Bravus 1500 (Tip stop) | - | - | 2187 | 4010 | 01R-29J-30J |
| ABUS | Bravus 2500 (Shoulder stop) | - | - | 2194 | 3656 | 01R-29J-30J |
| ABUS | Bravus 2500 (Tip stop) | - | - | 2185 | 4023 | 01R-29J-30J |
| ABUS | Bravus 3500 (Shoulder stop) | - | - | 2195 | 3657 | 01R-29J-30J |
| ABUS | Bravus 3500 (Tip stop) | - | - | 2180 | 3832 | 01R-29J-30J |
| ABUS | Bravus Pro 1500 (Shoulder stop) | - | - | 2190 | 4325 | 01R-29J-30J |
| ABUS | Bravus Pro 1500 (Tip stop) | - | - | 2186 | 4322 | 01R-29J-30J |
| ABUS | Bravus Pro 2500 (Shoulder stop) | - | - | 2191 | 4327 | 01R-29J-30J |
| ABUS | Bravus Pro 2500 (Tip stop) | - | - | 2181 | 4323 | 01R-29J-30J |
| ABUS | Bravus Pro 3500 (Shoulder stop) | - | - | 2192 | 4326 | 01R-29J-30J |
| ABUS | Bravus Pro 3500 (Tip stop) | - | - | 2188 | 4321 | 01R-29J-30J |
| ABUS | Mintus | - | - | 2189 | 4023 | 01R-29J-30J |
| ABUS | X12R (6+5) | | X1R00001- X1R12952 | 2062 | 4525 | 01R-01J-02J |
| ALBA | FM | - | - | 2172 | 4777 | 01R-01J-02J |
| ASSA ABLOY | Baodean MOD. 12 | - | - | 2171 | 4775 | 01R-01J-02J |
| BRISANT | Ultion WXM (6P) | - | - | 2168 | 4757 | 01R-128-02J |
| BTV | Snake (5+5)+(2T-4W) | | AA00001- AA29688 | 2199 | 4918 | 01R-01J-02J |
| BTV | Snake (5+5)+(2T-4W) | | AB00001- AB29688 | 2200 | 4918 | 01R-01J-02J |
| BTV | Snake (5+5)+(2T-4W) | | BY00001- BY29688 | 2201 | 4918 | 01R-01J-02J |



FUTURA – FUTURA PRO NEWS WEB



| | | | | | | |
|-----------|-------------------------|---------|---------------------|------|------|-------------|
| BTV | Snake (5+5)+(2T-4W) | | CA00001- CA29688 | 2202 | 4918 | 01R-01J-02J |
| CHINA | SERRUPRIX (6P) | - | - | 2183 | 4750 | 01R-01J-02J |
| GREATWALL | Great Wall (4T-6W) | - | - | 2198 | 2354 | 01R-01J-02J |
| ISEO | Iseo F90 CSF | FA..... | 000001-196122 | 9540 | 2504 | 01V |
| LOCKMAN | MEGA CROSS (4.0) | - | - | 1163 | 3031 | 01R-124-125 |
| NEXO 05 | NEXO 05 (5 Pin) | | 123456789 | 9547 | 4917 | 01V |
| SECUREMME | EVOK50 (6+5) | - | - | 2166 | 4747 | 01R-126-127 |
| SECUREMME | EVOK75 (5+5) | - | - | 2182 | 4784 | 01R-126-127 |
| STANDERS | CS115 (6P) | - | - | 2196 | 4783 | 01R-05J-06J |
| STS | IPS (6P) | | 0123456789 | 9544 | 4782 | 01V |
| TARONI | TAR16 6 pin | - | - | 2910 | 4780 | 01R-01J-02J |
| TARONI | TAR16R 6 pin | - | - | 2908 | 4779 | 01R-01J-02J |
| TARONI | TAR27P (SERIE5) (6P) | | B001001- B024117 | 9010 | 4500 | 01V |
| TARONI | TAR27P (SERIE5) (6P) | | C001001- C024117 | 9520 | 4500 | 01V |
| TARONI | TAR27P (SERIE5) (6P) | | D001001- D024117 | 9521 | 4500 | 01V |
| TARONI | TAR27P (SERIE5) (6P) | | E001001- E024117 | 9522 | 4500 | 01V |
| TARONI | TAR27P (SERIE5) (6P) | | F001001- F024117 | 9523 | 4500 | 01V |
| TARONI | TAR27P (SERIE5) (6P) | | K001001- K024117 | 9524 | 4500 | 01V |
| XIAOHULU | NR.4 | - | - | 2184 | 4816 | 01R-01J-02J |



FUTURA – FUTURA PRO

NEWS WEB



May 2020

1_2020 FUTURA V.3.19.0 – FUTURA PRO V.3.21.0

NEW SYSTEMS

| | LOCK MANUFACTURER | LOCK SYSTEM | PROFILE | SERIES | SN | DATA CARD | CLAMP |
|--|-------------------|----------------------|---------|-------------------|------|-----------|-----------------|
| | ABUS | ABUS G5X | | GX00001A-GX30000A | 2160 | 4744 | 01R-05J-06J |
| | ABUS | ABUS D20 (6+7) | | 1-39610 | 1343 | 3433 | 01R-72J-73J |
| | ANBO | ANBO X1 (6 pin) | - | - | 2158 | 4743 | 01R-01J-02J |
| | ASHICO | ASHICO (6 pin) | - | - | 2165 | 4753 | 01R-01J-02J |
| | CARRYBOY | Carryboy (4T-6W) | - | - | 2156 | 4738 | 01R-01J-02J-A34 |
| | EVERLEO | EVERLEO (6+6) | - | - | 2162 | 4751 | 01R-01J-02J |
| | GEVY | GEVY (5+4 pin) | - | - | 2161 | 4746 | 01R-01J-02J |
| | HYUNDAI | Hyundai (2T-8W) | CK.... | 0001-2500 | 4732 | 2164 | 01R-01J-02J |
| | ISEO | F7 KD | - | - | 9526 | 4628 | 01V |
| | ISEO | F7 MK Multiprofilo | - | - | 9527 | 4626 | 01V |
| | LINKE | LINKE (6 pin) | - | - | 2163 | 4752 | 01R-01J-02J |
| | LOCKMAN | MEGA CROSS (2,9) (S) | - | - | 1162 | 3030 | 01R-124-125 |
| | PANPAN BUYANG | PANPAN BUYANG OML | - | - | 2157 | 4742 | 01R-01J-02J |
| | SECUREMME | EVOK50 (6+4) | - | - | 2148 | 4747 | 01R-126-127 |
| | SILCA | SK3 (1T) | - | - | 1594 | 3905 | 01R-07J-08J |
| | VIRO | Serie 1030 Zama | | 1234567 | 9525 | 4745 | 01V |



FUTURA – FUTURA PRO

NEWS WEB



December 2019

1_2019 FUTURA V.3.18.0 – FUTURA PRO V.3.20.0

NEW SYSTEMS

| | LOCK MANUFACTURER | LOCK SYSTEM | PROFILE | SERIES | SN | DATA CARD | CLAMP |
|--|-------------------|-------------------------------|---------|---------------------|------|-----------|-------------|
| | APECS | Apecs New Diamond (5P-4W) | - | - | 2036 | 4501 | 01R-01J-02J |
| | BYD | | | 1234567 | 9515 | 4721 | 01V |
| | BYD | | | 12345678 | 9517 | 4728 | 01V |
| | CES | CES RBM (5 pin) | - | - | 2108 | 4631 | 01R-118-119 |
| | CES | CES RHM (5 pin) | - | - | 2107 | 4627 | 01R-118-119 |
| | CES | CES RHM (6 pin) | - | - | 2103 | 4624 | 01R-118-119 |
| | CHERY | | | 1234567890 | 9486 | 4701 | 01V |
| | CHERY | | | 12345678 | 9508 | 4710 | 01V |
| | CHERY | | | 12345 | 8766 | 3323 | 01V |
| | GEELY | | | 12345678 | 9516 | 4722 | 01V |
| | GERDA | WK E1 | | 1234567890 | 9507 | 4709 | 01V |
| | GREATWALL | | | 1234567 | 9509 | 4711 | 01V |
| | HALKE | | | 012345679 | 9518 | 4426 | 01V |
| | HYUNDAI | Hyundai (2T- 8W) | S.... | 0001-2500 | 2037 | 4732 | 01R-01J-02J |
| | HYUNDAI | Hyundai (2T- 8W) | Z.... | 0001-2501 | 2149 | 4732 | 01R-01J-02J |
| | IFAM | IFAM NK1000 | | N07507-N19818 | 2155 | 4733 | 01R-01J-02J |
| | KAKEN | Kaken NEW KXR-ED4N (2T-4W-5P) | - | - | 2154 | 4731 | 01R-01J-02J |
| | LIPS | | | 123456789 | 9519 | 816 | 01V |
| | LUFENG | | | 12345678 | 9513 | 4719 | 01V |
| | M&C | M&C Move (Main pins) | | M011A0001-M106M3600 | 2143 | 4715 | 01R-95J-96J |
| | M&C | M&C Move (Side) | | M011A0001-M106M3601 | 2144 | 4716 | 01R-01J-02J |



FUTURA – FUTURA PRO NEWS WEB



| | | | | | | |
|---------|------------------|-------|-------------------------|------|------|-------------|
| M&C | M&C Move (Snake) | | M011A0001- M106M3602 | 2145 | 4718 | 01R-14J-60J |
| MAZDA | | | 12345678 | 9511 | 4714 | 01V |
| MEGA | Mega MEG2 (6P) | | 123456789 | 9506 | 4708 | 01V |
| MOTTURA | Mottura CP6 | - | - | 2147 | 4729 | 01R-01J-02J |
| SARGENT | DG1 | | 0123456 | 9104 | 3890 | 01V |
| TITAN | (K58 & T60) | | 123456789 | 8888 | 2201 | 01V |
| WULING | | | 123456 | 9510 | 4713 | 01V |
| WULING | | | 1234 | 9512 | 4717 | 01V |



FUTURA – FUTURA PRO

NEWS WEB



October 2019

1_2019 FUTURA V.3.17.0 – FUTURA PRO V.3.19.0

NEW SYSTEMS

| | LOCK MANUFACTURER | LOCK SYSTEM | PROFILE | SERIES | SN | DATA CARD | CLAMP |
|--|-------------------|--------------------------------|---------|---------------------|------|-----------|-------------|
| | ADAPTA | PRIME HS | - | - | 2140 | 4702 | 01R-01J-02J |
| | ASEC-SECURITY | VITAL (6P) | | 01234567 | 9485 | 4699 | 01V |
| | AVOCET | ABS Master | - | MG3001178-MG8999932 | 2139 | 4700 | 01R-01J-02J |
| | EURO LOCKS | Ford Ranger Truck EU24 (2T-7W) | - | - | 2138 | 4692 | 01R-01J-02J |
| | IFAM | Ifam WX1000 (6+5+5) | | 000001-108570 | 2132 | 4457 | 01R-01J-02J |
| | IFAM | HUNO (5P) | HU..... | 0001-5715 | 9484 | 4693 | 01V |
| | INN | INN PRO/BASIC Master | - | - | 2135 | 4689 | 01R-01J-02J |
| | INN | INN PRO/BASIC CT | - | - | 2136 | 4690 | 01R-01J-02J |
| | KABA | Kaba 20 KA2 (4A) | - | - | 154 | 1514 | 07R |
| | L&F - WHITCO | | 11... | 001-232 | 9488 | 4703 | 01V |
| | L&F - WHITCO | | 14... | 001-232 | 9489 | 4703 | 01V |
| | L&F - WHITCO | | 15... | 001-232 | 9490 | 4703 | 01V |
| | L&F - WHITCO | | 16... | 001-232 | 9491 | 4703 | 01V |
| | L&F - WHITCO | | 17... | 001-232 | 9492 | 4703 | 01V |
| | L&F - WHITCO | | 18... | 001-232 | 9493 | 4703 | 01V |
| | L&F - WHITCO | | 19... | 001-232 | 9494 | 4703 | 01V |
| | L&F - WHITCO | | 20... | 001-232 | 9495 | 4703 | 01V |
| | L&F - WHITCO | | 21... | 001-232 | 9496 | 4703 | 01V |
| | L&F - WHITCO | | 22... | 001-232 | 9497 | 4703 | 01V |
| | L&F - WHITCO | | 23... | 001-232 | 9498 | 4703 | 01V |
| | L&F - WHITCO | | 24... | 001-232 | 9499 | 4703 | 01V |



FUTURA – FUTURA PRO NEWS WEB



| | | | | | | |
|----------------|--|-------|-----------------------|------|------|-------------|
| L&F - WHITCO | | 25... | 001-232 | 9500 | 4703 | 01V |
| L&F - WHITCO | | 26... | 001-232 | 9501 | 4703 | 01V |
| L&F - WHITCO | | 27... | 001-232 | 9502 | 4703 | 01V |
| L&F - WHITCO | | 28... | 001-232 | 9503 | 4703 | 01V |
| MLS | MLS KT122 ELITE 2 FP 6+5P | | 0000016- 05000006 | 2131 | 2242 | 01R-01J-02J |
| MLS | MLS KT053 ELITE 1 (6P) - Red Line | | XM01ZP24- XM01NDJ8 | 2133 | 1851 | 01R-01J-02J |
| MLS | MLS KT053 ELITE 1 (6P) - Red Line | | 000016-375006 | 1144 | 1851 | 01R-01J-02J |
| MLS | MLS KT152-MLS 6P FAMILY-RED LINE FP2 | | 0000096-1199986 | 9474 | 1872 | 01V |
| MLS | MLS KT052-MLS- 6P Antibumping Final FP2 | | 0000096-1199986 | 9478 | 1872 | 01V |
| PC Cortellezzi | PC Cortellezzi SY30.SY32, SY35 - C11 NEW | - | - | 2137 | 4360 | 01R-01J-02J |


August 2019

1_2019 FUTURA V.3.16.0 – FUTURA PRO V.3.18.0



- Solved a minor Software problem (SN 121)


NEW SYSTEMS

| LOCK MANUFACTURER | LOCK SYSTEM | PROFILE | SERIES | SN | DATA CARD | CLAMP |
|---|-------------------------------|----------|-----------------------|------|-----------|-------------|
| ABUS | ABUS A93 (5P) | AC.....X | 00001-30000 | 9482 | 4684 | 01V |
| CHERY | | | 1234 | 9480 | 4676 | 01V |
| CANTOL | MEGA 990 (5+5P) | - | - | 2119 | 4675 | 01R-01J-02J |
| FORTE | ENIGMA (2T-4) | - | - | 2129 | 4686 | 01R-01J-02J |
| CHICAGO | | | 0123456789 | 9483 | 4685 | 01V |
| GUARD | Profile G17 T6 | | 00001-99999 | 9476 | 666 | 01V |
| GREAT WALL | Great Wall (2T-8W) | - | - | 2127 | 4681 | 01R-19J-02J |
| GREAT WALL | Great Wall (2T-8W) | - | - | 2130 | 4683 | 01R-01J-02J |
| IFAM | F5S | | | 8532 | 2336 | 01V |
| LUXGEN | | | 1235 | 9481 | 4679 | 01V |
| MHA | MOD 31 (6P) | | | 2120 | 4673 | 01R-01J-02J |
| MLS  | MLS KT115 Standard FP2 5P | | 000001-012990 | 9470 | 2273 | 01V |
| MLS  | MLS KT117 Standard FP2 6P | | 0000016-0756556 | 9471 | 2764 | 01V |
| MLS  | MLS KT119 MLS FP2 6P | | 0000016-1200006 | 9473 | 1872 | 01V |
| MLS  | MLS KT130 ELITE 1 FP2 6P | | 000016-857986 | 2117 | 1851 | 01R-01J-02J |
| MLS  | MLS KT138 FAMILY FP2 6P | | 0000016-1209996 | 9472 | 1872 | 01V |
| MLS  | MLS KT122 ELITE 2 FP2 6+5P | | 00000016- 05000006 | 2115 | 2242 | 01R-01J-02J |



FUTURA – FUTURA PRO NEWS WEB



| | | | | | | |
|--|------------------------------|----------|---------------|-------|------|-------------|
| NATIONAL | NATIONAL | | 0001-1378 | 9477 | 1043 | 01V |
| PAPAIZ | 143CR R68 Multiponto(9+5) | - | - | 2122 | 4678 | 01R-01J-02J |
| PREFER | Prefer IAA (5+6+5) | IAA..... | 800001-801090 | 2123 | 4682 | 01R-01J-02J |
| R.O.C. | R.O.C. CH9T-(10P) | | 7654321 | 989 | 2660 | 02R |
| STANDERS | STANDERS (6p) | - | - | 21146 | 1857 | 01R-01J-02J |
| TRAVEX | 970 XT (7P) | - | - | 2118 | 4674 | 01R-01J-02J |
| US-LOCK | | | | 9475 | 4012 | 01V |
| VOLVO | HU152S16 (2T- 10W) | - | - | 2125 | 4680 | 01R-19J-02J |
| VOLVO | HU152S16 (2T- 10W) | | 4001-9001 | 2126 | 4680 | 01R-19J-02J |
| WINKHAUS  | WINKHAUS RPE/RPS | - | - | 1323 | 3364 | 01R-25J-26J |
| YALE | Yale 1010 | | 123456789AB | 9479 | 4672 | 01V |



FUTURA – FUTURA PRO NEWS WEB



July 2019

1_2019 FUTURA V.3.15.2– FUTURA PRO V.3.17.2



- Solved a minor Software problem (Winkhaus RPE/RPS SN 1323)

June 2019

1_2019 FUTURA V.3.15.0 – FUTURA PRO V.3.17.0




- Software improvements implemented, especially for the FUTURA AUTO version



- Solved a minor Software problem

NEW SYSTEMS

| | LOCK MANUFACTURER | LOCK SYSTEM | PROFILE | SERIES | SN | DATA CARD | CLAMP |
|--|--|------------------------|---------|------------|------|-----------|-------------|
|  | BEST | System:A2 | | 1234546789 | 9019 | 4638 | 07V |
| | BEST | System:A3 | | 123456 | 9171 | 4639 | 07V |
| | BEST | System:A4 | | 12345 | 9452 | 4640 | 07V |
| | HAFELE | Hafele HW15R (2t-4W) |PL | 3010-3999 | 2113 | 3061 | 01R-16J-17J |
| | HAFELE | | | 3010-3010 | 9453 | 4642 | 01V |
| | HUWIL | Huwil HW15R (2t-4W) | - | - | 1183 | 3061 | 01R-16J-17J |
| | KABA | Peaks A2 (0.150") (6P) | | 123456789 | 9012 | 4632 | 07V |
| | KABA | Peaks A2 (0.150") (6P) | | 123456789 | 9013 | 4633 | 07V |
| | KABA | Peaks A2 (0.150") (6P) | | 123456789 | 9014 | 4633 | 07V |
| | KABA | Peaks A2 (0.140") (6P) | | 123456789 | 9015 | 4634 | 07V |
| | KABA | Peaks A4 (0.150") (6P) | | 12345 | 9016 | 4635 | 07V |
| | KABA | Peaks A4 (0.150") (7P) | | 12345 | 9017 | 4636 | 07V |
| | KABA | Peaks A4 (0.140") (6P) | | 12345 | 9018 | 4637 | 07V |
| | TARONI  | TAR27P(Serie 5) (6p) | | 123456789 | 9010 | 4500 | 01V |
| | YALE | 1000 SERIES FP2 (5P) | - | - | 2104 | 3448 | 01R-13J-02J |



FUTURA – FUTURA PRO NEWS WEB



| | | | | | | |
|------|-----------------------------------|-------|----------|------|------|-------------|
| YALE | 1000 EF 6P SHORT KEY | - | - | 2105 | 4369 | 01R-13J-02J |
| YALE | 1000 SERIES FP2 LONG KEY-B (6P) | - | - | 2106 | 3448 | 01R-13J-02J |
| YALE | 1000 SERIES SHORT KEY-A (6P) | - | - | 1998 | 4369 | 01R-13J-02J |
| YALE | 2000 Series FP2 Short Key-A (5+5) | - | - | 1346 | 3477 | 01R-01J-02J |
| YALE | Yale YA99R (6+6) | - | - | 1841 | 4222 | 01R-01J-02J |
| YALE | 500 SERIES FP2 (5P) | | 12345678 | 9011 | 3437 | 01V |



FUTURA – FUTURA PRO




NEWS WEB



April 2019

1_2019 FUTURA V. 3.14.0 – FUTURA PRO V. 3.16.0

NEW SYSTEMS

| | LOCK MANUFACTURER | LOCK SYSTEM | PROFILE | SERIES | SN | DATA CARD | CLAMP |
|---|--|---------------------------------|---------|-----------------|------|-----------|-----------------|
| | EUROSECURE | EURO X Star | - | - | 2096 | 4609 | 01R-05J-06J |
| | BAOJUN | BAOJUN (2T-10W) | - | - | 2097 | 4616 | 01R-01J-02J |
| | FORD | Ford HU198T (2T-10W) | | 0020001-0032003 | 1956 | 4320 | 01R-01J-02J+A24 |
| | Chang An | Chang An (2T-7W) | - | - | 2098 | 4618 | 01R-01J-02J |
| | SECUREMME | EVO K1 (6P) | - | - | 2100 | 4619 | 01R-01J-02J |
| | WAN JA | WAN JA (7P) | - | - | 2101 | 4620 | 01R-01J-02J |
|  | MAUER  | MLS KT155 Elite 2 E2 FP2 (6+5P) | | 000001-059000 | 2099 | 2242 | 01R-01J-02J |
| | ABUS | CeniT | | CN11214-CN99894 | 9449 | 4617 | 01V |
| | RIELDA  | RS3 | | BL21ABAADPU O- | 9356 | 3756 | 01V |
| | ABUS | Wavy line - Wavy line Pro | | KLMZYX | 3797 | 2689 | 01V |
| | CHANG AN | Chang An | | ABCDE | 9450 | 4622 | 01V |
| | CHANG AN | | | 01234567 | 9008 | 4621 | 01V |
| | MAZDA | | | 01234567 | 9451 | 4623 | 01V |
| | WILKA | W1 | | 400001-499999 | 8040 | 740 | 01V |



FUTURA – FUTURA PRO

NEWS WEB



February 2019

1_2019 FUTURA V. 3.13.0 – FUTURA PRO V. 3.15.0

NEW SYSTEMS

| | LOCK MANUFACTURER | LOCK SYSTEM | PROFILE | SERIES | SN | DATA CARD | CLAMP |
|--|-------------------|-----------------------------------|---------|--------|------|-----------|-------------|
| | WILKA | Carat S3 | - | - | 1983 | 4359 | 01R-110-111 |
| | WILKA | Carat S5 | - | - | 1984 | 4359 | 01R-110-111 |
| | DOM | Dom IX TECO (Prf. 270) | - | - | 2087 | 4566 | 01R-108-109 |
| | DOM | Dom IX TECO (Prf. 271) | - | - | 2088 | 4567 | 01R-108-109 |
| | DOM | Dom IX7TE (Prf. 278) | - | - | 2089 | 4568 | 01R-108-109 |
| | DOM | Dom IX7TE (Prf. 274) | - | - | 2090 | 4569 | 01R-108-109 |
| | DOM | Dom IX7TE (Prf. 275) | - | - | 2091 | 4570 | 01R-108-109 |
| | DOM | Dom IX7TE (Prf. 273) | - | - | 2092 | 4571 | 01R-108-109 |
| | KABA | Kaba 10 (K10) (10+10+18) | - | - | 483 | 1508 | 01R-1J-02J |
| | KABA | Kaba Gemini | - | - | 75 | 1562 | 06R |
| | KABA | Kaba Gemini T 1.0 (K54) | - | - | 90 | 1563 | 06R |
| | KABA | Kaba ExperT Cross S1.0a (K89A) | - | - | 1731 | 4131 | 05R |
| | KABA | Kaba ExperT Cross S1.0b (K89B) | - | - | 1733 | 4134 | 05R |
| | KABA | Kaba 20 KA2 (4A) | - | - | 154 | 1514 | 07R |
| | KABA | Kaba Star (5A) old | - | - | 304 | 1566 | 07R |
| | DOM | Dom IX TWIDO (Prf. 280) | - | - | 2052 | 4506 | 01R-97J-98J |
| | DOM | Dom IX TWIDO (Prf. 281) | - | - | 2053 | 4507 | 01R-97J-98J |
| | DOM | Dom IX7TW (Prf. 282) | - | - | 2054 | 4508 | 01R-97J-98J |
| | DOM | Dom IX7TW (Prf. 283) | - | - | 2055 | 4509 | 01R-97J-98J |
| | DOM | Dom IX7TW (Prf. 284) | - | - | 2056 | 4510 | 01R-97J-98J |
| | DOM | Dom IX7TW (Prf. 285) | - | - | 2057 | 4511 | 01R-97J-98J |
| | DOM | Dom IX7TW (Prf. 288) | - | - | 2094 | 4588 | 01R-97J-98J |



FUTURA – FUTURA PRO NEWS WEB



| | | | | | | |
|------------|----------------------|--------|-------------|------|------|------------|
| VAST | Vast (2T-8W) | | 0001-2648 | 2095 | 4591 | 01R-1J-02J |
| HON | | ...E | 101-225 | 9411 | 4574 | 01V |
| FCV | FCV Stiftsatz B (5P) | | 123456789 | 9412 | 4579 | 01V |
| FCV | FCV Stiftsatz B (6P) | | 123456789 | 9413 | 4579 | 01V |
| SUZUKI | | | 1001-2174 | 8762 | 3294 | 01V |
| CHRYSLER | | VN.... | 0-1999 | 9321 | 745 | 01V |
| EURO LOCKS | | | 48001-9000 | 6154 | 200 | 01V |
| HON | | ...E | 100-111 | 8980 | 1069 | 01V |
| HON | | ... | 100-111 | 8979 | 1069 | 01V |
| HON | | ... | 405-550 | 8981 | 1069 | 01V |
| HON | | ...E | 101-225 | 8983 | 1069 | 01V |
| HON | | ...H | 101-225 | 8984 | 1069 | 01V |
| HON | | ...N | 101-225 | 8985 | 1069 | 01V |
| HON | | ...R | 101-225 | 8986 | 1069 | 01V |
| HON | | E... | 101-225 | 8987 | 1069 | 01V |
| HON | | HON... | 101-225 | 8988 | 1069 | 01V |
| HON | | .. | 01-10 | 8989 | 1039 | 01V |
| HON | | ..E | 01-10 | 8990 | 1039 | 01V |
| HON | | HON.. | 01-10 | 8991 | 1039 | 01V |
| HON | | LO.. | 01-10 | 8992 | 1039 | 01V |
| CX5 | Scorpion (6P) | | 0123456789A | 8993 | 4602 | 01V |
| HON | | GG... | 101-200 | 8982 | 1069 | 01V |
| TRIMARK | | ... | 851-867 | 9414 | 138 | 01V |
| TRIMARK | | CH... | 501-550 | 9448 | 138 | 01V |



FUTURA – FUTURA PRO NEWS WEB



| | | | | | | |
|---------|--|--------|-----------|------|------|-----|
| TRIMARK | | HC... | 0-496 | 9415 | 138 | 01V |
| TRIMARK | | RH... | 001-050 | 9416 | 138 | 01V |
| TRIMARK | | RH.. | 1-50 | 9417 | 138 | 01V |
| TRIMARK | | TH.. | 1-25 | 9418 | 138 | 01V |
| TRIMARK | | TH.. | 26-50 | 9419 | 138 | 01V |
| TRIMARK | | TM... | 851-867 | 9420 | 138 | 01V |
| TRIMARK | | TR... | 051-100 | 9421 | 138 | 01V |
| TRIMARK | | TM... | 301-323 | 9422 | 466 | 01V |
| TRIMARK | | TM... | 426-448 | 9423 | 466 | 01V |
| TRIMARK | | ... | 101-150 | 9424 | 1030 | 01V |
| TRIMARK | | ... | 151-200 | 9425 | 1030 | 01V |
| TRIMARK | | ... | 201-250 | 9426 | 1030 | 01V |
| TRIMARK | | ... | 500-650 | 9428 | 1030 | 01V |
| TRIMARK | | ... | 51-100 | 9427 | 1030 | 01V |
| TRIMARK | | ... | 901-950 | 9429 | 1030 | 01V |
| TRIMARK | | TM... | 101-150 | 9431 | 1030 | 01V |
| TRIMARK | | TM... | 151-200 | 9432 | 1030 | 01V |
| TRIMARK | | TM... | 201-250 | 9433 | 1030 | 01V |
| TRIMARK | | TM... | 500-650 | 9434 | 1030 | 01V |
| TRIMARK | | TM... | 51-100 | 9430 | 1030 | 01V |
| TRIMARK | | TM... | 901-950 | 9435 | 1030 | 01V |
| TRIMARK | | TR.... | 1001-1098 | 9436 | 1030 | 01V |
| TRIMARK | | TR.... | 1200-1259 | 9437 | 1030 | 01V |
| TRIMARK | | J... | 201-240 | 9445 | 4599 | 01V |



FUTURA – FUTURA PRO NEWS WEB



| | | | | | | |
|---------|---------------------|--------|-------------|------|------|-----|
| TRIMARK | | | 1001-1240 | 9440 | 4598 | 01V |
| TRIMARK | | | 2001-2240 | 9441 | 4598 | 01V |
| TRIMARK | | | 3001-3240 | 9442 | 4598 | 01V |
| TRIMARK | | | 4001-4240 | 9443 | 4598 | 01V |
| TRIMARK | | | 5001-5240 | 9444 | 4598 | 01V |
| TRIMARK | | TA... | 1-183 | 9446 | 4600 | 01V |
| TRIMARK | | ... | 700-729 | 9438 | 4066 | 01V |
| TRIMARK | | TM... | 700-729 | 9439 | 4066 | 01V |
| TRIMARK | | | 80001-81000 | 9447 | 4601 | 01V |
| HON | | ... | 301-450 | 8994 | 1039 | 01V |
| HON | | ...E | 301-451 | 8995 | 1039 | 01V |
| HON | | ...R | 301-452 | 8999 | 1039 | 01V |
| HON | | ...T | 301-453 | 9000 | 1039 | 01V |
| HON | | ...E | 801-950 | 9001 | 1039 | 01V |
| HON | | HON... | 301-455 | 9002 | 1039 | 01V |
| HON | | T... | 301-456 | 9003 | 1039 | 01V |
| HON | | L... | 700-824 | 9004 | 1039 | 01V |
| HON | | HG... | 001-150 | 9005 | 1039 | 01V |
| Clark | Clark Security (6P) | | 0123456789 | 9007 | 4602 | 01V |



FUTURA – FUTURA PRO NEWS WEB



January 2019

1_2018 FUTURA V.3.1202 – FUTURA PRO V.3.14.0







- Problem with the Hebrew language solved.
- Problem with engraving solved.

Dicember 2018

1_2018 FUTURA V.3.11.0 – FUTURA PRO V.3.13.0

NEW SYSTEMS

| | LOCK MANUFACTURER | LOCK SYSTEM | PROFILE | SERIES | SN | DATA CARD | CLAMP |
|--|---|--------------------------------|---------|-----------------------|------|-----------|-------------|
|  | ASSA | Twin Combi (1T-5W) | - | - | 907 | 2560 | 01R-01J-02J |
| | ABUS  PFAFFENHAIN | X12R (6+5) | | X0100001- X0150000 | 2062 | 4525 | 01R-01J-02J |
| | ABUS  | D10X (6+7) | | E00002A- E30000Z | 2063 | 4540 | 01R-05J-06J |
| | BRICARD  | BRICARD DUAL XP S2 | PL | XN.0342.10 | 2084 | 4562 | 01R-05J-06J |
| | MAGNUM | Magnum Superior (3+3) | - | - | 4805 | 4575 | 01R-35J-36J |
| | MAGNUM | Magnum Superior (4+4) | - | - | 4806 | 4576 | 01R-35J-36J |
| | MAGNUM | Superior+New(2T- 3W) | - | - | 4807 | 4577 | 01R-01J-02J |
| | MAGNUM | Superior+New(2T- 4W) | - | - | 4808 | 4578 | 01R-01J-02J |
| | MULT.LOCK | Mul-T-Lock Break Secure 3DS | - | - | 2024 | 2242 | 01R-01J-02J |
| | ROYAL | Royal Enfield | | 2001-3170 | 9410 | 4560 | V100 |
| | HON | HON (5P) | | 101E-225E | 9411 | 4574 | V100 |

October 2018

1_2018 FUTURA V.3.10.0 – FUTURA PRO V.3.12.0

NEW FUNCTIONS



- **COPIES OF VEHICLE KEYS**

This function is used to copy vehicle keys with standard or laser cuts, by means of facilitated searching.

- **IMPORTING HOOK POSITION FILE**

This function is used to import a CSV file containing a list of positions for hooks associated to the Silca keys stocked by a point of sale/key-cutting centre. The file is imported from a USB PEN inserted into the key-cutting machine USB port.

Please note









For further details, download the FUTURA PRO Software Manual from the FUTURA PRO section of the Silca website (www.silca.biz).

BUG FIXED



- Solved a minor Software problem.

NEW SYSTEMS

| | LOCK MANUFACTURER | LOCK SYSTEM | PROFILE/SERIES | SERIES | SN | DATA CARD | CLAMP |
|--|--|------------------------|----------------|---------------------|------|-----------|-------------|
|  | WILKA | Carat S1 | - | - | 1980 | 4358 | 01R-68J-69J |
| | WILKA | Carat S4 | - | - | 1986 | 4358 | 01R-68J-69J |
| | KABA  | Kaba K86 - matrix plus | - | - | 2032 | 4468 | 06R |
| | KABA  | Kaba K91 - entro | - | - | 2033 | 4469 | 06R |
| | M&C  | M&C Condor Mirror | | M011A1001-M109A3169 | 2038 | 4435 | 01R-104-105 |
| | M&C  | M&C Condor Mirror | | M011B1001-M109B3169 | 2039 | 4435 | 01R-104-105 |
| | M&C  | M&C Condor Mirror | | M011C1001-M109C3169 | 2040 | 4435 | 01R-104-105 |
| | M&C  | M&C Condor Mirror | | M011D1001-M109D3169 | 2041 | 4435 | 01R-104-105 |
| | M&C  | M&C Condor Mirror | | M011E1001-M109E3169 | 2042 | 4435 | 01R-104-105 |



FUTURA – FUTURA PRO NEWS WEB



| | | | | | | |
|-----------|---|---------|---------------------------|------|------|-------------|
| M&C | M&C Condor Mirror | | M011F1001- M109F3169 | 2044 | 4435 | 01R-104-105 |
| M&C | M&C Condor Mirror | | M011G1001- M109G3169 | 2045 | 4435 | 01R-104-105 |
| M&C | M&C Condor Mirror | | M011H1001- M109H3169 | 2046 | 4435 | 01R-104-105 |
| M&C | M&C Condor Mirror | | M011K1001- M109K3169 | 2047 | 4435 | 01R-104-105 |
| M&C | M&C Condor Mirror | | M011M1001- M106M3169 | 2048 | 4435 | 01R-104-105 |
| M&C | M&C Condor Mirror (Main+snake) | - | - | 2049 | 4438 | 01R-104-105 |
| M&C | M&C Condor Mirror (Main+side) | - | - | 2050 | 4440 | 01R-104-105 |
| M&C | M&C Condor Mirror (Main pins) | - | - | 2051 | 4443 | 01R-104-105 |
| M&C | M&C Condor Mirror (Snake) | - | - | 2058 | 4444 | 01R-104-105 |
| M&C | M&C Condor Mirror (Side) | - | - | 2059 | 4445 | 01R-104-105 |
| M&C | M&C Condor Mirror (Snake+Side) | - | - | 2060 | 4512 | 01R-104-105 |
| A.P.FER | Astral Sigillo W39 | ,,,,,HG | 00001-38832 | 2064 | 1414 | 01R-05J-06J |
| A.P.FER | Astral Sigillo W39 | ,,,,,HI | 00001-38832 | 2065 | 1414 | 01R-05J-06J |
| M&T | Astral Sigillo W41 | ,,,,,HM | 00001-38832 | 2066 | 1414 | 01R-05J-06J |
| M&T | Astral Sigillo W41 | ,,,,,HP | 00001-38832 | 2067 | 1414 | 01R-05J-06J |
| HUGO | HUGO GR 5S | | 6650000001- 6650294740 | 2076 | 4548 | 01R-01J-02J |
| SECUREMME | SECUREMME K3.3 (5+5) | - | - | 2077 | 4551 | 01R-13J-02J |
| KASSEL | NF 11 (6+5) | | - | 2078 | 4552 | 01R-01J-02J |
| TILANCO | Tilanco (5+5) (2T- 3W) | - | - | 2079 | 4531 | 01R-01J-02J |
| DOM | Dom IX Twinstar (Prof. 298) | - | - | 2070 | 4542 | 01R-88J-89J |
| DOM | Dom IX Twinstar Std. Cut (Prof. 298) | - | - | 2071 | 4543 | 01R-88J-89J |
| DOM | Dom IX Twinstar Prf. Cut (Prof. 298) | - | - | 2072 | 4544 | 01R-88J-89J |
| DOM | Dom IX Twinstar (Prof. 299) | - | - | 2073 | 4545 | 01R-88J-89J |
| DOM | Dom IX Twinstar Std. Cut (Prof. 299) | - | - | 2074 | 4546 | 01R-88J-89J |



FUTURA – FUTURA PRO NEWS WEB



| | | | | | | |
|----------|--------------------------------------|-------|------------------------------|------|------|-------------|
| DOM | Dom IX Twinstar Prf. Cut (Prof. 299) | - | - | 2075 | 4547 | 01R-88J-89J |
| KABA | Kaba Gemini (k50) | - | - | 1096 | 2883 | 06R |
| YALE | Superior 1 Star 10 Pin (2T-4W) | - | - | 2080 | 4558 | 01R-01J-02J |
| YALE | Platinum 3 Star 10 Pin (2T-4W) | - | - | 2082 | 4558 | 01R-01J-02J |
| YALE | Superior 1 Star 10 Pin (3+3) | - | - | 2081 | 4559 | 01R-35J-36J |
| YALE | Platinum 3 Star 10 Pin (3+3) | - | - | 2083 | 4559 | 01R-35J-36J |
| CCC | | | 12345 | 9398 | 4460 | 01V |
| KEYA | | | 123 | 9399 | 4516 | 01V |
| UEME | | | 12345 | 9400 | 4518 | 01V |
| SOPRANO | | | 1234 | 9401 | 4519 | 01V |
| WELKA | | | 0123456789 | 9402 | 4520 | 01V |
| BULLDOG | | | 0123456 | 9403 | 4521 | 01V |
| CISA | | | 0123456789 | 9404 | 4522 | 01V |
| SOPRANO | S-60 | | 01234567 | 9405 | 4523 | 01V |
| SOPRANO | S-25 | | 0123 | 9406 | 4524 | 01V |
| RIELDA | RS3 | | BL21ABAADPUO- BL3OJAAERNN | 9356 | 3756 | 01V |
| EVERGOOD | | | 123 | 9407 | 4526 | 01V |
| SOBINCO | | | 1234567 | 9408 | 4527 | 01V |
| KEYA | - | | 234 | 8976 | 4532 | 01V |
| CORNI | CC8 | | 12345 | 8977 | 4533 | 01V |
| STAM | | | 012345 | 9409 | 4893 | 01V |



FUTURA – FUTURA PRO

NEWS WEB



August 2018

1_2018 FUTURA V.3.9.0 – FUTURA PRO V.3.11.0

NEW SYSTEMS

| | LOCK MANUFACTURER | LOCK SYSTEM | PROFILE/SERIES | SERIES | SN | DATA CARD | CLAMP |
|--|--|---------------------|----------------|------------------------------|------|-----------|-------------|
| | ASSA ABLOY | Assa Abloy C310 | - | 12345678 | 9797 | 4505 | 01V |
| | LSDA | - | - | 0123456789 | 9395 | 4493 | 01V |
| | LSDA | - | - | 12345678 | 9396 | 4495 | 01V |
| | SUBARU | stop 4 | - | 30001-37850 | 9388 | 4459 | 01V |
| | CCC | - | - | 12345 | 9398 | 4460 | 01V |
| | KEYA | - | - | 123 | 9399 | 4516 | 01V |
| | UEME | - | - | 12345 | 9400 | 4518 | 01V |
| | SOPRANO | - | - | 1234 | 9401 | 4519 | 01V |
| | WELKA | - | - | 0123456789 | 9402 | 4520 | 01V |
| | BULLDOG | - | - | 0123456 | 9403 | 4521 | 01V |
| | CISA | - | - | 0123456789 | 9404 | 4522 | 01V |
| | SOPRANO | S-60 | - | 01234567 | 9405 | 4523 | 01V |
| | SOPRANO | S-25 | - | 0123 | 9406 | 4524 | 01V |
| | RIELDA  | RS3 | - | BL21ABAADPUO- BL3OJAAERNN | 9356 | 3756 | 01V |
| | EVERGOOD | - | - | 123 | 9407 | 4526 | 01V |
| | SOBINCO | - | - | 1234567 | 9408 | 4527 | 01V |
| | SILCA | Silca SK3 back side | - | - | 2012 | 4407 | 01R-01J-02J |
| | SILCA | Silca SK3 side | - | - | 2010 | 4395 | 01R-07J-08J |
| | HYUNDAI | Hyundai (2T- 8W) | - | 0001-2500 | 2037 | 3336 | 01R-01J-02J |
| | Iseo  | R11 PROGRESS | - | 000001-061110 | 2061 | 1597 | 01R-11J-02J |



FUTURA – FUTURA PRO NEWS WEB



| | | | | | | | |
|--|-------|----------------------|---|---|------|------|-------------|
| | TITAN | Titan T250 (6+5) | - | - | 1461 | 3713 | 01R-01J-02J |
| | TITAN | Titan T100 X-R (4+4) | - | - | 1248 | 3197 | 01R-50J-51J |

June 2018

1_2018 FUTURA V.3.8.0 – FUTURA PRO V.3.10.0

NEW FUNCTIONS



- SILCA SOFTWARE INTERFACE

The Silca Software Interface (SSI) function has been set up to run the production of master key system (MKS) in XML KESO and 'standard' DAT file formats ('special' DAT formats are not included).

Please note

For further details about the SSI function, download the FUTURA PRO Software Manual from the FUTURA PRO section of the Silca website (www.silca.biz)



- **OEM CLIENT ASSA®:** the OEM CLIENT function has been implemented for copying keys using data supplied by the manufacturer (OEM). At the moment the function runs the following ASSA®systems:
 - ASSA dp
 - ASSA Neptun
 - ASSA Triton





Important Note

Users who wish to use the special OEM CLIENT function must make a request to both the manufacturer and Silca. Consult the Silca sales network for information regarding which manufacturers allow this function to be used.

When users have been authorised by the manufacturer and have applied to be enabled by SILCA they must unlock the OEM CLIENT function on board the machine by downloading a specific software update for their own FUTURA cutting machine.

After the software update, check that enabling has been activated by selecting the INFORMATION window and checking the ENABLE OEM section.

NEW SYSTEMS

| LOCK MANUFACTURER | LOCK SYSTEM | PROFILE/SERIES | SERIES | SN | DATA CARD | CLAMP |
|---|--------------------------------|----------------|--------|------|-----------|-------------|
| AGA  | Aga SLC (5+5) | - | - | 2025 | 4346 | 01R-01J-02J |
| AGA  | Aga SLX (5+4) | - | - | 2026 | 4349 | 01R-01J-02J |
| ASSA | Assa DP Sidecode | - | - | 1095 | 2882 | 01R-68J-69J |
| ASSA | Assa Neptun-Triton (Side Code) | - | - | 1483 | 3553 | 01R-68J-69J |
| DOM  | Dom IX6 SR E (Prf.234) | - | - | 2019 | 4436 | 01R-01J-02J |
| DOM  | Dom IX6 SR E (Prf.234) AT | - | - | 2020 | 4437 | 01R-01J-02J |



FUTURA – FUTURA PRO NEWS WEB



| | | | | | | |
|-----------------|--------------------------------|------------------|--------------------|------|------|-------------|
| FLEXON | FLEXON CS2100 (6P) | - | - | 2027 | 4351 | 01R-01J-02J |
| FLEXON | FLEXON CS2001 (5+5) | - | - | 2028 | 4458 | 01R-01J-02J |
| LINCE | Lince C3 (5+5) | - | - | 864 | 2462 | 01R-24J-25J |
| M&C | M&C Condor (Snake) | - | - | 2022 | 4428 | 01R-82J-83J |
| M&C | M&C Condor (Side) | - | - | 2023 | 4429 | 01R-82J-83J |
| M&T | M&T Champions Pro CP4 (C6LVJ2) | C6LVJ2... ... | C6LVJ200010 A - | 2034 | 3802 | 01R-01J-02J |
| MOTTURA | Mottura Project (6P) | - | - | 2021 | 2982 | 01R-01J-02J |
| ASSA | Cliq | - | 123456789 | 3931 | 2880 | 01V |
| ASSA | Neptun | - | 123456789 | 4532 | 345 | 01V |
| ASSA | Triton 5900 | - | 111111- 888888 | 4530 | 3822 | 01V |
| CAS-CISA | - | - | 1234 | 9380 | 4434 | 01V |
| CEE | - | - | 1234567 | 9378 | 4432 | 01V |
| DOM | DOM 050-22 | - | 123456 | 8954 | 4476 | 01V |
| DOM | DOM 050-22 | - | 123456 | 8955 | 4476 | 01V |
| ERA | Fortress | 6Y | 300001- 398246 | 9381 | 4042 | 01V |
| GLOBAL | - | - | 123456 | 9377 | 4430 | 01V |
| IBFM | Art.2260/60mm | - | 123456789 | 9389 | 4470 | 01V |
| IBFM | Art.2240/40mm | - | 12345 | 9390 | 4471 | 01V |
| IBFM | Art.2302/OL/54mm | - | 123456 | 9391 | 4472 | 01V |
| IBFM | Art.2215/15mm | - | 12345678 | 9392 | 4473 | 01V |
| IBFM | Art.2220/20mm | - | 123456 | 9393 | 4474 | 01V |
| IBFM | Art.2225/25mm | - | 12345 | 9394 | 4475 | 01V |
| INFINITI/NISSAN | stop 4 | - | 1-22185 | 9386 | 4459 | 01V |
| INFINITI/NISSAN | stop 4 | - | 40001-41518 | 9387 | 4459 | 01V |



FUTURA – FUTURA PRO NEWS WEB














| | | | | | | |
|----------|-----------------|---|-------------------|------|------|-----|
| KABA | PX-PXP | - | 1234567890 | 8941 | 3706 | 01V |
| MAUER | S1 | - | 123456789 | 9379 | 4433 | 01V |
| NISSAN | stop 4 | - | 1-22185 | 9385 | 4451 | 01V |
| NISSAN | stop 4 | - | 1-22185 | 9388 | 4460 | 01V |
| RIELDA 🗝 | RS3 | - | BL21ABAADPU O- | 9356 | 3756 | 01V |
| TITAN | Titan K6TL (6P) | - | 123456789 | 8952 | 2202 | 01V |

April 2018

1_2018 FUTURA V.3.7.0 – FUTURA PRO V.3.9.0

NEW SYSTEMS

| LOCK MANUFACTURER | LOCK SYSTEM | PROFILE/SERIES | SERIES | SN | DATA CARD | CLAMP |
|--|-------------------------------------|----------------|---------------|------|-----------|-------------|
| ABUS  | ABUS BRAVUS PRO 1000(SHOULDER STOP) | - | - | 1963 | 4325 | 01R-29J-30J |
| ABUS  | ABUS BRAVUS PRO 3000(SHOULDER STOP) | - | - | 1964 | 4326 | 01R-29J-30J |
| ABUS  | ABUS BRAVUS PRO 2000(SHOULDER STOP) | - | - | 1965 | 4327 | 01R-29J-30J |
| ABUS  | ABUS BRAVUS PRO 4000(SHOULDER STOP) | - | - | 1966 | 4328 | 01R-29J-30J |
| ABUS  | ABUS BRAVUS PRO 3000(TIP STOP) | - | - | 1958 | 4321 | 01R-29J-30J |
| ABUS  | ABUS BRAVUS PRO 1000(TIP STOP) | - | - | 1959 | 4322 | 01R-29J-30J |
| ABUS  | ABUS BRAVUS PRO 2000(TIP STOP) | - | - | 1960 | 4323 | 01R-29J-30J |
| ABUS  | ABUS BRAVUS PRO 4000(TIP STOP) | - | - | 1962 | 4324 | 01R-29J-30J |
| VACHETTE | V-DIS Courte A | - | - | 1996 | 4369 | 01R-13J-02J |
| VACHETTE | V-DIS Longue B | - | - | 1997 | 3448 | 01R-13J-02J |
| VACHETTE | YALE 1000 EF 6P | - | - | 1998 | 4369 | 01R-13J-02J |
| VACHETTE | V-DIS+ | - | - | 1999 | 4266 | 01R-01J-02J |
| M&C  | M&C Color New (3+3) | | 1A0001-6M3600 | 2000 | 4332 | 01R-95J-96J |
| VACHETTE | Vachette Vac153R (6P) | - | - | 2011 | 4408 | 01R-01J-02J |
| POTENT | Potent PT6RP | - | - | 2013 | 4411 | 01R-01J-02J |
| OJMAR | OJ18(6+2) | - | - | 2014 | 4413 | 01R-01J-02J |
| ABUS | ABUS BIKE 8N | | 00001-05166 | 1993 | 4366 | 01R-92J-93J |
| M&C  | M&C Color New (2T-5W) | | 1A0001-6M3600 | 2001 | 4345 | 01R-01J-02J |
| EUROLOCKS | dethleffs EU22RP (2T-6W) | - | - | 2004 | 4350 | 01R-01J-02J |
| EVVA  | EVVA 4KS (2T) | - | - | 2009 | 4352 | 01R-07J-08J |



FUTURA – FUTURA PRO NEWS WEB



| | | | | | | |
|----------------|--------------------|-----------|--------------------------|------|------|-------------|
| TITAN | Titan K5+ | - | - | 1484 | 3737 | 01R-01J-02J |
| ABUS | Abus Vela Pro 2000 | VE20..... | 00001-30000 | 2015 | 4423 | 01R-01J-02J |
| ABUS | Abus Vela Pro 1000 | VE10..... | 00001-30000 | 2016 | 4424 | 01R-01J-02J |
| MAHINDRA | Mahindra (2T-8W) | - | - | 2017 | 4425 | 01R-19J-02J |
| HYUNDAI | Hyundai (2T--8W) | - | - | 2018 | 4427 | 01R-19J-02J |
| PUNDRA | | W... | 000-522 | 8947 | 561 | 01V |
| PUNDRA | | W... | 101-330 | 8948 | 561 | 01V |
| PUNDRA | | W... | 401-800 | 8949 | 561 | 01V |
| CES | | | 0123456 | 9360 | 4401 | 01V |
| KEYRACK | | | 0123456 | 9361 | 4402 | 01V |
| FAAB | | | 12345678 | 9362 | 4404 | 01V |
| CES | | | 1234567890 | 9363 | 4405 | 01V |
| BALINGLOCK | | | 0123456789 | 9364 | 4406 | 01V |
| LOCKWOOD (AUS) | | | 1234567890 | 9365 | 4410 | 01V |
| UAP | | | 0123456789AB CDEFGHIL | 9366 | 4412 | 01V |
| CORBIN | 405/20 | ... | 1234567 | 9367 | 4414 | 01V |
| CORBIN (AUS) | | | 0123456789 | 9368 | 4415 | 01V |
| BURG | | | 01234567 | 9369 | 4416 | 01V |
| MILA | | | 1234567 | 9370 | 4418 | 01V |
| MASTER | | | 012345678 | 9371 | 4419 | 01V |
| CIL LIL | | | 0123456789AB C | 9372 | 4420 | 01V |
| BURG | | | 123456 | 9373 | 4421 | 01V |
| ABUS | Abus Titalium | | 123456 | 9374 | 327 | 01V |
| ELZETT | 30/30 | | 123456 | 9375 | 2274 | 01V |



FUTURA – FUTURA PRO NEWS WEB



| | | | | | | | |
|--|----------|--|-------|-----------|------|------|-----|
| | TSS | | | 012345678 | 9376 | 4426 | 01V |
| | KENWORTH | | P... | 1-1500 | 8950 | 287 | 01V |

January 2018

1_2018 FUTURA V.3.6.0 – FUTURA PRO V.3.8.0

NEW FUNCTIONS



- The "User Model Editor" function has a new "Multiline" token (T13) for engraving text on a number of rows.



















NEW SYSTEMS

| | LOCK MANUFACTURER | LOCK SYSTEM | PROFILE/SERIES | SERIES | SN | DATA CARD | CLAMP |
|--|---|--|----------------|-------------------------|------|-----------|-------------|
|  | PFAFFENHAIN  | ABUS PFAFFENHAIN S6+ | - | - | 9359 | 4364 | 01V |
| | PUNDRA | | W... | 000-522 | 8947 | 561 | 01V |
| | PUNDRA | | W... | 101-330 | 8948 | 561 | 01V |
| | PUNDRA | | W... | 401-800 | 8949 | 561 | 01V |
| | TESA  | Tesa TX70 (5+5+11) | - | - | 1042 | 2770 | 01R-94J-83J |
| | TITAN | Titan K5-K55/CR T75 (275) | | K55 00001- K55 23375 | 1985 | 2570 | 01R-01J-02J |
| | FF-FACCHINETTI | SY30-SY32-SY35- C11 New | | 2260001- 2301184 | 1987 | 4360 | 01R-01J-02J |
| | VEGA | VP-7 | - | - | 1988 | 4361 | 01R-01J-02J |
| | KABA  | Kaba ExperT pluS S 1.0a (K83A)-Swed | | EM101000- EM105997 | 1989 | 3670 | 05R |
| | HYUNDAI | Hyundai Kona (2T- 8W) | H.... | 0001-2500 | 1990 | 4362 | 01R-01J-02J |
| | DOM | Dom IX6N | - | - | 1991 | 4363 | 01R-01J-02J |
| | YALE | Yale 987 Plus | - | - | 1992 | 4365 | 01R-01J-02J |
| | SCHLAGE | C999 Ultra | - | - | 1994 | 4280 | 01R-01J-02J |
| | ABUS | Abus Bike 6N (4T- 6W) | | 0001-1000 | 1995 | 4368 | 01R-92J-93J |

December 2017

1_2017 FUTURA v. 3.5.0 - FUTURA PRO v. 3.7.0

New Systems

| Lock Manufacturer | Lock System | Profile/Series | Series | SN | Data card | Clamp |
|--|---|----------------|---------------|------|-----------|-------------|
| DOM  | Dom IX Twinstar (Prof. 290-291) | - | - | 1901 | 4273 | 01R-88J-89J |
| DOM  | Dom IX Twinstar Std. Cut (Prof. 290-291) | - | - | 1968 | 4333 | 01R-88J-89J |
| DOM  | Dom IX Twinstar Prf. Cut (Prof. 290-291) | - | - | 1969 | 4334 | 01R-88J-89J |
| WINKHAUS  | Winkhaus X-TRA Inclined (5P) | - | - | 703 | 1856 | R30-80J-81J |
| IBFM | IBFM 2304/CS (5P) | - | - | 1976 | 4344 | 01R-01J-02J |
| APECS | AP 3 Star | - | - | 1977 | 4343 | 01R-01J-02J |
| CISA  | Cisa AP4 Pmec-C KA | PMEC-C-KA | XN.0326.10 | 1861 | 4230 | 01R-05J-06J |
| CISA  | Cisa AP4 Pmec-A KA | PMEC-A-KA | XN.0327.10 | 1862 | 4230 | 01R-05J-06J |
| CISA  | Cisa AP4 Pmec-9 KA | PMEC-9-KA | XN.0328.10 | 1863 | 4230 | 01R-05J-06J |
| CISA  | Cisa AP4 Pmec-6 KA | PMEC-6-KA | XN.0329.10 | 1864 | 4230 | 01R-05J-06J |
| CISA  | Cisa AP4 Pmec-5 KA | PMEC-5-KA | XN.0330.10 | 1865 | 4230 | 01R-05J-06J |
| CISA  | Cisa AP4 Pmec-3 KA | PMEC-3-KA | XN.0331.10 | 1866 | 4230 | 01R-05J-06J |
| CISA  | Cisa AP4 Pmec-C CA | PMEC-C-CA | XN.0335.10 | 1970 | 4230 | 01R-05J-06J |
| CISA  | Cisa AP4 Pmec-A CA | PMEC-A-CA | XN.0336.10 | 1971 | 4230 | 01R-05J-06J |
| CISA  | Cisa AP4 Pmec-9 CA | PMEC-9-CA | XN.0337.10 | 1972 | 4230 | 01R-05J-06J |
| CISA  | Cisa AP4 Pmec-6 CA | PMEC-6-CA | XN.0338.10 | 1973 | 4230 | 01R-05J-06J |
| CISA  | Cisa AP4 Pmec-5 CA | PMEC-5-CA | XN.0339.10 | 1974 | 4230 | 01R-05J-06J |
| CISA  | Cisa AP4 Pmec-3 CA | PMEC-3-CA | XN.0340.10 | 1975 | 4230 | 01R-05J-06J |
| TITAN | Titan K5-K55/CR T75 (275) | | 001C-23375C | 1979 | 2570 | 01R-01J-02J |
| ISEO  | Iseo R7 Leroy Merlin (5+6+6) | | 000001-428306 | 1982 | 868 | 01R-01J-02J |
| DOM  | Dom IXSATS(Pr.169- 170-171-172)(Precod) | - | - | 1506 | 3788 | 01R-91J-02J |



FUTURA – FUTURA PRO NEWS WEB



| | | | | | | |
|------------|------------------------------------|---------|-------------------------------|------|------|-------------|
| DOM | Dom IXSATS (Prof. 169) | - | - | 1507 | 3789 | 01R-91J-02J |
| DOM | Dom IXSATS (Prof. 170) | - | - | 1508 | 3790 | 01R-91J-02J |
| DOM | Dom IXSATS (Prof. 171) | - | - | 1509 | 3791 | 01R-91J-02J |
| DOM | Dom IXSATS (Prof. 172) | - | - | 1510 | 3792 | 01R-91J-02J |
| DOM | DOM IXSATS (Prof. 167) | - | - | 1644 | 3929 | 01R-91J-02J |
| INN | INN (Pr.169-170-171-172)(Precoded) | - | - | 1637 | 3992 | 01R-91J-02J |
| INN | INN (Prof. 169) | - | - | 1638 | 3993 | 01R-91J-02J |
| INN | INN (Prof. 170) | - | - | 1639 | 3994 | 01R-91J-02J |
| INN | INN (Prof. 171) | - | - | 1640 | 3995 | 01R-91J-02J |
| INN | INN (Prof. 172) | - | - | 1641 | 3996 | 01R-91J-02J |
| INN | INN (Prof. 167) | - | - | 1645 | 4008 | 01R-91J-02J |
| RIELDA | RS3 | | BL21AJAADMYU- BL28FEAAEHTJ | 9356 | 3756 | 01V |
| RIELDA | RS4-RS5 | | ABBA2010000- ABEL9917211 | 9358 | 3757 | 01V |
| FORD AUS | - | | 123456 | 9354 | 4337 | 01V |
| ABUS | T112-T114 | TD..... | 00001-02000 | 9266 | 3908 | 01V |
| ASSA/ABLOY | ASSA ABLOY SCD(6P) | | ABCDEFGHJ | 9357 | 345 | 01V |
| DOM | Dom 7D | 7D... | 001-200 | 4418 | 4353 | 01V |
| OMR | - | | 12 | 9355 | 4354 | 01V |

November 2017

1_2017 FUTURA v. 3.4.1 - FUTURA PRO v. 3.6.1

Problems Solved



- Problem solved relating to cutting EVVA 4KS

October 2017

1_2017 FUTURA v. 3.4.0 - FUTURA PRO v. 3.6.0

Problems Solved



- Problem solved in the 'Copy from Original' function for flat keys.

New Functions

- **OEM CLIENT EVVA®**: the OEM CLIENT function has been implemented for copying keys using data supplied by the manufacturer (OEM). At the moment the function runs the following EVVA® systems:
 - Evva 3KS - 3KS+
 - Evva 4KS

Important Note

Users who wish to use the special OEM CLIENT function must make a request to both the manufacturer and Silca. Consult the Silca sales network for information regarding which manufacturers allow this function to be used.

When users have been authorised by the manufacturer and have applied to be enabled by SILCA they must unlock the OEM CLIENT function on board the machine by downloading a specific software update for their own FUTURA cutting machine.

After the software update, check that enabling has been activated by selecting the INFORMATION window and checking the ENABLE OEM section.



New Systems

| Lock Manufacturer | Lock System | Profile/Series | Series | SN | Data card | Clamp |
|--|---|----------------|-------------|----------------------|-----------|-------------|
| INAFER | INAFER (5P+6P) | - | - | 1917 | 4280 | 01R-01J-02J |
| asec-security | Asec 6P Dimple | - | - | 1921 | 4286 | 01R-01J-02J |
| HUGO | HUGO GR 4S | - | - | 1919 | 4284 | 01R-01J-02J |
| HUGO | HUGO GR 3.5S | - | - | 1920 | 4285 | 01R-01J-02J |
| Superlock | Superlock SL 11/15 (4+4) | - | - | 1922 | 4287 | 01R-35J-36J |
| GEVY | GEVY 5 PINS | - | - | 1924 | 4290 | 01R-01J-02J |
| GEVY | GEVY 6 PINS | - | - | 1925 | 4292 | 01R-01J-02J |
| GEVY | GEVY 11 PINS | - | - | 1927 | 4293 | 01R-01J-02J |
| DOM  | Dom Sigma Plus (Prof. 146) | - | - | 1926 | 4294 | 01R-31J-32J |
| RAV-BARRIACH | LOCXIS/ILA | - | - | 1928 | 4296 | 01R-01J-02J |
| APECS | Apecs RT-110(50/60C)-C-G (6P) | - | - | 1929 | 4297 | 01R-01J-02J |
| MAGNUM | Magnum 6P | - | - | 1930 | 4299 | 01R-01J-02J |
| Titan | Titan K5-K55/CR T75 (275) | L..... | 00001-56331 | 1931 | 2570 | 01R-01J-02J |
| IBFM | IBFM 2304/CS | - | - | 1932 | 4300 | 01R-01J-02J |
| IBFM | IBFM 2306 | - | - | 1934 | 4302 | 01R-01J-02J |
| IBFM | IBFM 2309 | - | - | 1933 | 4301 | 01R-01J-02J |
| CES  | POLLUX WZ (6+5+6) | - | - | 1935 | 4303 | 01R-05J-06J |
| CES  | POLLUX WZ (7+6+7) | - | - | 1936 | 4304 | 01R-05J-06J |
| MUL.T.LOCK | Mul-T-Lock MT5 (L)(19D) | - | - | 1937 | 4305 | 01R-01J-02J |
| MUL.T.LOCK | Mul-T-Lock MT5+ (L)(19D) | - | - | 1938 | 4306 | 01R-01J-02J |
| MUL.T.LOCK | Mul-T-Lock MT5+ (R)(19D) | - | - | 1939 | 4307 | 01R-01J-02J |
| MUL.T.LOCK | Mul.T.Lock Interactive (262)(19D) Mul.T.Lock Interactive (264)(19D) Mul.T.Lock Interactive (248)(19D) | - | - | 1940 1941 1942 | 4308 | 01R-01J-02J |
| MUL.T.LOCK | Mul.T.Lock Interactive (115) MK | - | - | 1943 | 4309 | 01R-01J-02J |
| MUL.T.LOCK | Mul.T.Lock (9mm-R)(19D) | - | - | 1944 | 4310 | 01R-01J-02J |
| MUL.T.LOCK | Mul.T.Lock Junior/Classic (19D) Mul.T.lock Gardesa Lion(19D) | - | - | 1945 1946 | 4311 | 01R-01J-02J |
| MUL.T.LOCK | Mul.T.Lock (9mm-L)(19D) | - | - | 1947 | 4312 | 01R-01J-02J |
| MUL.T.LOCK | Mul.T.Lock Interactive (225)(19D) Mul.T.Lock Interactive (223)(19D) | - | - | 1948 1949 | 4313 | 01R-01J-02J |
| MUL.T.LOCK Corbin Goldstar | Mul-T-Lock MT5 (R)(19D) Corbin Goldstar(19D) | - | - | 1950 1951 | 4314 | 01R-01J-02J |
| MUL.T.LOCK | Mul.T.Lock Interactive (206)(19D) | - | - | 1952 | 4315 | 01R-01J-02J |
| MUL.T.LOCK | Mul.T.Lock (8.8mm-R)(19D) | - | - | 1953 | 4316 | 01R-01J-02J |
| MUL.T.LOCK | Mul.T.Lock Interactive (215)(19D) | - | - | 1954 | 4317 | 01R-01J-02J |
| MUL.T.LOCK | Mul.T.Lock Interactive (115)(19D) | - | - | 1955 | 4318 | 01R-01J-02J |
| MG MONTI  | MG ST-KO9 | - | - | 1889 | 4263 | 01R-01J-02J |
| YALE | Yale 2100 | - | - | 1895 | 4266 | 01R-01J-02J |
| FAB-HUF | VAG High (4T-10W+4W) | - | - | 1892 | 4264 | 01R-56J-57J |
| Superlock | Superlock SL 11/15 (2T-3W) | - | - | 1923 | 4288 | 01R-01J-02J |
| M&C  | M&C Condor (snake+side pins) | - | - | 1957 | 4319 | 01R-82J-83J |



FUTURA – FUTURA PRO NEWS WEB



| | | | | | | |
|-------|---------------------------|-------|-----------------|------|------|-------------|
| OGDEN | Ogden Axial 45 (7P) | | 24568ABCDEFGHJI | 446 | 1789 | 02R |
| OGDEN | Ogden Axial 40 (7P) | | 24568ABCDEFGHJI | 445 | 1790 | 02R |
| Ford | Ford Fiesta 2017 | - | - | 1956 | 4320 | 01R-01J-02J |
| AGENT | Agent NEW GMD-500 (5+5+5) | - | - | 1967 | 4329 | 01R-01J-02J |
| DOM | Dom Sigma Plus(Prof. 146) | | 01234567 | 8972 | 4295 | 01V |
| IBFM | IBFM SERIE 2300 | | 12345678 | 9353 | 594 | 01V |



FUTURA – FUTURA PRO NEWS WEB



September 2017

1_2017 FUTURA v. 3.3.0 - FUTURA PRO v. 3.5.0

Problems Solved



- A decoding problem with the mobile tracer has been solved

New Functions



- NEW FUNCTION: ENGRAVING.

The ENGRAVING function software comes free for all FUTURA PRO and FUTURE key-cutting machine models.

The ENGRAVING function requires the following accessories:

Jaw 01E

Jaw 02E

Cutter 18DW (specific for engraving)

Accessories for the FUTURA PRO ENGRAVING model are STANDARD and OPTIONAL for all other FUTURA and FUTURA PRO models.

The function is enabled by default. To disable and to hide certain engraving keys and fields, edit the parameter in the section: OPTIONS menu -> Settings -> Options -> Preferences DIMPLE/LASER keys

- IMPROVED DECODING OF SYMMETRICAL VEHICLE KEYS

To solve installation difficulties encountered with symmetrical vehicle keys on side A or B of the standard clamp, the user may select the key blank before decoding the key. In this way the machine will indicate the best side of the clamp (C or D) on which to fit the key and can run the decoding operation successfully.



FUTURA – FUTURA PRO NEWS WEB



New Systems

| Lock Manufacturer | Lock System | Profile/Serie s | Series | SN | Data card | Clamp |
|-------------------|--|-----------------|-------------------|----------------|-----------|-------------|
| KESO | Keso K3000 Syst. 5 / Var. 6 (5 Axis) | - | - | 259 | 2265 | 01R-26J-27J |
| ASSA | ASSA ABLOY K100 | - | 000001-117649 | 1870 | 4239 | 01R-86J-87J |
| IKON | IKON RW6 | - | 000001-117649 | 1871 | 4239 | 01R-86J-87J |
| UNION | Union KeyPRIME | - | 000001-117649 | 1873 | 4239 | 01R-86J-87J |
| ASSA | Assa ABLOY CY110 | - | 000001-117649 | 1874 | 4239 | 01R-86J-87J |
| VACHETTE | Vachette Vercy | - | 000001-117649 | 1877 | 4239 | 01R-86J-87J |
| IKON | IKON RW6 Main+Side Row | - | 01000001-64117649 | 1875 | 4241 | 01R-86J-87J |
| DOM | Dom IX Saturn (Prof.140) | - | - | 1247 | 3195 | 01R-01J-02J |
| DOM | Dom IX Saturn (Prof.168) | - | - | 1494 | 3765 | 01R-01J-02J |
| KESO | Keso K3000S (Step-Drilling) | - | - | 601 | 1571 | 01R-26J-27J |
| KESO | Keso K1000S (Step-Drilling) | - | - | 599 | 1570 | 01R-26J-27J |
| PREFER | Prefer A (4+2) | A | 001-330 | 1885 | 4261 | 01R-01J-02J |
| PREFER | Prefer AA (5+5) | AA | 001-331 | 1883 | 4259 | 01R-01J-02J |
| PREFER | Prefer DAA (6+4+5) | DAA | 800001-891280 | 1882 | 4252 | 01R-01J-02J |
| PREFER | Prefer EAA (6+3+3) | EAA | 800001-852160 | 1884 | 4260 | 01R-01J-02J |
| PREFER | Prefer GAB (4+2+3) | GAB | 800001-804410 | 1880 | 3941 | 01R-01J-02J |
| PREFER | Prefer HAA (5+5+4) | HAA | 800001-800468 | 1881 | 4250 | 01R-01J-02J |
| ELZETT | X11 (6+3+2) | - | - | 1887 | 4262 | 01R-01J-02J |
| A.P.FER | A.P.FER CHAMPIONS PRO (CP4-JP) | C6JLP | 00010-C6LJP003G9 | 1893 | 3802 | 01R-01J-02J |
| Mul.T.Lock | Mul.T.Lock Interactive | - | - | 1894 | 4267 | 01R-01J-02J |
| Abus | Abus EC660 | A-Z | 00001-30000 | 1900,1902-1915 | 4063 | 01R-05J-06J |
| WINKHAUS | WINKHAUS on-TRA (EGS) | - | - | 1667 | 4060 | 01R-78J-79J |
| CISA | Cisa Astral Tekno CE P-S (Special Prof.) | (XN027710) | 000001P-012070S | 1691 | 3533 | 01R-74J-75J |
| CISA | Cisa Astral Tekno Special Profiles | (XN026210) | 000002-194160 | 1359 | 3533 | 01R-74J-75J |
| BRICARD | Bricard Serial XP Special Profiles | (XN026210) | 000002-194160 | 1360 | 3533 | 01R-74J-75J |
| CISA | Cisa Astral Tekno CA (Special Profiles) | (XN026710) | 000008T-194155U | 1690 | 3533 | 01R-74J-75J |
| KIA | Kia (2T-- 8W) | C | 0001-2900 | 1886 | 4129 | 01R-01J-02J |
| TRIMARK | TriMark (2T-6W) | - | - | 1888 | 4203 | 01R-19J-02J |
| BMW | Bmw (2T-8W) | - | 10-81000 | 1890 | 1842 | 01R-01J-04J |
| FAB | FAB (2T-4W) | - | - | 1891 | 4265 | 01R-01J-02J |
| FAB | VAG Mid (4T-9W+3W) | - | - | 1706 | 4105 | 01R-56J-57J |
| KIA | Kia (2T - 8W) | JA | 1001-3500 | 1916 | 3336 | 01R-01J-02J |
| UAP | UAP Kinetica | | 0123456789A | 8964 | 4246 | 01V |
| UAP | UAP 35mm cyl. | | 0123456789A | 8962 | 4246 | 01V |
| PUNDRA | | B... | 101-330 | 8961 | 561 | 01V |
| WILKA | Wilka TH6 PR100 | | 200270-255966 | 8965 | 2952 | 01V |
| ABUS | | V65... | 1-331 | | 730 | 01V |
| GREATWALL | | | 45678 | 8966 | 4251 | 01V |
| YALE | Yale Jixin | | 123456 | 8998 | 4253 | 01V |
| CDP | | | 0123456 | 9065 | 4254 | 01V |
| BAB | | | 0123456789A | 8968 | 4255 | 01V |
| GELEM | SP148 | | 01234567 | 8969 | 4256 | 01V |



FUTURA – FUTURA PRO NEWS WEB



June 2017

1_2017 FUTURA v. 3.2.1 - FUTURA PRO v. 3.4.1

Problems Solved



- Solved some problems. We suggest to install this version.



New Functions

- **OEM CLIENT MOTTURA®**: the OEM CLIENT function has been implemented for copying keys using data supplied by the manufacturer (OEM). At the moment the function runs the following MOTTURA® systems:

- Champions C10
- Champions C28 - C29
- Champions C2J - C2K
- Champions C30 - C31
- Champions C34 - C35
- Champions C38
- Champions C43 - C44
- Champions C4J - C4K
- Champions CP4 - CM7
- Champions CP4 Armo & Riarmo
- Champions CP4 Matic
- Champions CP4 Armo&Riarmo Attiva/Disattiva
- Champions C28 Plus
- Champions C39
- Champions C43 Plus

Important Note

Users who wish to use the special OEM CLIENT function must make a request to both the manufacturer and Silca. Consult the Silca sales network for information regarding which manufacturers allow this function to be used.

When users have been authorised by the manufacturer and have applied to be enabled by SILCA they must unlock the OEM CLIENT function on board the machine by downloading a specific software update for their own FUTURA cutting machine.

After the software update, check that enabling has been activated by selecting the INFORMATION window and checking the ENABLE OEM section.



















- **Queue of Job Function**: the Queue of Job function has been revised to take into account new software developments. At the moment it is divided into:
 - o STANDARD queue with current functionalities but new graphics
 - o OEM queue for OEM jobs only

Important Note

For further details about the OEM CLIENT function and Job Queue, download the FUTURA PRO Software Manual from the Silca website, FUTURA PRO section (www.silca.biz)



New Systems

| Lock Manufacturer | Lock System | Profile/Series | Series | SN | Data card | Clamp |
|--|------------------------------------|----------------|-------------|------|-----------|-------------|
| AMIG  | Amig (6+6) | - | - | 827 | 2395 | 01R-01J-02J |
| FIAM | Fiam Logic 17(5+5) | - | - | 1049 | 2780 | 01R-66J-67J |
| FIAM | Fiam Logic 18/19(5+5) | - | - | 1050 | 2781 | 01R-66J-67J |
| WANJIN | Wanjin WJ1R (620-7P) | - | - | 1814 | 4193 | 01R-01J-02J |
| WANJIN | Wanjin WJ1R (650-7P) | - | - | 1815 | 4194 | 01R-01J-02J |
| WANJIN | Wanjin WJ1R (530-7P) | - | - | 1816 | 4196 | 01R-01J-02J |
| IBFM | ibfm 2303/CS | - | - | 1817 | 4197 | 01R-01J-02J |
| MSM | MSM GPI1 (7P) | - | - | 1818 | 4200 | 01R-01J-02J |
| APECS | APECS APK2R (6P) | - | - | 1819 | 4202 | 01R-01J-02J |
| GATEMATE | Gatemate (6P) | - | - | 1823 | 4204 | 01R-01J-02J |
| WINKHAUS  | Winkhaus X-TRA (5+5) | - | - | 526 | 1444 | 01R-80J-81J |
| M&C  | M&C Condor (Main+side pins) | - | - | 1831 | 4218 | 01R-82J-83J |
| M&C  | M&C Condor (Main pins) | - | - | 1867 | 4233 | 01R-82J-83J |
| M&C  | M&C Condor (Main + snake) | - | - | 1868 | 4234 | 01R-82J-83J |
| LIPS | Lips 2000 Octro (5A) | - | - | 663 | 1829 | 01R-01J-02J |
| YALE | Yale YA99R (6+6) | - | - | 1841 | 4222 | 01R-01J-02J |
| KESO  | K8000 Omega^2 Syst. 9 / Var. 44 | - | - | 1849 | 4224 | 01R-01J-02J |
| MUL.T.LOCK | Mul.T.Lock Gardesa Tiger (7P) | - | - | 1543 | 1504 | 01R-01J-02J |
| MUL.T.LOCK | Mul.T.Lock interactive (223) | - | - | 1845 | 956 | 01R-01J-02J |
| MUL.T.LOCK | Mul.T.Lock interactive (248) | - | - | 1846 | 889 | 01R-01J-02J |
| MUL.T.LOCK | Mul.T.Lock Junior/Classic | - | - | 646 | 1632 | 01R-01J-02J |
| MUL.T.LOCK | Mul.T.Lock Gardesa Lion | - | - | 1844 | 1632 | 01R-01J-02J |
| MUL.T.LOCK | Mul.T.Lock integrator | - | - | 1843 | 1504 | 01R-01J-02J |
| HOK | HOK HOK2R (6P) | - | - | 1850 | 4227 | 01R-01J-02J |
| CISA  | CISA AP4 PG | PG | XN.0310.10 | 1851 | 4228 | 01R-05J-06J |
| CISA  | CISA AP4 PG 3L | PG | XN.0317.10 | 1853 | 4228 | 01R-05J-06J |
| CISA  | CISA AP4 PG 3C | PG | XN.0318.10 | 1854 | 4228 | 01R-05J-06J |
| CISA  | CISA AP4 PG CA | PG | XN.0319.10 | 1855 | 4228 | 01R-05J-06J |
| CISA  | CISA AP4 PG P/S | PG | XN.0320.10 | 1856 | 4228 | 01R-05J-06J |
| CISA  | CISA AP4 PE | PE | XN.0321.10 | 1852 | 4229 | 01R-05J-06J |
| CISA  | CISA AP4 PE 3L | PE | XN.0322.10 | 1857 | 4229 | 01R-05J-06J |
| CISA  | CISA AP4 PE 3C | PE | XN.0323.10 | 1858 | 4229 | 01R-05J-06J |
| CISA  | CISA AP4 PE CA | PE | XN.0324.10 | 1859 | 4229 | 01R-05J-06J |
| CISA  | CISA AP4 PE P/S | PE | XN.0325.10 | 1860 | 4229 | 01R-05J-06J |
| TRELOCK | Trelock RS455-H2 (4T-4W) | - | - | 1411 | 3639 | 01R-01J-02J |
| EVVA  | EVVA 4KS (1T) | | 987654321 | 1848 | 4226 | 01R-07J-08J |
| KESO | Keso K3000 Syst.5 / Var.6 (3 Axis) | - | - | 600 | 1567 | 01R-26J-27J |
| LIPS | Lips 1000 Octro (5A) | - | - | 678 | 1830 | 01R-26J-27J |
| KABA | Kaba Miwa (11+11+10+10) | - | - | 800 | 2349 | 01R-84J-85J |
| KABA | Kaba Miwa New (11+11+10+10) | - | - | 1342 | 3432 | 01R-84J-85J |
| FEDERAL | YCF 35-35 | 6Y..... | 200001- | 9228 | 4042 | 01V |
| MAZDA | - | - | 10100-12283 | 8944 | 4231 | 01V |
| GREATWALL | - | - | 123 | 8945 | 4232 | 01V |
| WINKHAUS  | RPS+ | - | 0123456789 | 8903 | 4214 | 03V |
| ASSA-ABLOY | Cylinder VIP+ | - | 1234567890 | 8943 | 4221 | 01V |





FUTURA – FUTURA PRO NEWS WEB



| | | | | | | | |
|--|------------|--------------|--|------------|------|------|-----|
| | VACHETTE | HDI+/VMI+ | | 1234567890 | 8831 | 3719 | 01V |
| | ASSA-ABLOY | Cylinder VMI | | 12345678 | 8942 | 4216 | 01V |

Problems Solved



- Problem solved in decoding keys requiring a change of jaws.
- Cutting problem solved with cuts entered by the F9 function.



FUTURA – FUTURA PRO NEWS WEB



May 2017

1_2017 FUTURA v. 3.1.1 - FUTURA PRO v. 3.3.1

Problems Solved



- Solved a problem cutting more pieces of a key with only one cut axis.
- The number of cutting steps have been increased both for high security car keys and for edge keys.

April 2017

1_2017 FUTURA v. 3.1.0 - FUTURA PRO v. 3.3.0






























Problems Solved



- Solved a problem related to the “Check installed key” function
- Solved a problem related to the decoding function
- Corrected data of the following SN:1791 (SUPERIOR -PLATINUM), 22 (LANCIA GT2), 83 (Mercedes HU64P '93 (2T-10W), 1482 (Dodge 2T-10W), 1602 (Mercedes HU64P 2T-10W), 2 (Alfa romeo GT2AP 5+5), **1199** (Assa D12 Serie 1200), **1356** (Lexus TOY48 2T-4W), **9085** (MITSUBISHI).

New Systems



| Lock Manufacturer | Lock System | Profile/Series | SN | Data card | Clamp |
|--|-------------------------------|----------------------|------|-----------|-------------|
| ABUS  | Abus EC660 | S00001B- S30000B | 1803 | 4063 | 01R-05J-06J |
| ISEO  | Iseo R11 Progress | 000001-038897 | 1820 | 1597 | 01R-11J-02J |
| ISEO  | Iseo R11 Progress (Cantiere) | 000001-012977 | 1821 | 1597 | 01R-11J-02J |
| ISEO  | Iseo R11 Progress (Padronale) | 100001-112977 | 1822 | 1597 | 01R-11J-02J |
| ABUS  | Abus vela 1000 | VE10.....00001-30000 | 1770 | 4152 | 01R-01J-02J |
| ABUS  | Abus vela 2000 | VE20.....00001-30000 | 1775 | 4156 | 01R-01J-02J |
| ABUS  | Abus xp20s |DXPY | 1830 | 4217 | 01R-05J-06J |
| WINKHAUS  | Winkhaus ON-tra (P1) | - | 1613 | 3938 | 01R-78J-79J |
| WINKHAUS  | Winkhaus ON-tra (P3) | - | 1614 | 3939 | 01R-78J-79J |
| WINKHAUS  | Winkhaus ON-tra + (P1-P1) | - | 1616 | 3943 | 01R-78J-79J |
| WINKHAUS  | Winkhaus ON-tra + (P1-P2) | - | 1617 | 3944 | 01R-78J-79J |
| WINKHAUS  | Winkhaus ON-tra + (P1-P3) | - | 1618 | 3945 | 01R-78J-79J |
| WINKHAUS  | Winkhaus ON-tra + (P1-P4) | - | 1619 | 3946 | 01R-78J-79J |
| WINKHAUS  | Winkhaus ON-tra + (P1-P5) | - | 1620 | 3947 | 01R-78J-79J |
| WINKHAUS  | Winkhaus ON-tra + (P1-P6) | - | 1621 | 3948 | 01R-78J-79J |
| WINKHAUS  | Winkhaus ON-tra + (P1-P7) | - | 1622 | 3949 | 01R-78J-79J |
| WINKHAUS  | Winkhaus ON-tra + (P1-P8) | - | 1623 | 3950 | 01R-78J-79J |
| WINKHAUS  | Winkhaus ON-tra + (P3-P1) | - | 1624 | 3951 | 01R-78J-79J |
| WINKHAUS  | Winkhaus ON-tra + (P3-P2) | - | 1625 | 3952 | 01R-78J-79J |
| WINKHAUS  | Winkhaus ON-tra + (P3-P3) | - | 1626 | 3953 | 01R-78J-79J |
| WINKHAUS  | Winkhaus ON-tra + (P3-P4) | - | 1627 | 3954 | 01R-78J-79J |
| WINKHAUS  | Winkhaus ON-tra + (P3-P5) | - | 1628 | 3955 | 01R-78J-79J |
| WINKHAUS  | Winkhaus ON-tra + (P3-P6) | - | 1629 | 3956 | 01R-78J-79J |
| WINKHAUS  | Winkhaus ON-tra + (P3-P7) | - | 1630 | 3957 | 01R-78J-79J |
| WINKHAUS  | Winkhaus ON-tra + (P3-P8) | - | 1631 | 3958 | 01R-78J-79J |
| SSANGYONG | SSANGYONG (4T-6W) | KW1234 | 1813 | 2372 | 01R-01J-02J |
| LEXUS | Lexus TOY48P (4T-8W) | O0001-O5000 | 4801 | 480 | 01R-01J-02J |
| M&C  | M&C Matrix | .. 1A-9Z | 1828 | 4209 | R01-66J-67J |
| M&C  | M&C Condor | 011A1001-109A3169 | 1826 | 4206 | 01R-82J-83J |
| M&C  | M&C Condor | 011B1001-109B3169 | 1832 | 4206 | 01R-82J-83J |
| M&C  | M&C Condor | 011C1001-109C3169 | 1833 | 4206 | 01R-82J-83J |



FUTURA – FUTURA PRO NEWS WEB



| | | | | | |
|------------|--------------------------|-------------------|------|------|-------------|
| M&C | M&C Condor | 011D1001-109D3169 | 1834 | 4206 | 01R-82J-83J |
| M&C | M&C Condor | 011E1001-109E3169 | 1835 | 4206 | 01R-82J-83J |
| M&C | M&C Condor | 011F1001-109F3169 | 1836 | 4206 | 01R-82J-83J |
| M&C | M&C Condor | 011G1001-109G3169 | 1837 | 4206 | 01R-82J-83J |
| M&C | M&C Condor | 011H1001-109H3169 | 1838 | 4206 | 01R-82J-83J |
| M&C | M&C Condor | 011K1001-109K3169 | 1839 | 4206 | 01R-82J-83J |
| M&C | M&C Condor | 011M1001-106M3169 | 1840 | 4206 | 01R-82J-83J |
| HUF | BAIC Motors D50 | - | 1825 | 4186 | 01R-19J-02J |
| HUF | Mercedes HU126T (2T-10W) | - | 1827 | 4207 | 01R-01J-04J |
| VALEO | Chang An (2T-7W) | - | 1829 | 4212 | 01R-01J-02J |
| ASSA-ABLOY | C300 | 12345678 | 8808 | 4213 | 01V |
| MINDA | | 2001-3170 | 5840 | 4201 | 01V |
| ASSA-ABLOY | Gen-6 System | 0123456789BHT | 8809 | 4195 | 01V |
| MEDECO | KeyMark X4 7P | 0123456789 | 8790 | 4059 | 01V |
| YALE | Serie 62000 60mm | 0123456789 | 8789 | 4208 | 01V |
| SUZUKI | | 7701-8904 | 9351 | 157 | 01V |



FUTURA – FUTURA PRO NEWS WEB



March 2017

1_2017 FUTURA v. 3.0.3 - FUTURA PRO v. 3.2.2

Problems Solved



- Fixed data card data of SN 1791 (SUPERIOR-PLATINUM), 22 (LANCIA GT2), 2 (ALFA ROMEO GT2AP), 83-1602 (MERCEDES HU64P), 1482 (DODGE).

March 2017

1_2017 FUTURA v. 3.0.1 - 3.0.2

Problems Solved



- Solved some problems. We suggest to install this version.

February 2017

1_2017 FUTURA v. 3.0.0 - FUTURA PRO v. 3.2.0

New Functions



- **Software performance greatly enhanced to make navigation and searches quicker**
- **New guided software update procedures implemented via tablet and USB PEN**
- CodeMaker function (option to buy) implemented for flat and dimple keys. Used to create data cards not yet included in the SILCA database
- F9 function introduced to facilitate entering combinations for KABA Expert keys
- Cutting review function introduced for laser-cut keys
- New simplified search implemented for automotive keys
- Function implemented for using any side of clamp 01V to cut symmetrical, flat double keys
- Method modified for cutting flat and laser keys by selecting the number of times the cutter passes

New Systems

| Lock Manufacturer | Lock System | Profile/Series | SN | Data card | Clamp |
|--|-----------------------|-----------------|------|-----------|-------------|
| YALE | Yale 1000 Series (5P) | 1001-3640 | 1795 | 3448 | 01R-13J-02J |
| GERDA  | GERDA PROSystem | LP00162-LP17D99 | 1796 | 4181 | 01R-01J-02J |
| BASI/DOM  | Basi K10 (prof, 157) | - | 1443 | 3694 | 01R-01J-02J |
| PREFER | Prefer (3+3W+2) | (3+3W+2) | 303 | 1770 | 01R-01J-02J |
| MCM | Mcm 4SE MC10R (6P) | - | 191 | 1510 | 01R-62J-63J |
| POTENT | POTENT 4000 Evolution | 800001-830000 | 1800 | 4190 | 01R-13J-77J |
| POTENT | POTENT 4000 Evolution | 800001-830000 | 1801 | 4190 | 01R-13J-77J |
| YALE  | YALE YL6 Main Row | - | 1802 | 4191 | 01R-01J-02J |
| EUROSPEC | D69 Padlock | - | 1673 | 4069 | 01R-01J-02J |
| EUROSPEC | D54 Chain Lock | - | 1674 | 4070 | 01R-01J-02J |
| EUROSPEC | D74 U Lock | - | 1675 | 4071 | 01R-01J-02J |
| EUROSPEC | D51 Cable Lock | - | 1676 | 4072 | 01R-01J-02J |
| Lehmann | Lehmann Prestige B5 | | 1559 | 3868 | 01R-76J-77J |
| Audi-VW | Audi-VW HU66P (2T-8W) | 0001-6000 | 102 | 970 | 01R-03J-02J |
| Audi-VW-FORD- | FORD HU66P (2T-8W) | 6001-8110 | 1798 | 970 | 01R-03J-02J |
| AUDI/PORSCHE/ | HU66T6 (2T-9W) (D1) | 6001-8110 | 1799 | 2399 | 01R-03J-02J |
| EURO LOCKS | | 50001-52000 | 6156 | 200 | 01V |
| MASTER | | 470K000-479K999 | 9326 | 3002 | 01V |
| MASTER | | 480K000-489K999 | 9327 | 3002 | 01V |
| MASTER | | 490K000-499K999 | 9328 | 3002 | 01V |
| MASTER | | 500K000-509K999 | 9329 | 3002 | 01V |
| MASTER | | 510K000-509K999 | 9330 | 3002 | 01V |
| MASTER | | 520K000-529K999 | 9331 | 3002 | 01V |





FUTURA – FUTURA PRO NEWS WEB



| | | | | | |
|---------|--|-----------------|------|------|-----|
| MASTER | | 530K000-539K999 | 9332 | 3002 | 01V |
| MASTER | | 540K000-549K999 | 9333 | 3002 | 01V |
| MASTER | | 550K000-559K999 | 9334 | 3002 | 01V |
| MASTER | | 560K000-569K999 | 9335 | 3002 | 01V |
| MASTER | | 570K000-579K999 | 9336 | 3002 | 01V |
| MASTER | | 580K000-589K999 | 9337 | 3002 | 01V |
| MASTER | | 590K000-594K999 | 9338 | 3002 | 01V |
| MASTER | | 001-737 | 9339 | 4182 | 01V |
| MASTER | | 012345678 | 9340 | 4183 | 01V |
| BASTA | | 012345678 | 9341 | 4184 | 01V |
| MASTER | | 460K000-469K999 | 9342 | 3002 | 01V |
| CHICAGO | | 7K00-97 | 9343 | 1041 | 01V |
| MAZDA | | 0123 | 9344 | 4185 | 01V |
| MASTER | | 30H... 000-629 | 9345 | 526 | 01V |
| MASTER | | 32H... 169-620 | 9346 | 526 | 01V |
| MASTER | | 450K000-459K999 | 9347 | 3002 | 01V |
| BURG | | 19151-19350 | 9348 | 1643 | 01V |
| PUNDRA | | P001-600 | 9349 | 4018 | 01V |
| PUNDRA | | S01-59 | 9350 | 4019 | 01V |

Problems Solved



- Problem solved relating to cutting LEGALLAIS: SN 905



FUTURA – FUTURA PRO

NEWS WEB



December 2016

1_2016 FUTURA v. 2.21.0 - FUTURA PRO v. 3.1.0

NEW SYSTEM

| Lock Manufacturer | Lock System | Profile/Series | SN | Card | Clamp |
|-------------------|--|----------------------|------|------|-------------|
| ABUS | Abus Vela 1000 | VE10.....00001-30000 | 1770 | 4152 | 01R-01J-02J |
| ABUS | Abus Vela 2000 | VE20.....00001-30000 | 1775 | 4156 | 01R-01J-02J |
| AMIG | 10000 | - | 1789 | 4176 | 01R-01J-02J |
| BASI | Basi I6BM | B.....001-33938 | 1776 | 4157 | 01R-05J-06J |
| DOM | Dom IX6 SR S (prof. 250/251/252/253/254) | - | 1779 | 4159 | 01R-44J-02J |
| ERA | UCFTP (EA) | EA 400001-411502 | 1783 | 4173 | 01R-01J-02J |
| ERA | UCFTP (EB) | EB 400001-411502 | 1787 | 4174 | 01R-01J-02J |
| ERA | UCFTP (EC) | EC 400001-411502 | 1788 | 4175 | 01R-01J-02J |
| HDS | HDS WZ (6+5+6) | - | 1677 | 4073 | 01R-05J-06J |
| HDS | HDS WZ (7+6+7) | - | 1376 | 3562 | 01R-05J-06J |
| ISEO | R9 Plus | EDL 000001-350589 | 1790 | 868 | 01R-01J-02J |
| MOIA | MCHGYPC (7+4+3) | - | 1780 | 4170 | 01R-01J-02J |
| MOIA | MCHGYPC-M (7+4+3) | - | 1781 | 4171 | 01R-01J-02J |
| MOIA | MCGHYPC-C (6+3+3) | - | 1782 | 4172 | 01R-01J-02J |
| SECUREMME | Securemme EVOK64 (10 Pin) | - | 1777 | 4158 | 01R-13J-02J |
| SECUREMME | Securemme EVOK22 (11 Pin) | - | 1769 | 4150 | 01R-13J-02J |
| SECUREMME | Securemme EVOK64 (11 Pin) | - | 1778 | 4150 | 01R-13J-02J |
| YALE | Superior / Platinum (2T-4W) | - | 1791 | 4179 | 01R-01J-02J |
| YALE | Superior / Platinum (5+4) | - | 1792 | 4180 | 01R-35J-36J |
| YALE | Superior / Platinum (4+3) | - | 1793 | 4180 | 01R-35J-36J |
| YALE | Superior / Platinum (3+2) | - | 1794 | 4180 | 01R-35J-36J |
| SCHLAGE | AUB system | 1234567 | 9325 | 4151 | 01V |
| M&C | Matrix | 1A4001-6M8162 | 9323 | 4146 | 01V |
| RENAULT-DACIA | | 1234 | 9324 | 4145 | 01V |



BUG FIXED

| | |
|--|--|
| | <ul style="list-style-type: none"> - Solved a problem related to the cutting of DOM: SN 1231, 1244 and 1245 - Solved a problem related to the 05V clamp - Fixed data card data of SN 1402-1403 (FF-FACCHINETTI), 1632 (PREFER). - Codes updated for SN 1235 (ISEO) |
|--|--|

September 2016









1_2016 FUTURA v. 2.20.0

NEW FUNCTIONS



- The working mode of carter microswitch has been improved.


NEW SYSTEM

| | Lock Manufacturer | Lock System | Profile/Series | SN | Card | Clamp |
|---|---|--------------------------------|---------------------------------|------|------|-------------|
|  | KABA  | Kaba ExperT S 1.2b (K56B) | - | 575 | 1606 | 05R |
| | KABA  | Kaba ExperT S 1.2a (K56A) | - | 569 | 1607 | 05R |
| | KABA  | Kaba ExperT S 1.2a (K56A) | - | 1542 | 1607 | 05R |
| | KABA  | Kaba ExperT pluS S 1.0a (K83A) | - | 1425 | 3670 | 05R |
| | KABA  | Kaba ExperT pluS S 1.0b (K83B) | - | 1430 | 3675 | 05R |
| | M&T  | M&T Champions Pro CP4 (C6LJ2) | C6LJ2.....C6LJ200010-C6LJ2003G9 | 1738 | 3802 | 01R-01J-02J |
| | M&T  | M&T Champions Pro CP4 (C6LJK) | C6LJK.....C6LJK00010-C6LJK003FJ | 1739 | 3802 | 01R-01J-02J |
| | ABUS | |GN 8510-9509 | 9322 | 538 | 01V |

BUG FIXED



- Fixed data card data of SN 1688.
- New jaw "04V." for the cards (2658 V14-XY14-Y14) (3862 X6V) (3913 Vitess 1000) (3907 Vitess 2000) (3922 Vitess 4000)




July 2016

1_2016 FUTURA v. 2.19.0

NEW SYSTEM

| | Lock Manufacturer | Lock System | Profile/Series | SN | Card | Clamp |
|---|---|--------------------------------|----------------------|------|------|--------------------------------|
|  | EURO LOCKS | EU21P (2T-7/8W) | - | 1734 | 4133 | 01R-01J-02J |
| | FEDERAL | UCF3100 | C 400001-414382 | 1727 | 4128 | 01R-01J-02J |
| | KIA | Kia (2T-- 8W) | KD 0001-3000 | 1728 | 4129 | 01R-01J-02J |
| | KIA | Kia (2T-- 8W) | D 0001-3000 | 1729 | 4129 | 01R-01J-02J |
| | TITAN | I6 (6P) | - | 1725 | 4126 | 01R-05J-06J |
| | TONYON | TY340-STZ52-STB24-KB23 (4T-5W) | B 80001-81560 | 1672 | 4068 | 01R-01J-02J |
| | TRELOCK  | InX M2 (4T-4W) | M.....200001-210000 | 1722 | 4122 | 01R-01J-02J |
| | TRELOCK  | InX ML2 (4T-4W) | ML.....200001-210000 | 1723 | 4122 | 01R-01J-02J |
| | WITTE | Volvo XC90 (2T - 8W) |A001-F099 | 1726 | 4127 | 01R-01J-02J+A34 01R-19J-02J |
| | YARDENI | Yardeni 6 Master-No cut tip | - | 1707 | 4107 | 01R-01J-02J |
| | YARDENI | Yardeni 6 Regular-Cut tip | - | 1708 | 4108 | 01R-01J-02J |
| | YARDENI | Yardeni 6 Master-Cut tip | - | 1709 | 4109 | 01R-01J-02J |
| | ABUS | Abus 83 |0001-8900 | 9317 | 3908 | 01V |
| | ABUS | Abus U72 | U72.....1-1043 | 9318 | 729 | 01V |
| | ABUS | Abus U74 | U74.....1-1043 | 9319 | 729 | 01V |
| | ESETY  | Esety Omega | 123456789 | 9315 | 4123 | 01V+B14 |
| | PFAFFENHAIN | S5+ |9876543210XYZ | 9316 | 4124 | 01V |
| | RONIS | |4001-5000 | 9320 | 206 | 01V |

BUG FIXED

| | |
|---|---|
|  | <ul style="list-style-type: none"> - Fixed data card data of SN 750 (YARDENI), 1419-3145-3318 (EVVA) - Codes updated for SN 921-766 (HUF) - The problem regarding cutting the Esety Omega system (data card 1532 replaced by data card 4123) has been solved. - Solved a problem related to the cutting of FORD: SN 694, 1165 and 1513. - Solved a minor Software problem. |
|---|---|



FUTURA – FUTURA PRO

NEWS WEB



June 2016

1_2016 FUTURA v. 2.18.0

NEW SYSTEM

| | Lock Manufacturer | Lock System | Profile/Series | SN | Card | Clamp |
|-----|---------------------|----------------------|----------------|------|------|-------------|
| | GOAL | Goal GP (6+6+6) | - | 1698 | 4089 | 01R-01J-02J |
| | GOAL | Goal GP (7+7+7) | - | 1699 | 4090 | 01R-01J-02J |
| | OXLOC | Oxloc O9,2 | - | 1700 | 4093 | 01R-29-30J |
| | OXLOC | Oxloc O9,3 | - | 1701 | 4094 | 01R-29-30J |
| | OXLOC | Oxloc O8,2 (4P) | - | 1702 | 4095 | 01R-24-25J |
| | OXLOC | Oxloc O8,3 (4P) | - | 1703 | 4096 | 01R-24-25J |
| | VOLKSWAGEN SKODA | HU162T (4T-8W) | - | 1704 | 4100 | 01R-56J-57J |
| | OXLOC | Oxloc O8,2 | 9876543210XYZ | 9297 | 4080 | 01V |
| | OXLOC | Oxloc O8,3 | 9876543210XYZ | 9296 | 4079 | 01V |
| | HUDSON | | T001-050 | 9303 | 1039 | 01V |
| | HUDSON | | G401-500 | 9304 | 1039 | 01V |
| | HUDSON | | H0001-1000 | 9305 | 1039 | 01V |
| | HUDSON | | AM0001-1000 | 9306 | 1039 | 01V |
| | HUDSON | | C007-1000 | 9307 | 1039 | 01V |
| | HUDSON | | PMI100-149 | 9308 | 1039 | 01V |
| | HUDSON | | HL251-1495 | 9309 | 1039 | 01V |
| | MG (MONTI) | Chiave normale 4P | 1234567 | 9310 | 4101 | 01V |
| | MG (MONTI) | Chiave normale 5P | 1234567 | 9311 | 4101 | 01V |
| | MG (MONTI) | Chiave ridotta 5P | 12345 | 9312 | 4102 | 01V |
| | MG (MONTI) | Chiave Simmetrica 6P | 1234567 | 9313 | 4103 | 01V |
| ESP | | | T0-1000 | 9314 | 561 | 01V |

BUG FIXED



- Solved a problem related to the decoding of ABUS Bravus e OXLOC:
SN 1417, 1418, 1419, 1420, 1536, 1646, 1650, 1654, 1647, 1700, 1701.



FUTURA – FUTURA PRO NEWS WEB



May 2016

1_2016 FUTURA v. 2.17.0

NEW SYSTEM

| Lock Manufacturer | Lock System | Profile/Series | SN | Card | Clamp |
|-------------------|--|----------------------------|------|------|-------------|
| CISA | Astral Tekno CA | (XN027510) 000008U-194155U | 1688 | 3226 | 01R-05J-06J |
| CISA | Astral Tekno CE P-S | (XN027710) 000001P-012070S | 1689 | 3226 | 01R-05J-06J |
| GOAL | Goal V-18 Master NEW (6+6+6) | - | 1698 | 4089 | 01R-01J-02J |
| GOAL | Goal V-18 Master NEW (7+7+7) | - | 1699 | 4090 | 01R-01J-02J |
| ISEO | R7 Extra Cantiere (Cantiere) | ECE 000001-039242 | 1692 | 868 | 01R-01J-02J |
| ISEO | R7 Extra Cantiere (Padronale) | ECE 100001-139242 | 1693 | 868 | 01R-01J-02J |
| ISEO | R7 Extra Ricifrabile (Cantiere) | EGG 000001-009744 | 1694 | 868 | 01R-01J-02J |
| ISEO | R7 Extra Ricifrabile (Padronale 1) | EGG 100001-109744 | 1695 | 868 | 01R-01J-02J |
| ISEO | Iseo R7 Extra Ricifrabile (Padronale 2) | EGG 200001-209744 | 1696 | 868 | 01R-01J-02J |
| ISEO - DORMA | DEC261 SKG | EBM 000001-171276 | 1697 | 2176 | 01R-01J-02J |
| MOTTURA | Champions Pro CP4-CM7 | - | 1679 | 3802 | 01R-01J-02J |
| MOTTURA | Mottura Champions Pro CP4 Armo-Riarmo | - | 1680 | 3803 | 01R-01J-02J |
| MOTTURA | Mottura Champions Pro CP4 Matic | - | 1681 | 3804 | 01R-01J-02J |
| MOTTURA | Mottura Champions Pro CP4 Riarmo Att-Dis | - | 1682 | 3805 | 01R-01J-02J |
| MOTTURA | MOTTURA Champions C28 Plus | - | 1683 | 4075 | 01R-01J-02J |
| MOTTURA | MOTTURA Champions C39 | - | 1684 | 4076 | 01R-01J-02J |
| MOTTURA | Mottura Champions C43 Plus | - | 1685 | 4078 | 01R-01J-02J |
| ASSA | Profile AS | AS0123456789 | 9285 | 345 | 01V |
| ASSA | Profile PS | PF0123456789 | 9286 | 345 | 01V |
| ASSA | Profile US | US0123456789 | 9287 | 345 | 01V |
| ASSA | Profile HN | HN0123456789 | 9288 | 345 | 01V |
| ASSA | Profile NK | NK0123456789 | 9289 | 345 | 01V |
| ASSA | Profile GM | GM0123456789 | 9290 | 345 | 01V |
| ASSA | Profile PM | PM0123456789 | 9291 | 345 | 01V |
| ASSA | Profile PK | PK0123456789 | 9292 | 345 | 01V |
| ASSA | Profile SH | SH0123456789 | 9293 | 345 | 01V |
| BURG | | D1001-3187 | 9294 | 1643 | 01V |
| DOM | Dom Plura | 01234567 | 9295 | 3707 | 01V |
| EURO LOCKS | | 2801-2900 | 9298 | 4081 | 01V |
| L&F | | W1001-3000 | 9299 | 4082 | 01V |
| NEMEF | | NF21234567890 | 9300 | 3481 | 01V |
| NEMEF | | NF11234567890 | 9301 | 3481 | 01V |
| ANKER | | FK1234567 | 9302 | 2888 | 01V |

BUG FIXED



FUTURA – FUTURA PRO

NEWS WEB



- Problem solved regarding copying a key with measurements read after decoding (Standard Keys system only).
- CISA code search for series:SN 1273.
- Solved a problem related to the cutting of "Vachette Radial VAC91" SN 76.
- Solved a problem related to the cutting of "Kia - Hyundai (4T-6W)" SN 1001, 1310.
- Solved a problem related to the cutting of GOAL: SN 547, 1182.
- Solved a problem related to the decoding of SN 1538 "RB-LOCKS Lockxis".
- Problem solved regarding gauging/cutting/decoding for MAGNUM and M&C systems: SN 1540, 1523, 1524, 1525, 1526, 1527, 1528.
- Decodes for SN 1550.
- Solved a minor Software problem.

February 2016

1_2016 FUTURA v. 2.16.0

NEW SYSTEM

| Lock Manufacturer | Lock System | Profile/Series | SN | Card | Clamp |
|-------------------|-----------------------------|----------------------|------|------|---------------|
| ABUS | EC660 | S00001A-S30000A | 1668 | 4063 | 01R-05J-06J |
| APECS | Premier CD (7+7) | - | 1665 | 4056 | 01R-01J-02J |
| BKS | WS50 - (Profile NW) | - | 743 | 2228 | 01R-039J-038J |
| DOM | IXGamma (Prf.153) (5+3+7) | - | 1231 | 3189 | 01R-46J-45J |
| DOM | IXGamma (Prf.155) (5+3+7) | - | 1245 | 3191 | 01R-46J-45J |
| HONDA | Honda Motorcycle (4T-6W) | A...101-800 | 1655 | 4036 | 01R-01J-02J |
| HONDA | Honda Motorcycle (4T-6W) | B...101-800 | 1670 | 4036 | 01R-01J-02J |
| GOAL | D-9 (3+3+3) | - | 1669 | 4064 | 01R-01J-02J |
| M&T | New Power (7W-2P) |2000002-2353872 | 1671 | 4067 | 01R-01J-02J |
| STS | ST6 (6+5+11) | - | 1131 | 2986 | 01R-58J-61J |
| STS | ST8 | - | 1151 | 3006 | 01R-58J-61J |
| BOMMER | | 1001-2000 | 9166 | 1039 | 01V |
| ABUS | T12 | TD 00001-02000 | 9266 | 3908 | 01V |
| ABUS | T10 | TE 00001-02000 | 9267 | 3908 | 01V |
| CHICAGO | | 1E01-3E00 | 9268 | 1041 | 01V |
| CHICAGO | | 1EY01-2EY00 | 9269 | 1041 | 01V |
| CHICAGO | | 1GW1-3GW0 | 9270 | 1041 | 01V |
| MEDECO | KeyMark X4 | 123456789 | 9271 | 4059 | 01V |
| CHICAGO | | DLP 0001-1742 | 9272 | 561 | 01V |
| SENTRY | | SB 1-9 | 9273 | 4061 | 01V |
| TRIO-VING | R-key | 123456789 | 9274 | 4062 | 01V |
| ARCO | | LG 3001-5999 | 9275 | 1040 | 01V |
| ARCO | | TG 3001-5999 | 9276 | 1040 | 01V |
| ABUS | Abus V65 | V65 1-331 | 9277 | 730 | 01V |
| ABUS | Abus V63 | V63 1-331 | 9278 | 730 | 01V |
| KABA | Kaba Peaks A2 (0.150") (7P) | 123456789 | 9279 | 1620 | 01V |
| EURO LOCKS | | T 2001-2200 | 9280 | 298 | 01V |
| ERA | | 123456789 | 9281 | 2427 | 01V |
| EURO LOCKS | | E 1-200 | 9282 | 298 | 01V |
| EURO LOCKS | | N1-200R | 9283 | 298 | 01V |
| EBERHARD | | U201-300 | 9284 | 4066 | 01V |

BUG FIXED



FUTURA – FUTURA PRO

NEWS WEB



- Fixed data card data of SN 272-1475 (AGENT), 1267 (ALPHA), 547-731-884-1182 (GOAL), 1164-1268 (NAGASAWA), 613-1561 (SHOWA), 1065-1358 (TOSTEM), 477-638-639-1135-1471-1472-1476-1477 (WEST)

January 2016

1_2016 FUTURA v. 2.15.0

NEW SYSTEM

| Lock Manufacturer | Lock System | Profile/Series | SN | Card | Clamp |
|-------------------|------------------------|-------------------|------|------|-------------|
| Nissan | Emergency Key (5+5+4) | - | 1658 | 4045 | 01R-01J-02J |
| Wilka | P2 | - | 1660 | 4046 | 01R-48J-47J |
| Wilka | PR300Q | - | 1661 | 4048 | 01R-48J-47J |
| Wilka | P3Q | - | 1662 | 4049 | 01R-48J-47J |
| Yale | 2000 Plus Series (5+5) | ABC10001-AEH26822 | 1663 | 4050 | 01R-03J-02J |
| MINDA-HUF | | 3001-3858 | 9222 | 4022 | 01V |
| MINDA-HUF | | 1001-2252 | 9223 | 4037 | 01V |
| MINDA-HUF | | 2001-3170 | 9224 | 4038 | 01V |
| MINDA-HUF | | 1001-2174 | 9225 | 4039 | 01V |
| BURG | | 1234 | 9226 | 4040 | 01V |
| FORD | Market TAIWAN | 12345 | 9227 | 4041 | 01V |
| FEDERAL | YCF 35-35 | 6Y200001-298246 | 9228 | 4042 | 01V |
| CHICAGO | | 5AH1-7AH5 | 9229 | 1041 | 01V |
| ABUS | Abus V63 | X631-331 | 9230 | 730 | 01V |
| ABUS | Abus Z74 | Z741-1043 | 9231 | 729 | 01V |
| SOFICLEF | 50/40 | 123456789 | 9232 | 4043 | 01V |
| ILLINOIS | | SD101-110 | 9233 | 4015 | 01V |
| ILLINOIS | | J200-703 | 9234 | 4015 | 01V |
| JOFCO | | J401-440 | 9235 | 1054 | 01V |
| NATIONAL | | RD001-615 | 9236 | 1054 | 01V |
| NATIONAL | | PA001-634 | 9237 | 1054 | 01V |
| NATIONAL | | PG001-575 | 9238 | 1054 | 01V |
| MAZDA | Market TAIWAN | 1234 | 9239 | 4044 | 01V |
| NATIONAL | | C001-175B | 9240 | 1054 | 01V |
| NATIONAL | | GF201-400 | 9241 | 1054 | 01V |
| GUARD | Profile G17 | 17T1500000-99999 | 9242 | 666 | 01V |
| NATIONAL | | D001-633AR | 9243 | 1054 | 01V |
| NATIONAL | | B001-633A | 9244 | 1054 | 01V |
| NATIONAL | | C001-633A | 9245 | 1054 | 01V |
| NATIONAL | | D001-633A | 9246 | 1054 | 01V |
| NATIONAL | | FF001-574 | 9247 | 1054 | 01V |
| CHICAGO | | 5D66-6D30 | 9248 | 1041 | 01V |
| CHICAGO | | 1X01-3X00 | 9249 | 1041 | 01V |
| CHICAGO | | 1X1-7X6 | 9250 | 1041 | 01V |
| CHICAGO | | 1MC1-6MC5 | 9251 | 1041 | 01V |





FUTURA – FUTURA PRO NEWS WEB



| | | | | | |
|-----------|--|---------------|------|------|-----|
| CHICAGO | | 1BM01-2BM00 | 9252 | 1041 | 01V |
| CHICAGO | | 1MS1-3MS1 | 9253 | 1041 | 01V |
| CHICAGO | | 1RR01-2RR00 | 9254 | 1041 | 01V |
| CHICAGO | | 1L001-450 | 9255 | 1041 | 01V |
| CHICAGO | | 2Y01-9Y99 | 9256 | 1041 | 01V |
| CHICAGO | | 2HM01-5HM00 | 9257 | 1041 | 01V |
| CHICAGO | | 1B01-3B50 | 9258 | 1041 | 01V |
| CHICAGO | | 2K01-2K99 | 9259 | 1041 | 01V |
| CHICAGO | | 1N01-9N99 | 9260 | 1041 | 01V |
| CHICAGO | | 5D01-5D65 | 9261 | 1041 | 01V |
| CHICAGO | | IS01-99 | 9262 | 1041 | 01V |
| PUNDRA | | B0001-1092 | 9263 | 4018 | 01V |
| PUNDRA | | K0001-1092 | 9264 | 4018 | 01V |
| HUWIL | | 14101-16020IG | 9265 | 539 | 01V |
| CRAFTSMAN | | Z8001-9000 | 9205 | 4017 | 01V |

BUG FIXED



- Standard decoding refreshed for KESO: SN 57-273-673-1158-1298-1299-1576-1656-1657. systems



FUTURA – FUTURA PRO

NEWS WEB



December 2015

1_2015 FUTURA v. 2.14.0

NEW SYSTEM

| Lock Manufacturer | Lock System | Profile/Series | SN | Card | Clamp |
|-------------------|------------------------|-----------------|------|------|-------------|
| Abus | Bravus 1000 (Tip stop) | - | 1646 | 4010 | 01R-29J-30J |
| Abus | Bravus 2000 (Tip stop) | - | 1650 | 4023 | 01R-29J-30J |
| Abus | Bravus 4000 (Tip stop) | - | 1654 | 4024 | 01R-29J-30J |
| Fort | CH10T (7P) | X01001-08704 | 1648 | 4020 | 02R |
| Kale | 164 DBNE (5+5) | - | 1643 | 2244 | 01R-01J-02J |
| Oxloc | O9 | - | 1647 | 4014 | 01R-29J-30J |
| Pacri | Pacri (5+5) | - | 1642 | 3981 | 01R-01J-02J |
| Anderson Hickey | | NM01-NM128 | 9190 | 4009 | 01V |
| Bauer | | BR500-BR999 | 9191 | 1069 | 01V |
| Chicago | | H1001-3000 | 9192 | 1041 | 01V |
| Chicago | | H2001-H2576 | 9204 | 4016 | 01V |
| Corbin | | HB1-HB700 | 9193 | 1367 | 01V |
| Craftsman | | LL151W-LL175W | 9217 | 1288 | 01V |
| Craftsman | | LL1W-LL225W | 9108 | 1268 | 01V |
| Craftsman | | 3001-3050 | 9218 | 1268 | 01V |
| Craftsman | | 135 | 9205 | 4017 | 01V |
| Eagle | | 76P1-76P240 | 9194 | 1045 | 01V |
| Eagle | | C1-C12 | 9195 | 1046 | 01V |
| F.I.C. | | HF301-HF351 | 9201 | 4013 | 01V |
| Fastec | | EF301-EF351 | 9199 | 4013 | 01V |
| Fastec | | 301-351 | 9198 | 4013 | 01V |
| Fastec | | CF301-CF351 | 9200 | 4013 | 01V |
| Fort | | X01001-X08704 | 1648 | 4020 | 01V |
| Haworth | | HW001-HW300 | 9197 | 4011 | 01V |
| Ilco | | C26-C50 | 9196 | 1049 | 01V |
| Illinois | | H200-H483 | 9202 | 4015 | 01V |
| National | | HBH1250-HBH1749 | 9179 | 4030 | 01V |
| National | | AM1-AM950 | 9189 | 1043 | 01V |
| National | | 1N-400N | 9187 | 1043 | 01V |
| National | | D100-D7000 | 9186 | 1043 | 01V |
| National | | 1-970 | 9180 | 1043 | 01V |
| National | | RN601-RN791 | 9188 | 1043 | 01V |
| Pundra | | S1-S1092 | 9206 | 4018 | 01V |
| Sentry | | 3A2-3K2 | 9207 | 4019 | 01V |
| Taylor | | B101-B112 | 9135 | 1062 | 01V |
| Taylor | | F10-F21 | 9136 | 1063 | 01V |
| US Lock | | 123456789 | 9203 | 4012 | 01V |
| Subaru | | 32000--39867 | 8816 | 3646 | 01V |
| Subaru | | 50000-69999 | 9208 | 3646 | 01V |
| Bommer | | 0123456 | 9166 | 1039 | 01V |
| Honda | | 000-1013 | 8939 | 3806 | 01V |
| Miwa | Market Jap side A | 123456 | 9167 | 3970 | 01V |
| Miwa | Market Jap.side A | 123456 | 9168 | 3972 | 01V |
| Miwa | Market Japan. | 1234 | 9171 | 3975 | 01V |
| Mitsubishi | Market Jap. stop 3 | 8100-9113 | 9169 | 3973 | 01V |
| Squire&Sons | ATL4 & ATL5 | 123456789 | 9172 | 3976 | 01V |
| Squire&Sons | KB | 123456789 | 9173 | 3979 | 01V |
| Eurolocks | | 12345 | 9174 | 3982 | 01V |





FUTURA – FUTURA PRO NEWS WEB



| | | | | | | |
|----------|------------|--------------------------------|--------------|------|------|-----|
| | Toyota | Chinese market (reversed cuts) | 1234 | 9176 | 3985 | 01V |
| | Ronis | | 12345 | 9175 | 3984 | 01V |
| | | | | | | |
| | Minda-Huf | | A1001-3500 | 9177 | 3987 | 01V |
| | Honda | | R/S0001-1074 | 9178 | 4003 | 01V |
| | Ifam | E-50-60-70 & M-50-60 | 123456 | 9214 | 4029 | 01V |
| | Ifam | | 123 | 9211 | 4028 | 01V |
| | Ifam | | 123456 | 9212 | 4027 | 01V |
| | Ifam | | 123456 | 9213 | 4027 | 01V |
| | Ifam | E-30 & M-30 | | 9210 | 4025 | 01V |
| | Ifam | E-40 & M-40 | | 9215 | 4025 | 01V |
| | Hyundai | Chinese market | M0001-2500 | 9209 | 3419 | 01V |
| | Hyundai | KIA (DEPTHS 1-5) | V0001-2500 | 9216 | 3419 | 01V |
| | Oxloc | Oxloc O8 | | 9185 | 4007 | 01V |
| | Oxloc | Oxloc O7 | | 9181 | 4006 | 01V |
| | Oxloc | Oxloc O7 | | 9182 | 4006 | 01V |
| | Oxloc | Oxloc O7 | | 9183 | 4006 | 01V |
| | Oxloc | Oxloc O7 | | 9184 | 4006 | 01V |
| | Craftsman | | LL151-175W | 9217 | 1268 | 01V |
| | Winkhaus | W-Profile | | 9219 | 4033 | 01V |
| Winkhaus | XL-Profile | | 9220 | 4034 | 01V | |

BUG FIXED



- Solved a problem related to the cutting of DOM: SN 861-862-1027-1244.
- Solved some problem about “**User code table import**”.
- Solved a problem related to the decoding of SN 1269 “Sanwa (2+1+2+1+1+1P)”.



FUTURA – FUTURA PRO NEWS WEB



November 2015

1_2015 FUTURA v. 2.13.3

BUG FIXED



- Solved a minor Software problem.

November 2015

1_2015 FUTURA v. 2.13.2

BUG FIXED



- Solved a problem related to the decoding of SN 1348 “BMW BW9EHP (4T-4W)”.
- Solved a problem related to the cutting of “Bmw (2T-8W)” SN 1572 .

November 2015

1_2015 FUTURA v. 2.13.1

BUG FIXED



- Standard decoding refreshed for DOM systems.

October 2015

1_2015 FUTURA v. 2.13.0

REMEMBER TO



- Remember to update the Silca.apk and SilcaKeyboard.apk after installing the Software update (see the on board Instructions Manual - Ch 7.3 APP UPDATE (APK))
- With the new **MySilca apk** from Silca, you can keep the entire expertise and experience of your Key Partner at hand anytime anywhere.

NEW SYSTEM



| Lock Manufacturer | Lock System | Profile/Series | SN | Card | Clamp |
|-------------------|------------------------------|----------------|------|------|-------------|
| Corbin | Corbin TWO (6P) | - | 1615 | 1500 | 01R-01J-02J |
| Tokai Rika | Subaru Emergency Key (2T-4W) | - | 1635 | 3964 | 01R-01J-02J |
| Union | Union EG | 123456 | 9165 | 4593 | 01V |

NEW FUNCTIONS



- As an alternative to a tablet ↔ machine Wi-Fi connection, a USB connection can be used with the cable provided. To activate this connection enable the Android **“Tethering USB”** function from the **Settings menu on the Android tablet** (see User’s Manual version 7).
- The Futura machine can be registered through any browser, at the web address <https://www.silcawebsw.biz/futura/reg/index.html>
- Silca periodically distributes Software and Data updates for FUTURA. A message will occasionally notify you to check for new updates using one of the connection modes available (see menu Options -> Updates).
- Decodes for SN 1228 and 1229

BUG FIXED



- Standard decoding refreshed for KESO systems: SN 20-21-105-807
- Problem solved relating to saving the “Wi-Fi channel” setting (if different from default) after a software update
- Solved a problem related to the cutting algorithm of “Standard Key” (method “M_LASER_FLAT_LFD”).

September 2015

1_2015 FUTURA v. 2.12.0

REMEMBER TO



- Remember to update the Silca.apk and SilcaKeyboard.apk after installing the Software update (see the on board Instructions Manual – Ch 7.3 APP UPDATE (APK))
- With the new **MySilca apk** from Silca, you can keep the entire expertise and experience of your Key Partner at hand anytime anywhere.

NEW SYSTEM



| Lock Manufacturer | Lock System | Profile/Series | SN | Card | Clamp |
|-------------------|--------------------------|----------------|------|------|-------------|
| Avocet | Avocet Pioneer plus (6P) | - | 1612 | 3936 | 01R-01J-02J |
| Prefer | Prefer S211 (5+5+4) | - | 1633 | 3942 | 01R-01J-02J |
| Prefer | Prefer UL20 (6P) | - | 1463 | 3715 | 01R-01J-02J |
| Prefer | Prefer W551 (4+4+3) | - | 1632 | 3941 | 01R-01J-02J |
| Trelock | Trelock RS430 (4T-7W) | H400000-404999 | 1556 | 3865 | 01R-01J-02J |
| Ankerslot | | EE112-545 | 9159 | 3431 | 01V |
| Burg | | 18001-18246 | 9162 | 1643 | 01V |
| Euro Locks | | H1001-3000 | 9161 | 723 | 01V |
| Euro Locks | | G1001-3000 | 9160 | 723 | 01V |
| Euro Locks | | F4001-5000 | 9163 | 1435 | 01V |
| JPM | | 12345678 | 9157 | 3935 | 01V |
| Marutti Suzuki | | IP5001-6001 | 9158 | 3937 | 01V |

NEW FUNCTIONS



- New **“Transponder Guide”** function accessible from the Search menu. This function contains all the transponder key copying solutions provided by Silca.
- Use of Silca Remote Service (SRS) Version 1.0.38.5** to register your Futura machine on the Silca server.
- Use of Silca Remote Service (SRS) Version 1.0.38.5** to update your Futura machine in one of the ways described below:
 - Quick update** (saves time as only the files needed for updating are downloaded onto a blank FAT32 format USB PEN)
 - Total update** (all the files related to updating are downloaded onto a blank FAT32 format USB PEN)

** The program can be downloaded from the Silca website www.silca.biz; select the Products menu -> Silca Key Programs -> SKP Forms -> Silca Remote Service

BUG FIXED



- Solved a problem related to the decoding of SN 1285 Euro Locks (2T-5W).
- Solved a problem related to the cutting of HONDA: SN 582-619-805-806
- Solved a problem related to the cutting of KESO: SN 20-273-1299

July 2015

1_2015 FUTURA v. 2.11.3

NEW SYSTEM



| Lock Manufacturer | Lock System | Profile/Series | SN | Card | Clamp |
|-------------------|----------------------|--------------------------|------|------|-------------|
| Cisa | Cisa AP3 DA/CA/CE | XN.0161.10 | 734 | 1600 | 01R-05J-06J |
| Cisa | Cisa Asix Pro (6P) | 00012-38832 DC | 1607 | 1575 | 01R-05J-06J |
| Cisa | C3000 | (XN029010) 000001-238428 | 9156 | 3928 | 01V |
| Cisa | | AT..... 00001-03628 | 7774 | 5590 | 01V |
| Cisa | C2000 5P 0,44 | AR..... 00001-20728 | 8490 | 2183 | 01V |
| Cisa | C2000 5P 0,65 | AR..... 00001-20728 | 8488 | 2182 | 01V |

July 2015

1_2015 FUTURA v. 2.11.2

BUG FIXED



- Solved a problem related to the cutting algorithm of (Standard Key)

July 2015

1_2015 FUTURA v. 2.11.1

BUG FIXED



- Fixed a problem related to cutting PFAFFENHAIN (Vitess-Zolit)

June 2015

1_2015 FUTURA v. 2.11.0

REMEMBER TO



- **Remember** to update the Silca.apk and SilcaKeyboard.apk after installing the Software update (see the on board Instructions Manual – Ch APP UPDATE (APK)).
- With the new **MySilca apk** from Silca, you can keep the entire expertise and experience of your Key Partner at hand anytime anywhere.

NEW SYSTEM

| Lock Manufacturer | Lock System | Profile/Series | SN | Card | Clamp |
|-------------------|------------------------------|--------------------|------|------|-------------|
| Yale | Yale 1000 Series (6P) |40001-53260 | 1592 | 3448 | 01R-13J-02J |
| Iseo | Iseo R7 (5+6) | EDL000001-350589 | 916 | 2176 | 01R-01J-02J |
| Pfaffenhain | Pfaffenhain Vitess 2000 (4P) | - | 1598 | 3914 | 01R-28J-25J |
| Pfaffenhain | Pfaffenhain Vitess 4000 (4P) | - | 1599 | 3918 | 01R-28J-25J |
| Pfaffenhain | Pfaffenhain Zolit 2000 (4P) | - | 1600 | 3919 | 01R-24J-25J |
| Pfaffenhain | Pfaffenhain Zolit 4000 (4P) | - | 1601 | 3920 | 01R-24J-25J |
| Brisant | Brisant ULTION (5+6) | U11000001-11291140 | 1605 | 3925 | 01R-01J-02J |
| Hyundai | Hyundai (4T - 6W) | LK....0001-2500 | 1580 | 2372 | 01R-01J-02J |
| Hyundai | Hyundai (4T - 6W) | M....0001-2500 | 1581 | 2372 | 01R-01J-02J |
| Kia | Kia (4T - 6W) | E....0001-2500 | 1582 | 2372 | 01R-01J-02J |
| Hyundai | Hyundai (4T - 6W) | HK....0001-2500 | 1583 | 2372 | 01R-01J-02J |
| Kia | Kia - (4T-6W) | KG....0001-2500 | 1584 | 2372 | 01R-01J-02J |
| Kia | Kia (4T - 6W) | V....0001-2500 | 1585 | 2372 | 01R-01J-02J |
| Hyundai/Kia | Kia-Hyundai (4T-6W) | K....0001-2500 | 1586 | 2372 | 01R-01J-02J |
| Hyundai | Hyundai (2T-8W) |1001-3500 | 1587 | 3336 | 01R-01J-02J |
| Hyundai | Hyundai (2T-8W) | X....1001-3500 | 1588 | 3336 | 01R-01J-02J |
| Kia | Kia (4T - 5W) | KU....0001-2608 | 1589 | 3742 | 01R-01J-02J |
| Hyundai | Hyundai (4T - 5W) | B....0001-2608 | 1590 | 3742 | 01R-01J-02J |
| Kia | Kia (2T-8W) | UM....1001-3500 | 1591 | 3618 | 01R-01J-02J |
| Hyundai | Hyundai (4T - 5W) | X....0001-2254 | 1596 | 3909 | 01R-01J-02J |
| Hyundai | Hyundai Card Key (2T - 5W) | X....0001-2254 | 1597 | 3911 | 01R-01J-02J |
| Zadi/Giussani/Ft | Giussani (2T-8W) | - | 1603 | 3924 | 01R-01J-02J |
| Huf | Mercedes HU64P (2T-10W) | - | 1602 | 3921 | 01R-01J-04J |
| Dom | DORMA RS-8 SINGLE CODED | UK 15000-23971 | 9154 | 2990 | 05V |
| Dom | DORMA RS-8 SINGLE CODED | UK 01001-14047 | 9155 | 2990 | 05V |
| Abus | E50 | 12345 | 9147 | 3908 | 01V |
| Pfaffenhain | Vitess 2000 | 9876543210XYZ | 9146 | 3907 | 04V |
| Pfaffenhain | Zolit 1000 | 9876543210XYZ | 9148 | 3910 | 01V |
| Pfaffenhain | Vitess 1000 | 9876543210XYZ | 9149 | 3913 | 04V |
| Pfaffenhain | Zolit 2000 | 9876543210 | 9150 | 3915 | 01V |
| Pfaffenhain | Zolit 4000 | 9876543210XYZ | 9151 | 3916 | 01V |
| Pfaffenhain | Vitess 4000 | 9876543210XYZ | 9153 | 3922 | 04V |
| Federal | Avocet ATK | 012345678 | 9152 | 3917 | 01V |



FUTURA – FUTURA PRO NEWS WEB



NEW FUNCTION



- Decodes for SN 823, 850 and 860 (Renault, Peugeot, Citroen and Toyota car keys)
- SMART decoding for KESO 1000-2000-4000-CASA systems. The new decoding recognises the real key cuts and ignores "PRE-CUTS" (cuts by manufacturer).

BUG FIXED



- Fixed a problem related to cutting DOM: SN 861-862-1027-1244.

May 2015


1_2015 FUTURA v. 2.10.0







REMEMBER TO



- **Remember** to update the Silca.apk and SilcaKeyboard.apk after installing the Software update (see the on board Instructions Manual – Ch APP UPDATE (APK)).
- With the new **MySilca apk** from Silca, you can keep the entire expertise and experience of your Key Partner at hand anytime anywhere.

NEW SYSTEM



| Lock Manufacturer | Lock System | Profile/Series | SN | Card | Clamp |
|--|--|----------------|------|------|-------------|
| Honda | Honda Emergency Key (2T-6W) | - | 3896 | 1575 | 01R-52J-53J |
| Spider | SPIDER (5+5+5) | - | 165 | 876 | 01R-01J-02J |
| Chairo | CHAIRO 118 (6P) | - | 1570 | 3889 | 01R-01J-02J |
| Duro | DURO 280/50 (6+6) | - | 1571 | 3892 | 01R-01J-02J |
| Lince | Lince XA, XB, | - | 1834 | 683 | 01R-24J-25J |
| Keso  | Keso Casa | - | 1576 | 3898 | 01R-01J-02J |
| Huf | Bmw (2T-8W) | - | 1572 | 3893 | 01R-01J-02J |
| Dom  | Dom IXDAS (Prof.138) (5P) | - | 861 | 2457 | 01R-01J-02J |
| Dom  | Dom IXDAS (Prof.138) (5+6+6) | - | 862 | 2458 | 01R-01J-02J |
| Dom  | Dom IXDAS (Prof.138) (Precoded key only) | - | 1027 | 2744 | 01R-01J-02J |
| Dom  | Dom IXGamma (Prf.154) (5+3+7) | - | 1244 | 3190 | 01R-46J-45J |
| Mauer | Mauer_NW4 (5P - 2T-5W) | -000101-651630 | 1264 | 3897 | 01R-54J-55J |
| Ces  | Ces WSM NEW (5+5+6) | - | 1495 | 3767 | 01R-01J-02J |
| Chicago | | FR301-800 | 9102 | 561 | 01V |
| National Rockford | | T1-675 | 9103 | 1043 | 01V |
| Sargent | DG1 | 123456 | 9104 | 3890 | 01V |
| Sargent | DG2-DG3 | 123456 | 9105 | 3891 | 01V |
| Piaggio Cycles | | 1001-3532 | 9106 | 258 | 01V |
| Avocet | ATK | 012345678 | 9107 | 3899 | 01V |
| Weslock | | 01234567 | 9145 | 3900 | 01V |



FUTURA – FUTURA PRO NEWS WEB



NEW FUNCTION



- New “User code table import” function accessible from “Settings”=> “User series”. This new function allows users to import a code table in the XML-Keso or csv format to create a new user series
- New “Change dimensions” function. For all edge simmetrical keys, it is now possible to view dimensions in two ways: Depths referred to the middle of the key or depths referred to the edge of the key
- Improved the “Queue of jobs.” function

BUG FIXED



- Solved some problems related to machine software updating via tablet. For more details refer to the user manual (version 5.0 section 6.2.3)

May 2014

1_2015 FUTURA v. 2.9.1

BUG FIXED



- Solved the problem of password enabling for some data cards (Futura NA)

March 2015

1_2014 FUTURA v. 2.9.0

REMEMBER TO



- **Remember** to update the Silca.apk and SilcaKeyboard.apk after installing the Software update (see the on board Instructions Manual – Ch 6.2 APP UPDATE (APK)).
- With the new **MySilca apk** from Silca, you can keep the entire expertise and experience of your Key Partner at hand anytime anywhere.

NEW SYSTEM

Data update with new main series.



- Agent BJ-1(5+5+5)
- BKS WS42 - WS50 MK
- Bunka (Market Japanese)
- Ces UDM (4P) - WSM NEW (5+5+6)
- Dom (Dom RS8)
- Dom IX5 DAS (pf.038/101)
- Dom IX6 SR E (prof 232)
- Dom IX6 SR E (prof 233)
- Dom IX6KG (Prof.102) (5+5+5)
- Dom IX6SR E (prof. 230)
- Dom IX6SR E (prof. 235)
- Dom IX6SR E (prof.129/130/241) MK
- Dom IX6SR E (prof.131/132/233) MK
- Dom IX6SR E (prof.232/234) AT
- Dorma 2 in 1 (Prof. 233) (5P)
- Ezcurra DS10/15 (5+5)
- EUROSPEC MPX6Plus
- FCV (6P) - (6+5+4)
- Giobert Alfa Romeo GT2AP (5+5) - Lancia GT2 (5+5)
- Goal AD5 (Market Japanese)
- Honda (Market India)
- Iseo R7 Extra
- Metal X6S - X6V (Market Bulgarian)
- Mg HS Plus (5+5+5)
- Schlage Everest SFIC
- Showa W2-DAC (4T-4W)
- Snc – 30/30 (Market Bulgarian)
- Titan T200
- Wilka PR300
- Wilka Carat - P3
- Wilka Carat - P1
- Wilka PR100
- Yamaha (Market India)

NEW FUNCTION



- New Function "Cutting Tree" from "Card => Partial cuts". This function shows you how to recut multiple codes onto the same key blank so you can test each one and use a minimum number of key blanks.
- New Function "Cutting speed tuning" on Copy by original, copy by card for standard, laser and dimple keys. Using this function, it's possible to change the "cutting speed" and the "Depth removal step" according to the thickness and the material of the blank key to be cut.
- Turkish language.



FUTURA – FUTURA PRO NEWS WEB



February 2015

1_2014 FUTURA v. 2.8.0

REMEMBER TO



- **Remember** to update the Silca.apk after installing the Software update (see the on board Instructions Manual – Ch 6.2 APP UPDATE (APK)).
- With the new **MySilca App** from Silca, you can keep the entire expertise and experience of your Key Partner at hand anytime anywhere.

NEW SYSTEM



Data update with new main series.

- | | |
|--|---|
| <ul style="list-style-type: none"> • Honda (Market India) • Honda (4T-6W) • Keso 2000 S (Special) • Metal (X6V) • Metal 2x6J 30/30 (6P) | <ul style="list-style-type: none"> • Trio-Ving (Triton) • Viro Palladium (7P) • Viro Palladium PV (7P) • Yale YA35/40 MSG SN • Yamaha (Market India) |
|--|---|

BUG FIXED



- Fixed a problem related to cutting more than one piece for some systems
- Fixed a problem related to cutting and decoding of card 1493 (Keso 1000)

February 2015

1_2014 FUTURA v. 2.7.1

BUG FIXED



- Fixed a problem related to searching by Sn

February 2015

1_2014 FUTURA v. 2.7.0

REMEMBER TO



- **Remember** to update the Silca.apk after installing the Software update (see the on board Instructions Manual – Ch 6.2 APP UPDATE (APK)).
- With the new **MySilca App** from Silca, you can keep the entire expertise and experience of your Key Partner at hand anytime anywhere.

NEW SYSTEM



Data update with new main series.

- Brisant (6P)
- Cisa (CS501)
- Gege (pExtra Swe)
- Metal (x6s)
- Snc (30/30)
- Valeo (2T-8W)

BUG FIXED



- Fixed a problem related to cutting/decoding of MAGNUM : SN 1524, 1525, 1527, 1528.
- Fixed a problem related to the cut algorithm of SEA : SN 34-35.
- Fixed a problem related to the cut algorithm of VALEO : SN 1117.

January 2015

1_2014 FUTURA v. 2.6.1

BUG FIXED



- Fixed a problem related to German language

January 2015

1_2014 FUTURA v. 2.6.0

REMEMBER TO



- **Remember** to update the Silca.apk and SilcaKeyboard.apk after installing the Software update (see the on board Instructions Manual – Ch 6.2 APP UPDATE (APK)).
- With the new **MySilca App** from Silca, you can keep the entire expertise and experience of your Key Partner at hand anytime anywhere.

NEW SYSTEM

Data update with new main series.



- | | |
|---|--|
| <ul style="list-style-type: none"> • ABUS (System V14-XY14-Y14 - Abus Bravus 1000-2000-3000-4000) • ANKERSLOT (Infinity / Multi) • ASSA_NEP (Neptun) • ASSA_TRI (Triton 5900 - P600) • ATRA / DIERRE (Atra New Power (7W-2P) – Padronale) • CES (CES PSM-UDM) • CISA/ABUS (SP-TSP) • DOM (Dom-Sigma - System RN (5P/6P)) • EURO LOCKS (Euro Locks MK U (2T - 10W)) • GEGER (APN-ESP-AP-CNS - pExtra-ANS-2-3-4) • GERA (Gera 2000 Plus) | <ul style="list-style-type: none"> • GTV (Standard GTV) • ISEO (Iseo KLE8R (5+5)) • KABA (Kaba maTriX (K59)) • KESO Keso 1000/Lips (3A) • MAGNUM (Magnum Superior/Superior+) • MAUER (Mauer DT-1) • MLS / MAUER (MAUER ML+ (5+5)) • PFAFFENHAIN (Pfaffenhain Wavy line Pro - Pfaffenhain KV14 - XV14 - Pfaffenhain Integral 14) • RUKO (Merkur 401) • VACHETTE (Radial) • WILKA (Carat-P1-PR100-P1) • WINKHAUS (AZ/RPE/RPS/VS/VS6/Xpert - TEC RPS/RPE) |
|---|--|

NEW FUNCTION



- If Futura is not connected to Internet, it is now possible to download the Futura Software update into the tablet connected to internet and then upgrade the machine from the tablet.
- If Futura is not connected to internet, it is now possible to download the software upgrade **into the PC via Silca Remote Service (SRS)** and then use a USB PEN to



FUTURA – FUTURA PRO NEWS WEB



upload the Upgrade to the machine.

- If requested **register the machine to Silca Web**, in order to join the 6 months Free Subscription.

BUG FIXED



- Fixed a problem related to decoding of Serial Number 1255 **ISEO CSR R9 PLUS N.**
- Fixed data card data of SN 34, 35, 628, 929, 1117, 1285.
- Fixed a problem related to cutting cards 3207 and 3769 after decoding.

November 2014

1_2014

FUTURA v. 2.5.0

BUG FIXED



- Improved the “Connect to” function that allows to easily find the Futura IP address in a network accessible via router.
- Solved a problem related to the decoding of dimple keys that in some instances returned a wrong combination
- Solved a problem related to the cutting of dimple keys following decoding
- Solved a problem related to the decoding of edge keys with depths lesser then 4.10 mm
- Solved a problem related to the cutting algorithm of Esety Omega (card 2211)
- Solved a problem related to the cutting algorithm of Abus EC550 (card 2749)
- Solved the problem of white screen on tablet following some searching operations
- Fixed the displaying of ILCO references
- Restored card 2549 (Atra New Power) erroneously eliminated in the previous version

November 2014

1_2014

FUTURA v. 2.4.3

BUG FIXED



- Solved the problem related clamp 02V

November 2014

1_2014

FUTURA v. 2.4.1

BUG FIXED



- Solved a minor Software problem



FUTURA – FUTURA PRO NEWS WEB



October 2014

1_2014

FUTURA v. 2.4.0

NEW SYSTEM



Data update with new series.

- Russwin (A Class-old – 981 Class- 752 Class)
- Best (A3)
- YAMAHA (Market India)
- Atra New Power (7W-2P)

October 2014

1_2014

FUTURA v. 2.3.0

NEW SYSTEM



Data update with new series.

- HERO HONDA (Market India)
- BAJAJ (Market India)
- MAHINDRA (Market India)



FUTURA – FUTURA PRO NEWS WEB



September 2014

1_2014 FUTURA v. 2.2.0

NEW SYSTEM

Data update with new series.



- AVOCET (Avocet ABS)
- CES (Ces WSM (5+5+6))
- DOM (Dom IX Emergency- Dom IX Hochrippe (5+5+5))
- KABA (Kaba K6 (K6)- Kaba K8 green (K8G) (4+4+4)- Kaba K8S (K14))
- LOB (Lob Nefryt (5P))
- MOTTURA (Mottura C28 (5+4+4)- Mottura C30-C31 (5+4))
- PFAFFENHAIN (Pfaffenhain Wavy line)
- TITAN (K66)
- MIWA (Miwa UR- Miwa U9)
- GUARD (Profile G11-G12-G13- G14- G17- EPS/P EP83)
- MUL.T.LOCK (Mul.T.Lock Interactive (115)- (115) MK- (206)- (215)- (225)- (262)- (264)- Mul-T-Lock MT5)

NEW FUNCTION



- CISA code search for series: (SN 631-634-635-733)
- A new function that allows third party programs (such as Master Key Program) to transmit a job to the Futura "Queue of jobs" using a wireless connection or a local area network
- Japanese language

BUG FIXED



- Fixed a problem related to an OPEN router connection (without password)

June 2014

1_2014 FUTURA v. 2.1.10

BUG FIXED



- Solved the problem of the message "Internal Server Error" after the update, if it has been selected in the machine the Measurement unit "Thousandths of Inch"

June 2014

1_2014 FUTURA v. 2.1.8

NEW SYSTEM



Data update with new series.

- GERDA (WKM3; WKM1)
- CORBIN (Evolution)
- LINCE (C4;C2)
- MAUER (MLS)
- ISEO (CSR R9 Country N; Plus N)
- TESA
- KESO (2000S;4000S)
- KABA (Titan; 8S-14 Mixed)
- YALE
- ABUS (NW52;NW72)
- AGB (5000)
- GERA (WS; WSG; 2000 Plus)
- IFAM
- VIRO
- MOTTURA (C43)
- BASI (CX6 Left)
- ESETY (Omega)
- ANKERSLOT (Infinity / Multi)
- HUGO (GR 2.55)

NEW FUNCTION



- Decoding and copying using read measurements
- Management of more jaws for the same data card

BUG FIXED



- Corrected a decoding problem related to some dimple keys
- Solved the problem related to search of some data card

May 2014

1_2014

FUTURA v. 2.0.1

BUG FIXED



- Solved the problem of password enabling for some data cards

May 2014

1_2014

FUTURA v. 2.0.0

NEW FUNCTION



- Management of comparatives and alternatives key
- Option to select the key manufacturer
- Option to detect key blank measurement before cutting edge keys

BUG FIXED



- Copy a SIMPLEX Key by card
- Error in decoding dimple key due to a false electric contact.
- Improved accuracy and performance of “Copy by original”